



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1907-057
DATE : 1-Jul-2019
POLICY NO. : FWD PNPV2018-00005669-01
VEHICLE REG. NO. : SJC6223A
VEHICLE MAKE : MITSUBISHI LANCER 1.6 (A)

TO Motor Claim Department
India International Insurance Pte Ltd
64 Cecil Street, #04-#05 IOB Building, Singapore 049711
Tel: 6347 6100
Fax: 6224 4174 / 6225 7743

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper / CRW	1	\$ 700.00	\$ 700.00
2	Rear Bumper Clips / NR	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH / NR	1	\$ 40.00	\$ 40.00
4	Rear Bumper Retainer LH X NII	1	\$ 40.00	\$ 40.00
5	Rear Tail Lamp RH / CRW	1	\$ 420.00	\$ 420.00
6	Rear Tail Lamp LH X NII	1	\$ 420.00	\$ 420.00
7	Rear Tail Lamp Grommet Upper X NII	2	\$ 10.00	\$ 20.00
8	Rear Tail Lamp Grommet Lower X NII	2	\$ 5.00	\$ 10.00
9	Rear / End Panel Garnish X NII	1	\$ 180.00	\$ 180.00
10	End Panel X R	1	\$ 420.00	\$ 420.00
Total Spare Parts				\$ 2,300.00
SPECIAL NETT				
Total Special Nett				\$
LABOUR				
11	Spray Painting Rear Bumper and Skirting Include Inner Panel	1	\$ 600.00	\$ 600.00
12	Replace Rear including Fitting, Cut, Weld and Re-align	1	\$ 600.00	\$ 600.00
13	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00
14	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 80.00	\$ 80.00
15	Check and rectify electrical wiring	1	\$ 20.00	\$ 20.00
Total Labour				\$ 1,380.00
Amount Before Excess				\$ 3,680.00
Add GST @ 7%				257.60
Total Amount Payable				\$ 3,937.60

Estimate prepared by: Raymond Tan
The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Steve (LKK)
8322 8813

Steve Chan @ LKK auto-repair

P-1071

L-750

1821

L/S - 1456-80
= 1450

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve Chen (LKK Auto)

From: info@automotiverepaircentre.com.sg
Sent: Friday, August 23, 2019 8:41 AM
To: Steve Chen (LKK Auto)
Cc: 'Lin Shu Juan'
Subject: RE: SJC6223A

Dear Steve,

We confirmed L/S repair \$1,450.00 (3 repair days)

Thank you.

Best Regards,
Raymond Tan
Automotive Repair Centre Pte Ltd
38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: +65 64688834
Fax: +65 64622278

From: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Sent: Thursday, 22 August 2019 7:37 PM
To: info@automotiverepaircentre.com.sg
Subject: SJC6223A

Dear Raymond,

Our finalize is \$1450 (L/S, before GST). 3 repair days.

Kindly confirm.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: info@automotiverepaircentre.com.sg [<mailto:info@automotiverepaircentre.com.sg>]
Sent: Thursday, August 22, 2019 4:34 PM
To: Steve Chen (LKK Auto)
Subject: RE: SJC6223A

Dear Steve,