



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:JANICE			Ref: CC4/ASM19006511/Gpa3q2 Date: 14/01/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SCP 5010T	Veh. Inspected	SLE 1198M
	Policy No.	GA437869	Coverage (\$)	0.00
	Claim No.	S9M01JV7	Excess (\$)	0.00
	Assign From		Assign Date	11/04/2019
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MERCEDES BENZ B180	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	WDD2462422J247733	Colour	WHITE
	Odometer	96000 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/45Z R17	MICHELIN	6 mm
	L/H Front Tyre	225/45Z R17	MICHELIN	6 mm
	R/H Rear Tyre	225/45Z R17	MICHELIN	6 mm
	L/H Rear Tyre	225/45Z R17	MICHELIN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	07/04/2019	Inspection Date	27/06/2019
	Survey held at	K KIM HIN AUTO PTE LTD 160 SIN MING DRIVE #02-20 SIN MING AUTO CITY SINGAPORE 575722		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	