

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ After-Paint: _____
 Contacts : _____

Vehicle Nos : **SGG 5283Y**
 Model : Toyota Altis
 Year : _____
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Bootlid	1	\$ 680.50	\$ ✓ 680.50	DDV
2	Bootlid logo	1	\$ 59.90	\$ ✓ 59.90	
3	Bootlid emblem '1.6'	1	\$ 42.00	\$ ✓ 42.00	
4	Bootlid emblem 'E'	1	\$ 36.50	\$ ✓ 36.50	NEC
5	Bootlid emblem 'VVT-I'	1	\$ 42.50	\$ 37.10 42.50	
6	Bootlid emblem 'Corolla'	1	\$ 66.80	\$ ✓ 66.80	
7	Bootlid emblem 'Altis'	1	\$ 68.50	\$ ✓ 68.50	
8	Bootlid outer chrome moulding	1	\$ 214.50	\$ 214.50	NNX
9	Bootlid reflector Rh	1	\$ 286.40	\$ ✓ 286.40	BRV
10	Bootlid reflector Lh	1	\$ 286.40	\$ ✓ 286.40	BRV
11	Bootlid inner lock	1	\$ 285.20	\$ 240.00 285.20	JAM
12	Bootlid striker	1	\$ 85.60	\$ ✓ 85.60	BT
13	Bootlid hinge	2	\$ 167.60	\$ 335.20	NNX
14	Bootlid weather strip	1	\$ 211.60	\$ 125.60 211.60	CuTV
15	Rear bumper	1	\$ 685.90	\$ ✓ 685.90	DDV
16	Rear bumper side retainer	2	\$ 58.20	\$ ✓ 116.40	NECV
17	Rear bumper side bracket	1	\$ 68.60	\$ 68.60 137.20	BRV
18	Rear bumper lower	1	\$ 106.80	\$ ✓ 106.80	DDV
19	Rear end panel	1	\$ 662.10	\$ ✓ 662.10	DDV
20	Rear end panel top garnish	1	\$ 240.90	\$ 116.70 240.90	DL
21	Spare tyre panel	1	\$ 791.10	\$ 708.10 791.10	DDV
22	Spare tyre panel top board	1	\$ 158.60	\$ ✓ 158.60	BRV
23	Spare tyre panel fastener	1	\$ 84.00	\$ 84.00	NNX
24	Taillamp Rh	1	\$ 436.30	\$ ✓ 436.30	BRV
25	Taillamp base panel	1	\$ 132.20	\$ ✓ 132.20	DDV
26	Taillamp apron panel	1	\$ 64.50	\$ 64.50	RX
27	Taillamp Lh	1	\$ 436.30	\$ ✓ 436.30	BRV
28	Taillamp base panel	1	\$ 132.20	\$ ✓ 132.20	DDV
29	Taillamp apron panel	1	\$ 64.50	\$ 64.50	RX
30	Rear fender Lh	1	\$ 757.70	\$ 757.70	RX
31	Rear fender inner trim Lh	1	\$ 152.50	\$ ✓ 152.50	DISV
32	Rear fender Rh	1	\$ 757.70	\$ 757.70	RX
33	Rear fender inner trim Rh	1	\$ 152.50	\$ ✓ 152.50	DISV
34	Rear windscreen moulding	1	\$ 89.70	\$ 89.70	NNX
35	Rear no plate lamp	2	\$ 68.30	\$ 136.60	NNX
Parts Sub Total :				\$ 8,997.30	
25% Discount :				\$ 2,249.33	
PARTS TOTAL :				\$ 6,747.98	

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 60.00	\$ 60.00	NNX
2	Bootlid reflector seal	2	\$ 40.00	\$ 60.00 80.00	✓
3	Taillamp seal	2	\$ 60.00	\$ 60.00 120.00	✓

4	Rear bumper clips	1	\$	50.00	\$ 30.00	50.00	✓
5	Rear bumper lower clips	1	\$	50.00	\$ 30.00	50.00	✓
6	Rear end panel top garnish clips	1	\$	50.00	\$ 30.00	50.00	✓
7	Tail lamp apron panel rivet Rh	1	\$	50.00	\$ 30.00	50.00	✓
8	Taillamp apron panel rivet Lh	1	\$	50.00	\$ 30.00	50.00	✓
9	Rear fender inner trim clips	2	\$	50.00	\$ 60.00	100.00	✓
10	Rear end panel sealant	1	\$	100.00	\$ 60.00	100.00	✓
11	Spare tyre panel sealant	1	\$	100.00	\$ 60.00	100.00	✓
12	Reverse sensor with module	2	\$	200.00	\$ 200.00	400.00	✓
13	Rear no plate with cover	1	\$	80.00	\$ 50.00	80.00	✓
14	Reverse camera	1	\$	500.00	\$	500.00	NNX
15	Rear windscreen inner seal	1	\$	180.00	\$	180.00	NNX
16	Rear windscreen primer and cleaner	1	\$	80.00	\$	80.00	NNX
SPECIAL NETT TOTAL :					\$	2,050.00	

Nos.	LABOUR	S\$		
1	R&R bootlid component	\$ 50.00	100.00	
2	R&R petrol filler hose	\$	150.00	NNX
3	R&R reverse sensor	\$ 60.00	100.00	✓
4	R&R rear windscreen	\$	250.00	NNX
5	Disconnect wire harness to facilitate repair, reconnect and test function	\$ 50.00	100.00	✓
6	R&R upholstery	\$ 50.00	150.00	✓
7	Panel beat	\$ 1400.00	1,800.00	
8	Rust proofing	\$ 100.00	200.00	
9	Spray painting	\$ 1200.00	1,800.00	
10	Conduct water leakage test	\$	60.00	NNX
LABOUR TOTAL :		\$	4,710.00	

PARTS TOTAL : \$ 6,747.98
 SPECIAL NETT TOTAL : \$ 2,050.00
 LABOUR TOTAL : \$ 4,710.00
GRAND TOTAL : \$ 13,507.98

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Resurvey on 1/7/19

Lump sum repairs

Repair days 10

Lim Teow Guan

Lim

1/7/19 1600 hrs