

33	1	RR BOOTLID INSULATOR <i>Delint</i>	\$	288.00	✓
34	1	RR BOOTLID LOGO	\$	165.00	✓
35	1	RR BOOTLID EMBLEM CHEVROLET <i>2</i>	\$	82.00	✓
36	1	RR BOOTLID EMBLEM CRUZE LS <i>1</i>	\$	80.00	✓
37	1	RR BOOTLID LOCK <i>Delint</i>	\$	286.00	✓
38	1	RR BOOTLID LOCK COVER <i>Missing</i>	\$	38.00	✓
39	1	RR BOOTLID LOCK KEYLESS SENSOR <i>Delint</i>	\$	167.00	✓
40	1	RR BOOTLID HINGE RH <i>2 Bent</i>	\$	176.00	✓
41	1	RR BOOTLID HINGE LH	\$	176.00	✓
42	1	RR BOOTLID LAMP RH <i>3 Bent</i>	\$	401.00	✓
43	1	RR BOOTLID LAMP LH <i>3 Bent</i>	\$	401.00	✓
44	1	RR TAILLAMP LH <i>3 Bent</i>	\$	850.00	✓
45	1	RR TAILLAMP RH	\$	850.00	✓
46	1	RR END PANEL <i>Delint</i>	\$	996.00	✓
47	1	RR END PANEL TOP GARNISH <i>Delint</i>	\$	267.00	✓
48	1	RR SPARE TYRE PANEL <i>Repair</i>	\$	1,439.00	+
49	1	RR SPARE TYRE PANEL BOARD <i>Delint</i>	\$	473.00	+
50	1	RR EXHAUST SILENCER BOX <i>new</i>	\$	559.00	+
51	1	RR EXHAUST SILENCER BOX MOUNTING <i>new</i>	\$	45.00	+

17082
15373.80

Parts Total: \$ 21,577.00
Less 10%: \$ 2,157.70
Total: \$ 19,419.30

Labour

No.	Labour Description	Price (SGD)	
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 2,400.00	1400
2	Carry out spray painting on affected area, RR BUMPER, RR BOOTLID, RR END PANEL, RR SPARE TYRE PANEL, RR FENDER LH, RR FENDER RH, RR DOOR LH	\$ 2,000.00	1300
3	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 160.00	30
4	Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$ 300.00	100
5	To remove and refix reverse sensor and conduct test	\$ 120.00	60
6	To conduct transfer of parts from old bootlid to new bootlid	\$ 180.00	80
7	To remove and replace exhaust pipe	\$ 180.00	+
8	To remove and refix rear windscreen	\$ 200.00	120
9	To conduct anti rust of under carriage tuff coat	\$ 100.00	60
10	To conduct water leakage test after repairs of vehicle	\$ 60.00	X
11	Remove and replace LHR under carriage parts	\$ 300.00	X
12	To conduct 4 wheel alignment	\$ 180.00	+
13	To conduct reset of engine light on	\$ 200.00	+

3150

Labour Total : \$ 6,380.00

Others

Other Description

No.			Price (SGD)
1	10	RR BUMPER CLIP <i>plan</i>	\$ 40.00 ✓
3	10	RR BOOTLID INNER TRIM CLIP <i>plan</i>	\$ 40.00 ✓
4	10	RR FENDER INNER TRIM CLIP <i>plan</i>	\$ 40.00 ✓
5	10	RR FENDER INNER SHIELD CLIP <i>plan</i>	\$ 40.00 x
6	5	RR END PANEL TOP GARNISH CLIP <i>plan</i>	\$ 20.00 ✓
7	1	RR WINDSCREEN SEALANT <i>plan</i>	\$ 65.00 45 ✓
8	1	RR WINDSCREEN INNER SEAL <i>plan</i>	\$ 40.00 30 ✓
9	1	RR NUMBER PLATE <i>plan</i>	\$ 65.00 ✓

280

TOTAL: 350.00

GRAND TOTAL : 26,149.30

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor
Kelvin Chew
HP: 8292 5595 Fax: 68445185

Adrian L
H/S 26/06/19.

12 Days.

total: 18803.80
H/S: 141c (Nett Value)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: