

Registration No. QX 1018R

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Front Bumper	1	Broken			
1.2	Front RH Bumper Retainer	1	Broken			
1.3	Front LH Bumper Retainer	1	Broken			
1.4	Front Bumper Centre Grill	1	Broken			
1.5	Front Bumper Lower Lip	1	Crushed			
1.6	Radiator Grill	1	Broken			
1.7	Front Number Plate	1	Bent			
1.8	Front Bumper Sponge	1	Broken			
1.9	Front Bumper Reinforcement	1	Dented			
1.10	Front Bumper Lower Beam	1	Not Necessary			
1.11	Front Support Panel	1	Dented			
1.12	RHS Head Lamp	1	Broken			
1.13	RHS Head Lamp Lower Bracket	1	Bent			
1.14	LHS Head Lamp	1	Broken			
1.15	LHS Head Lamp Lower Bracket	1	Bent			
1.16	Radiator	1	Unconfirm			
1.17	Radiator Top Hose	1	Not Necessary			
1.18	Radiator Upper Hose	1	Not Necessary			
1.19	Radiator Lower Hose	1	Not Necessary			
1.20	Radiator Neck	1	Not Necessary			
1.21	Radiator Fan Assy	1	Unconfirm			
1.22	Air Con Condenser	1	Unconfirm			

1.23	Air Con Condenser Discharge Hose	1	Not Necessary			
1.24	Air Con Condenser Liquid & Suction hose	1	Not Necessary			
1.25	Bonnet Cover	1	Crushed			
1.26	RHS Bonnet Cover Hinge	1	Missing			
1.27	LHS Bonnet Cover Hinge	1	Not Necessary			
1.28	Bonnet Cover Lock Assy	1	Bent			
1	LABOUR DESCRIPTION					
1.1	Replace & Spray Paint (2 colours) for Front Bumper including replacing both side Front Bumper Retainers, Centre Grill, Radiator Grill Lower Lip, Front Bumper Sponge & Front Number Plate.					6
1.2	Replace Front Bumper Reinforcement					1.5
1.3	Replace Front Bumper Lower Beam					1
1.4	Replace Front Support Panel					4
1.5	Replace & Wiring for RHS Head Lamp including replacing RHS Head Lamp Lower Bracket					1
1.6	Replace & Wiring for LHS Head Lamp including replacing LHS Head Lamp Lower Bracket					1
1.7	Replace Radiator including replacing Radaitor Top, Upper, , Lower Hose & Radiator Neck		Unconfirm			3.5
1.8	Condenser Discharge Hose & Air Con Condenser Liquid & Suction Hose		Unconfirm			8
1.9	replacing both side Bonnet Cover Hinges, Bonnet Cover Lock Assy & Replacing 'POLICE' Wording Sticker on Bonnet Cover					5
COSTING		TOTAL PARTS COST				
		TOTAL MAN-HOUR				31