

AGG - LKK  
Kenneth.



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Repair Estimates

SLJ 8398 E

Parts	(a) Cost / List Price Items	\$	11,924.15
	Plus/Less 25%	\$	2,981.04
	<b>Total of Cost / List</b>	<b>\$</b>	<b>8,943.11</b>
	(b) Nett Price Items		
	Less		
	<b>Total of Nett Item</b>		
	(c) Special Nett Items	\$	345.00
<b>Total Parts Cost</b>		<b>\$</b>	<b>9,288.11</b>
<b>Labour</b>		<b>\$</b>	<b>3,330.00</b>
<b>Total</b>		<b>\$</b>	<b>12,618.11</b>

Not Notwork

Resurvey Be paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 11/7/19 at \_\_\_\_\_

### Remarks By Surveyor

(a) The repair of this vehicle is not authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 4-5 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Le Date: 11/7/19



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : **SLJ 8398 E**  
Make & Model : **TOYOTA PRIUS**  
Chassis No : **JTDKB3FU403539220F**

Submit By : **SERENCE**  
Year Manufacture : **2016**  
Engine No. :

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding <i>me</i>	1	\$97.70		✓
2	Rear windscreen sealant <i>me</i>	1	\$50.00	S.N	4052
3	Rear number plate <i>sz</i>	1	\$45.00	S.N	X
4	Reverse sensor <i>Shoy</i>	1	\$200.00	S.N	✓
5	Rear bumper <i>Bu</i>	1	\$497.50		✓
6	Rear bumper clip <i>me</i>	10	\$40.00		✓
7	Rear bumper side retainer LH <i>D11</i>	1	\$112.70		✓
8	Rear bumper side retainer RH <i>D11</i>	1	\$112.70		✓
9	Rear bumper reinforcement <i>B1</i>	1	\$398.90		✓
10	Rear bumper lower garnish centre <i>B1 / cm</i>	1	\$582.60		✓
11	Rear bumper lower garnish LH <i>mg cm</i>	1	\$149.70		✓
12	Rear bumper lower garnish RH <i>mg cm</i>	1	\$149.70		✓
13	Rear bumper tow cover <i>m17</i>	1	\$31.70		✓
14	Rear bumper under cover	1	\$355.20		?
15	Rear bumper under cover LH	1	\$187.60		?
16	Rear bumper under cover RH	1	\$187.60		?
17	Rear bumper under cover clip	4	\$14.00		?
18	Tail door <i>B1</i>	1	\$1,122.50		✓
19	Tail door lock <i>R</i>	1	\$487.70		X
20	Tail door emblem <i>me</i>	1	\$61.70		✓
21	Wording "PRIUS" <i>me</i>	1	\$51.90		✓
22	Wording "HYBRID" <i>me</i>	1	\$55.47		✓
23	Tail door hinge LH <i>R</i>	1	\$87.60		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**Spare Parts**

Vehicle No. : **SLJ 8398 E**

Make & Model : **TOYOTA PRIUS**

Chassis No : **JTDKB3FU403539220F**

Submit By : **SERENCE**

Year Manufacture : **2016**

Engine No. : **0**

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail door hinge RH <i>R</i>	1	\$87.60		<i>X</i>
25	Tail door plate garnish <i>CM</i>	1	\$782.50		<i>✓</i>
26	Tail door inner trim <i>Sn</i>	1	\$278.90		<i>X</i>
27	Tail door inner trim clip <i>rv</i>	10	\$28.00		<i>X</i>
28	Tail end panel	1	\$596.60		<i>?</i>
29	Tail end panel garnish	1	\$151.60		<i>?</i>
30	Tail end panel garnish clip	10	\$35.00		<i>?</i>
31	Boot weatherstrip <i>Sn</i>	1	\$353.10		<i>X</i>
32	Spare tyre well panel <i>R</i>	1	\$793.15		<i>X</i>
33	Spare tyre board <i>Sn</i>	1	\$566.79		<i>X</i>
34	Spare tyre compartment sponge LH <i>Sn</i>	1	\$297.67		<i>X</i>
35	Spare tyre compartment sponge RH <i>Sn</i>	1	\$297.67		<i>X</i>
36	Spare tyre compartment centre <i>Sn</i>	1	\$251.70		<i>X</i>
37	Tail lamp LH - UPPER <i>Sn</i>	1	\$498.75		<i>X</i>
38	Tail lamp RH - UPPER <i>(CM) Sn</i>	1	\$498.75	<i>rv</i>	<i>X</i>
39	Tail lamp LH - LOWER <i>Sn</i>	1	\$511.60		<i>X</i>
40	Tail lamp RH - LOWER <i>Sn</i>	1	\$511.60		<i>X</i>
41	Taildoor glass <i>Sn</i>	1	\$598.70		<i>X</i>
42	Taildoor glass sealant <i>rv</i>	1	\$50.00	S.N	<i>40Sn</i>
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.





## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Labour

Vehicle No. : **SLJ 8398 E** Submit By : **SERENCE**  
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, TAILDOOR PLATE GARNISH, SPARE TYRE COMPARTMENT)	\$1,200.00	500
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, TAILDOOR PLATE GARNISH, SPARE TYRE COMPARTMENT)	\$1,200.00	880
3	To tuff coat.	\$100.00	?
4	TO Check wiring	\$50.00	20
5	To transfer boot mechanism to new boot	\$120.00	60
6	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20
7	To remove & refit reverse sensor	\$150.00	50
8	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	X
9	To remove & refit rear windscreen.	\$120.00	✓
10	To remove & refit Taildoor glass to assist work load	\$120.00	60

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*