

Kd

Kenneth



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLJ 8398 E

Finalised

arts (a) Cost / List Price Items

\$ 4247.27 11,924.15

Plus/Less 25%

\$ 1061.82 2,981.04

Total of Cost / List

\$ 3185.45 8,943.11

(b) Nett Price Items

Less

Total of Nett Item

(c) Special Nett Items

\$ 280.00 345.00

ital Parts Cost

\$ 3465.45 9,288.11

bour

\$ 1740.00 3,330.00

tal

\$ 5205.45 12,618.11

85175.45

e above total will be subjected to 7% G.S.T.

Name of Surveyor

Kenneth

Company

CKK

Survey conducted on

11/7/19

at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 4 - day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess

:\$

(e) Signature of surveyor

Se

Date:

11/7/19



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLJ 8398 E

TOYOTA PRIUS
JTDKB3FU403539220F

Submit By :
Year Manufacture :
Engine No. :
Cost / List

SERENCE

2016

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding	1	\$97.70		✓
2	Rear windscreen sealant	1	\$50.00	S.N	405m
3	Rear number plate	1	\$45.00	S.N	X
4	Reverse sensor	1	\$200.00	S.N	✓
5	Rear bumper	1	\$497.50		✓
6	Rear bumper clip	10	\$40.00		✓
7	Rear bumper side retainer LH	1	\$112.70		✓
8	Rear bumper side retainer RH	1	\$112.70		✓
9	Rear bumper reinforcement	1	\$398.90		✓
10	Rear bumper lower garnish centre	1	\$582.60		✓
11	Rear bumper lower garnish LH	1	\$149.70		✓
12	Rear bumper lower garnish RH	1	\$149.70		✓
13	Rear bumper tow cover	1	\$31.70		✓
14	Rear bumper under cover	1	\$355.20		X
15	Rear bumper under cover LH	1	\$187.60		X
16	Rear bumper under cover RH	1	\$187.60		X
17	Rear bumper under cover clip	4	\$14.00		✓
18	Tail door	1	\$1,122.50		X
19	Tail door lock	1	\$487.70		✓
20	Tail door emblem	1	\$61.70		✓
21	Wording "PRIUS"	1	\$51.90		✓
22	Wording "HYBRID"	1	\$55.47		✓
23	Tail door hinge LH	1	\$87.60		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

31k 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

3464.77

240 SN

are Parts

Vehicle No. :

Make & Model :

Chassis No. :

SLJ 8398 E

TOYOTA PRIUS

JTDKB3FU403539220F

Submit By :

Year Manufacture :

Engine No. :

Cost / List

SERENCE

2016

0

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail door hinge RH	1	\$87.60		X
25	Tail door plate garnish	1	\$782.50		✓
26	Tail door inner trim	1	\$278.90		X
27	Tail door inner trim clip	10	\$28.00		X
28	Tail end panel	1	\$596.60		X
29	Tail end panel garnish	1	\$151.60		X
30	Tail end panel garnish clip	10	\$35.00		X
31*	Boot weatherstrip	1	\$353.10		X
32	Spare tyre well panel	1	\$793.15		X
33	Spare tyre board	1	\$566.79		X
34	Spare tyre compartment sponge LH	1	\$297.67		X
35	Spare tyre compartment sponge RH	1	\$297.67		X
36	Spare tyre compartment centre	1	\$251.70		X
37	Tail lamp LH - UPPER	1	\$498.75		X
38	Tail lamp RH - UPPER	1	\$498.75	nc	X
39	Tail lamp LH - LOWER	1	\$511.60		X
40	Tail lamp RH - LOWER	1	\$511.60		X
41	Taildoor glass	1	\$598.70		X
42	Taildoor glass sealant	1	\$50.00	S.N	405m
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Labour

Vehicle No. : **SLJ 8398 E** Submit By : **SERENCE**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, TAILDOOR PLATE GARNISH, SPARE TYRE COMPARTMENT)	\$1,200.00	500
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, TAILDOOR PLATE GARNISH, SPARE TYRE COMPARTMENT)	\$1,200.00	880
3	To tuff coat. <i>nn</i>	\$100.00	7 50 X
4	TO Check wiring	\$50.00	200
5	To transfer boot mechanism to new boot	\$120.00	600
6	To conduct water leakage tests to ensure proper air and sealing	\$120.00	200
7	To remove & refit reverse sensor	\$150.00	500
8	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	X
9	To remove & refit rear windscreen.	\$120.00	✓
10	To remove & refit Taildoor glass to assist work load	\$120.00	600

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.