Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)

Sent: Saturday, 19 October 2019 11:52 AM

To: 'eqiprs@eqinsurance.com.sg'

Cc: Admin A

Subject: <SEEK MANDATE>: Direct Settlement - Accident Involving SKQ2952U (OI: EQI -

DM19HO01792/JT) AND SGB8969J (TP: LKK REF - CC6/EQI19011611/Apb3) on

24.06.2019

Attachments: LKK Survey Report & Photos.pdf; LOD - SGB8969J.pdf

EQ ref : **DM19HO01792/JT**

LKK ref : CC6/EQI19011611/Apb3s2

Dear Sirs/Madam,

ACCIDENT INVOLVING SKQ2952U(EQ-OI) / SGB8969J(TP)/ OTHERS ON 24/06/2019

We refer to the above matter.

The said chain collision involved 3 vehicles whereby our insured was the last vehicle. In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.

We seek your approval to offer Third Party repairer "XIN HUA WORKSHOP PTE LTD" at \$8,970.45(all-in).

The summary is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair	\$ 21,875.98	\$ 8,000.00
2. Loss of Rental(9days x \$120.00)(w/GST)	\$ 1,155.60	\$ 963.00(9days x \$100.00) (w/GST)
3. LTA/ GIA Search Fee	\$ 7.45	\$ 7.45
Total	\$ 23,039.03	<u>\$ 8,970.45</u>

Surveyor recommended 7 days for repair + 1Sunday + 1PRS = 9days.

Enclosed here with all the relevant documents for your perusal.

Kindly let us have your approval/instruction.

Best Regards,

 $\textbf{Hsiao Tong, Chew (Ms)} \mid \texttt{Case Handler}$

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Wednesday, 14 August 2019 10:01 AM
To: Shu Pei (LKKAuto) <shupei@lkkauto.com>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: FW: Direct Settlement - Accident Involving SKQ2952U (OI: EQI-DM19HO01792/JT) AND SGB8969J (TP: LKK

REF - CC6/EQI19011611/Apb3) on 24.06.2019

Dear Shu Pei

As attached.

Regards,

Janet Tan

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190 www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Shu Pei (LKKAuto) [mailto:shupei@lkkauto.com]

Sent: Monday, August 5, 2019 5:46 PM

To: Janet Tan < <u>janet.tan@eqinsurance.com.sg</u>>

Cc: Hsiao Tong (LKKAuto) < chewht@lkkauto.com >; Admin A < admin-a@lkkauto.com >

Subject: RE: Direct Settlement - Accident Involving SKQ2952U (OI: EQI - TBA) AND SGB8969J (TP: LKK REF -

CC6/EQI19011611/Apb3) on 24.06.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupei@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto) < shupei@lkkauto.com>

Sent: Monday, 1 July 2019 4:24 PM

To: 'Janet Tan' < janet.tan@eqinsurance.com.sg>

Cc: Hsiao Tong (LKKAuto) < chewht@lkkauto.com>; Admin A < admin-a@lkkauto.com>

Subject: Direct Settlement - Accident Involving SKQ2952U (OI: EQI - TBA) AND SGB8969J (TP: LKK REF -

CC6/EQI19011611/Apb3) on 24.06.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SGB 8969J at M/s Xin Hua Workshop Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you

Best Regards,

Shu Pei| Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupei@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)