

ASS. REC. BY:

REF:

CS/FCI19011613/RVD3172

Special Instruction:

SURVIVOR:

Rasul

ASSIGNMENT (Office)

CWS From (Person): Henry Kao to FCI Date/Time: 01/7/19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJK 9298Y

Insured:

SHA05SR

at Workshop m/s

Yew Tee Automobile

Tel:

67653373

of

191K 6 Woodlands Rd 3995 Yew Tee Ind. Estate

Policy No:

Claim No:

D19024244 MFSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/6/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SJK 9298Y x

SHA 05SR x

3/7/19

Email pret. revised to FCI

11/7/19

LS \$7300 confirmed by email (Ref 12,933.36, 64%)
mv: \$30K (est) LTA: \$13,981 NV: \$16,019

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJK 92984
 at Workshop m/s YEN TEE AUTOMOBILE
 of 399F
 Insured: 1 PCU
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 30k
 IDAC Accident Report: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lump Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJK 92984 Yr Regn: 2008 / NOV
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: HONGTAI / 8XA cc 1799
 Colour: WHITE A/C: Insured / Std / NI / NA
 Sp. Reading: 139564 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RN 61087361
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/45R17
 R: 1
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Hankook
 Front: _____ Rear: _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 26/06/19 D.O.I. 01/07/19
 Survey held at YEN TEE AUTOMOBILE
 Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair limit 15K</u>
	RECEIVED 11 JUL 2019

Date/Time, File Pass to?	☐ : Preli. Report	Days Of Repair: <u>12</u>	Survey Fee: <u>170 + 150</u>
1) _____	☐ : Final Report	Resurvey No. of Trip: <u>1</u>	
Date/Time, File Return to?			Transportation: <u>50</u>
2) <u>11/7 - typist</u>			<u>50</u>
Report Format: <u>CWS</u>	Add Fee: ☐ Site Insp (\$)		<u>94</u>
Lump Sum / I.B.I. (\$) <u>7300p</u>	☐ Interview (\$)		
	☐ Tech. Invs (\$)		
	☐ Weekend (\$)		
			TOTAL: <u>514</u>



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19004244MFSH

Our Ref: CS/FCI19011613/R1vd3

Date : 3/7/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJK 9298Y


We thank you for your instruction on 1/7/2019

Please be informed that we had conducted the inspection of the above mentioned
1/7/2019 at the premises of M/s YEW TEE AUTOMOBILE TECH PTE LTD
and have the following to report:-

Workshop Estimate Amount	: S\$20,233.36
Revised Estimate Amount	: S\$9,164.76
"Check" Items Amount	: S\$2,589.04
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
front and rear poriton



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	28-06-2019	Our Ref No. D19004244MFSH
Accident Date	26-06-2019	Claim Type. Third Party
Insured Vehicle	SHA0555R	Third Party Vehicle. SJK9298Y
Survey Location	BLK 6 WOODLANDS ROAD 399F YEW TEE INDUSTRIAL ESTATE	
Contact Person.	VINNIE LIM	
Contact No.	67653373/ 0	Fax No. 67604895
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	YEW TEE AUTOMOBILE TECH PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Rasul (LKKAuto)
Sent: Tuesday, 2 July 2019 9:36 AM
To: utauto@singnet.com.sg
Cc: Veron Chen (LKKAuto)
Subject: SJK 9298Y DOA : 26/06/19

Hi Winnie,

As spoken the repair limit for this vehicle is 15K.
Anyway, base on the calculation repair cost is much lower than 15K

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd *Save the Earth. Print only when necessary.*

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 3 July 2019 9:43 AM
To: 'CWS Motor Claims'
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004244MFSH/1, SJK 9298Y
Attachments: SJK 9298Y PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJK 9298Y
Date of survey: 1/7/2019
Number of days : 12 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 1 July 2019 12:26 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004244MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Best Regards,

Shiau Chan on behalf of G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 1 July 2019 12:17 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004244MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.

www.avg.com

QuickBooks® Online

Manage Outgoing Payments. Watch Your Business Grow. Intuit Quickbooks

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 10 Years COE Renewal! Toyota Wish 1.8A



1.8L 16V 1800 cc
1600 cc 1600 cc 1600 cc
1600 cc 1600 cc 1600 cc
GV Credit Pte Ltd

• Free VICOM evaluation
• Free grooming and 6 months maintenance
• In-house workshop ensures quality service
• Member of SVTA and hire purchase association
• 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Back (1 ... 2 3 4 5 6 ... 16) Next

Sort by Date Posted

20 results/page

313 vehicles

honda stream

Advanced Search

Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
honda stream	Any	Any	Any	Any	Any	Any	All



Honda Stream 1.8A X

-

N/A

23-Jul-2011

1,799 cc

-

MPV

SOLD

New Facelift. Accident Free. Low Mileage. Well Kept. No Repairs Needed. Fully Services By Sparks Car Care. Bank Loans And In-House Financing Available. Good For Short Term Usage And Future COE Renewal...

Posted: 22-Jun-2018

Tags: 2011 Honda Stream, 2011 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda



Honda Stream 1.8A Style Edition (COE till 03/2024)

\$33,800

\$7,120 /yr

30-Mar-2009

1,799 cc

-

MPV

Available

Full Loan Available At \$700 Plus! Purchase From An Award Winning Dealership! 1 Year Comprehensive Warranty Inclusive! Accident-Free Quality Pre-Owned With Low Mileage Done For Peace Of Mind. 100% Loan...

Cosmo Automobiles

Posted: 22-Jun-2018

Tags: 2009 Honda Stream, 2009 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda



Honda Stream 1.8A (COE till 04/2024)

\$37,800

\$7,830 /yr

29-Apr-2009

1,799 cc

-

MPV

Available

Loan High Approval! In House Finance Packages. We Provide 6 Months Warranty On Engine And Gearbox, Optional For 5 Or 10 Years COE Renewal. 6 Months Extended Engine And Gearbox Warranty! Engine And Gear...

Posted: 21-Jun-2018

Tags: 2009 Honda Stream, 2009 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda



Honda Stream 1.8A Style Edition

\$18,800

N/A

19-Dec-2009

1,799 cc

177,800 km

MPV

Available

Road Tax Till Dec 2019. Smooth Engine, Easy To Maintain Unit, Immaculate Condition, Most Popular Honda MPV For Your Family Usage. Accident Free And No Modifications Done. Very Spacious And Big Boot Sp...

Posted: 21-Jun-2018

Tags: 2009 Honda Stream, 2009 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Buy Tyres Online
Latest "Special" Offer From Tyresport



Honda Stream 1.8A (COE till 11/2022)

-

N/A

14-Dec-2007

1,799 cc

-

MPV

SOLD

Road Tax Just Renewed On 13/6/19.

Posted: 20-Jun-2018

Tags: 2007 Honda Stream, 2007 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda

Direct Owner



Honda Stream 1.8A RS2

-

N/A

01-Apr-2010

1,799 cc

-

MPV

SOLD

Previous Owner Trade-in For New Car. Tip-top Condition And Good For Short Term Use (9 Months Left), Monthly Depreciation Only At \$600. Take And Go With No Worries. Call Our Friendly Staff To Arrange F...

ABW24 Bus Pte Ltd

Posted: 20-Jun-2018

Tags: 2010 Honda Stream, 2010 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda

Premium Car



Honda Stream 1.8A (COE till 04/2024)

-

N/A

06-Apr-2009

1,799 cc

-

MPV

SOLD

3.18% Per Annum, \$638 Monthly, \$0 Ac Metallic Paint. New Pure Leather. New 8

base. Extra Add On Items: New 2 Years Warranty For Engine And Gearbox. New 2k

GV Credit Pte Ltd

Approved

Compare

Posted: 29-Jun-2019 Tags: 2009 Honda Stream, 2009 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda



Honda Stream 1.8A Style Edition (COE till 04/2029)

\$57,800

\$5,580 /yr

27-Apr-2009

1,799 cc

101,000 km

MPV

Available

Full Loan Available. Meticulously Well Maintained Unit With Regular Servicing Done Yet Low Mileage Done! Definitely Worth COE Renewal, View To Believe It's Condition! Guaranteed Accident Free With No ...

Creative Auto

Posted: 29-Jun-2019 Tags: 2008 Honda Stream, 2008 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda



Honda Stream 1.8A (COE till 05/2024)

-

N.A

27-May-2009

1,799 cc

-

MPV

SOLD

One Meticulous Owner Only, Agent KAH Motor Unit, Elegant White Colour Unit, Under-usage Low Mileage, Well-Maintained In Tip-Top Condition, Comfortable And Spacious MPV Ideally For Daily Family Drives...

DIRECT OWNER

Posted: 29-Jun-2019 Tags: 2009 Honda Stream, 2009 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda



Honda Stream 1.8A X (COE till 03/2023)

\$36,000

\$8,000 /yr

16-Jun-2008

1,799 cc

132,590 km

MPV

Available

Popular Model, The Most Reliable MPV Car Available For Sale. Well Maintained, 100% Accident Free, No Repair Needed. Consignment Unit! Trade In Welcome! Loan And Insurance Available. Call Now For View!

CONSIGNMENT

Prem Ray Motoring

Posted: 29-Jun-2019 Tags: 2008 Honda Stream, 2008 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda



Sell your Car for \$3,000 More

With over 15K cars sold via Auction and a 500+ Dealer Network, cars on sgCarMart Quotz typically receive up to \$3,000 above market value. Quotz Guarantees the Highest Selling Price in Singapore - If we fail, you get \$100 cash from us. Get your Car Listed Today.

Find out more!



Honda Stream 1.8A RSZ

-

N.A

20-Jun-2011

1,799 cc

-

MPV

SOLD

Genuine Low Mileage Done! Superb Handling, Comfortable Sedan With Good Fuel Efficient Car For You And Your Lovely Family, This Is Your Choice! No Repairs Needed, Is In A Very Good Condition, High Trad...

Posted: 19-Jun-2019 Tags: 2011 Honda Stream, 2011 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda



Honda Stream 1.8A RSZ Sunroof (COE till 05/2029)

-

N.A

24-Jun-2009

1,799 cc

-

MPV

SOLD

1 Owners Only! Very Well Maintain! In House Loan Available! Highest Offer For All Trade In! Low Fuel Consumption! Smooth And Responsive Engine! Highly Recommended Popular Family Car! Excellent Condi...

Posted: 19-Jun-2019 Tags: 2009 Honda Stream, 2009 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda



Honda Stream 1.8A (COE till 04/2024)

-

N.A

15-Jul-2009

1,799 cc

-

MPV

SOLD

3.18% Interest Rate Per Annum, \$638 Monthly, \$0 Admin Fees For All GV Purchase. Extra Add On Items: New 2 Years Warranty For Engine And Gearbox, New 2k Metallic Paint, New Pure Leather, New Rims, 16"...

DIRECT OWNER

GV Credit Pte Ltd

Posted: 19-Jun-2019 Tags: 2009 Honda Stream, 2009 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda



Honda Stream 1.8A RSZ Sunroof

-

N.A

22-Dec-2011

1,799 cc

-

MPV

SOLD

Sporty Drive Marries Practicality, Full Specs Kah Motor (Authorised Distributor) RSZ With Sunroof! Selling Family Second Car. In Very Good Condition, Accident Free, Low Genuine Mileage, Well Take Care...

DIRECT OWNER

Posted: 19-Jun-2019 Tags: 2011 Honda Stream, 2011 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda



Honda Stream 1.8A X (COE till 05/2023)

\$28,666

\$7,320 /yr

27-Jun-2008

1,799 cc

97,800 km

MPV

Available

New Arrival! Beautiful And Sporty White In Black Stream 1.8A X, Reliable And Low Maintenance Cost, Own By Careful Owner, Most Popular Honda MPV For Your Family Usage! 100% Accident Free And No Modific...

Posted: 18-Jun-2019 Tags: 2008 Honda Stream, 2008 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda



Honda Stream 1.8A RSZ (COE till 05/2022)

-

N.A

22-May-2007

1,799 cc

-

MPV

SOLD

Original Condition And Lowest Price In The Market, Accident-Free, Very Well Maintained Interior And Exterior, With No Wear And Tear To Be Replaced, Low Mileage, New Tyres, Trade In Welcome, Call Our F...

Posted: 18-Jun-2019 Tags: 2007 Honda Stream, 2007 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda

Honda Stream 1.8A (COE till 01/2022)

-

N.A

02-Feb-2007

1,799 cc

-

MPV

SOLD

Honda Stream Auto, Coe Paid \$26330 E Selling Fast, View To Believed.

tarts Replaced With Receipts Shown, Very Good Condition, Owner New Car Arriving,

DIRECT OWNER

Compare



Posted: 17-Jun-2019

Tags: 2007 Honda Stream, 2007 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda

Honda Stream 1.8A Sunroof
(COE till 07/2023)

\$29,800

\$7,300 /yr

22-Aug-2008

1,799 cc

-

MPV

Available

Car Is Very Well Maintained By Fussy Owner, All Major Work Done To Have Problem Free Drive. 100% Problem Free, Gearbox 3month Warranty, New Paint Work Lik E New Regular Service With Fully Synthetic Mo...

SHEET OWNER

Posted: 17-Jun-2019

Tags: 2008 Honda Stream, 2008 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda

Honda Stream 1.8A (COE till
04/2029)

\$54,800

\$5,590 /yr

20-Apr-2009

1,799 cc

135,000 km

MPV

Available

One Of The Most Well Maintained Unit In The Market With No Accident Or Mishap, Well Maintained Interior, And A Perfect Exterior Paintwork. New 4 x Spark Plugs, Suspensions, New 6 Months Road Tax, And ...

Tan Wei Auto Pte Ltd

Posted: 17-Jun-2019

Tags: 2009 Honda Stream, 2009 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda



Honda Stream 1.8A

\$35,800

\$11,950 /yr

03-Jun-2011

1,799 cc

108,000 km

MPV

Available

Rare 1 Owner Stream! Kah Motor Unit, Most Reliable And Stylish Compact MPV! Great Condition! View To Believe! No Gimmicks! Trade In Welcome! Call Us For An Appointment Now!

Posted: 17-Jun-2019

Tags: 2011 Honda Stream, 2011 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda

Save this search criteria, to get email alerts whenever a match is found:

Filter: **Model** Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

Back (: ... 2 3 4 5 6 ... 16) Next »

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used honda stream, honda stream Singapore, used honda stream Singapore, used honda stream, used vehicles Singapore or even buy used honda stream Singapore. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, movies, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Details	
Owner ID Type:	Singapore NRIC
Owner ID:	0794I
Vehicle Details	
Vehicle No.:	SJK9298Y
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8X A
Primary Colour:	Brown
Manufacturing Year:	2008
Engine No.:	R18A1796849
Chassis No.:	RN61087361
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$17,776.00
Original Registration Date:	10 Nov 2008
First Registration Date:	10 Nov 2008
Transfer Count:	1
Actual ARF Paid:	\$17,776.00
PARF Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Details	
COE Expiry Date:	09 Nov 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$16,061.00
COE Rebate Amount:	\$13,981.00
Total Rebate Amount:	\$13,981.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 02 Jul 2019

OK

30,000
13,981

16,019

(15K)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 07941

Vehicle Details

Vehicle No.: SJK9298Y
Vehicle to be Exported: Yes
Intended Deregistration Date: 28 Jun 2019
Vehicle Make: HONDA
Vehicle Model: STREAM 1.8X A
Primary Colour: Brown
Manufacturing Year: 2008
Engine No.: R18A1796849
Chassis No.: RN610B7361
Maximum Power Output: 103.0 kW (138 bhp)
Open Market Value: \$17,776.00
Original Registration Date: 10 Nov 2008
First Registration Date: 10 Nov 2008
Transfer Count: 1
Actual ARF Paid: \$17,776.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 09 Nov 2023
COE Category: B - Car (1601cc & above)
COE Period(Years): 5
PQP Paid: \$16,061.00
COE Rebate Amount: \$14,025.00
Total Rebate Amount: \$14,025.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 28 Jun 2019

OK

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate

Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : FIRST CAPITAL INSURANCE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTHQ/TP/1906/016
Policy No:	5105789969	Date of Loss:	26/06/2019
Vehicle Reg. No.:	SJK9298Y	Driveable?	yes
Driver Age:		Third Party Vehicle No.:	SHA555R, SKC79C
Any Injuries?	no	Contact No:	
Insured/Claimant:	MUHAMMAD HAIRULNIZAM BIN SAMAD	Driver:	EMELIA BINTE RABU

Make/Model:	Honda, Stream	Vehicle Reg. Date:	29/03/2019
Vehicle Colour:	WHITE	Engine Number:	R18A1796849
Chassis No:	RN61087361	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss CHAIN COLLISION
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

	Amount
Parts	13,415.36
Miscellaneous Items	1,723.00
Labour	3,110.00
Paintwork Labour	1,985.00
Towing	0.00
Gross Total(S\$):	20,233.36
GST 7.00%(S\$):	1,416.34
Nett Amount(S\$):	21,649.70

This claim is handled by: Vinnie Lim M H

8/67999

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR TAILGATE <i>H</i>	0.00	1,160.00	-20.00	928.00
2	1	REAR TAILGATE HINGES LH <i>X 2 suc</i>	0.00	140.00	-20.00	112.00
3	1	REAR TAILGATE HINGES RH <i>X 1 suc</i>	0.00	140.00	-20.00	112.00
4	1	REAR TAILGATE LOCK <i>H</i>	0.00	303.80	-20.00	243.04
5	1	REAR TAILGATE LOCK CATCH <i>4 suc</i>	0.00	55.00	-20.00	44.00
6	1	REAR TAILGATE RUBBER <i>adj</i>	0.00	189.00	-20.00	151.20
7	1	REAR TAILGATE LOGO <i>de</i>	0.00	38.00	-20.00	30.40
8	1	REAR TAILGATE STREAM EMBLEM <i>de</i>	0.00	58.00	-20.00	46.40
9	1	REAR TAILGATE INNER TRIM BOARD <i>X 1 suc</i>	0.00	489.50	-20.00	391.60
10	1	REAR TAILGATE DAMPER LH <i>X 1 suc</i>	0.00	297.00	-20.00	237.60
11	1	REAR TAILGATE DAMPER RH <i>X 1</i>	0.00	297.00	-20.00	237.60
12	1	REAR NUMBER PLATE OUTER GARNISH <i>cm</i>	0.00	183.40	-20.00	146.72
13	2	REAR NUMBER PLATE LAMP <i>X</i>	0.00	88.00	-20.00	70.40
14	1	REAR TAILGATE OUTER HANDLE <i>X 1 an</i>	0.00	189.00	-20.00	151.20
15	1	REAR WINDSCREEN GLASS MOULDING <i>de</i>	0.00	118.00	-20.00	94.40
16	1	REAR BUMPER <i>de</i>	0.00	1,185.00	-20.00	948.00
17	1	REAR BUMPER SIDE RETAINER LH <i>de</i>	0.00	48.50	-20.00	38.80
18	1	REAR BUMPER SIDE RETAINER RH <i>X suc</i>	0.00	48.50	-20.00	38.80
19	1	REAR BUMPER BRACKET LH <i>de</i>	0.00	41.40	-20.00	33.12
20	1	REAR BUMPER BRACKET RH <i>de</i>	0.00	41.40	-20.00	33.12
21	1	REAR BUMPER TOWING COVER <i>cm</i>	0.00	25.00	-20.00	20.00
22	1	REAR TAILLAMP RH <i>X an</i>	0.00	454.30	-20.00	363.44
23	1	REAR TAILLAMP RH <i>LH suc</i>	0.00	454.30	-20.00	363.44
24	1	REAR TAILLAMP PANEL LH <i>repair</i>	0.00	325.00	-20.00	260.00
25	1	REAR TAILLAMP PANEL RH <i>X suc an suc</i>	0.00	325.00	-20.00	260.00
26	1	REAR END PANEL <i>H</i>	0.00	685.00	-20.00	548.00
27	1	REAR END PANEL INNER GARNISH <i>X suc</i>	0.00	189.50	-20.00	151.60
28	1	REAR FENDER LH <i>repair</i>	0.00	968.60	-20.00	774.88
29	1	REAR FENDER RH <i>X</i>	0.00	0.00	0.00	0.00
30	1	REAR FENDER INNER TRIM BOARD LH <i>? X suc</i>	0.00	628.50	-20.00	502.80
31	1	REAR FENDER INNER TRIM BOARD RH <i>X</i>	0.00	628.50	-20.00	502.80
32	1	REAR EXHAUST SILENCER <i>X</i>	0.00	689.50	-20.00	551.60
33	1	REAR EXHAUST PIPE <i>X</i>	0.00	638.30	-20.00	510.64
34	1	REAR EXHAUST HEAT SHIELD <i>X</i>	0.00	80.00	-20.00	64.00
35	1	FRONT BUMPER <i>de</i>	0.00	635.40	-20.00	508.32
36	1	FRONT BUMPER SIDE RETAINER LH <i>de</i>	0.00	22.00	-20.00	17.60
37	1	FRONT BUMPER SIDE RETAINER RH <i>de</i>	0.00	22.00	-20.00	17.60
38	1	FRONT BUMPER BRACKET LH <i>de</i>	0.00	38.50	-20.00	30.80
39	1	FRONT BUMPER BRACKET RH <i>de</i>	0.00	38.50	-20.00	30.80
40	1	FRONT BUMPER INNER SPONGE <i>? X suc</i>	0.00	120.00	-20.00	96.00
41	1	FRONT BUMPER REINFORCEMENT <i>X</i>	0.00	437.00	-20.00	349.60
42	1	FRONT BUMPER FOG LAMP LH <i>X suc</i>	0.00	295.00	-20.00	236.00
43	1	FRONT BUMPER LOWER GRILLE <i>? X suc</i>	0.00	80.00	-20.00	64.00
44	1	FRONT GRILLE <i>cm</i>	0.00	220.00	-20.00	176.00
45	1	FRONT GRILLE CHROME MOULDING <i>? X an</i>	0.00	120.00	-20.00	96.00
46	1	FRONT GRILLE EMBLEM <i>? X an</i>	0.00	53.00	-20.00	42.40
47	1	FRONT HEADLAMP HID LH <i>X suc</i>	0.00	963.80	-20.00	771.04
48	1	FRONT HEADLAMP LOWER BRACKET LH <i>? X suc</i>	0.00	45.00	-20.00	36.00
49	1	FRONT HEADLAMP PANEL LH <i>? X suc</i>	0.00	110.00	-20.00	88.00
50	1	BONNET <i>bt</i>	0.00	680.00	-20.00	544.00
51	2	BONNET HINGES <i>X</i>	0.00	110.00	-20.00	88.00
52	1	BONNET LOCK <i>X suc</i>	0.00	130.00	-20.00	104.00
53	1	FRONT FENDER LH <i>X</i>	0.00	486.50	-20.00	389.20

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
54	1	FRONT FENDER INNER SHIELD LH <i>X sur</i>	0.00	80.50	-20.00	64.40
55	1	REAR SPARE TYRE PANEL <i>repair</i>	0.00	880.00	-20.00	704.00
Total Parts (S\$)						13,415.36

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR WINDSCREEN SEALANT <i>new</i>	0.00	60.00	0.00	60.00 40
2	1	REAR NUMBER PLATE <i>new</i>	0.00	45.00	0.00	45.00 35
3	1	REAR BUMPER CLIPS <i>new</i>	0.00	45.00	0.00	45.00
4	1	REAR BUMPER SENSORS (SET) <i>new</i>	0.00	260.00	0.00	260.00 200
5	1	REAR BUMPER LOWER SKIRT (SPORTS) <i>new</i>	0.00	600.00	0.00	600.00 300
6	2	REAR EXHAUST MOUNTING <i>X sur</i>	0.00	30.00	0.00	30.00
7	1	FRONT NUMBER PLATE <i>new</i>	0.00	45.00	0.00	45.00 35
8	1	FRONT BUMPER LOWER SKIRT (SPORTS) <i>new</i>	0.00	600.00	0.00	600.00 300
9	1	FRONT FENDER INNER SHIELD CLIPS <i>X new</i>	0.00	38.00	0.00	38.00
Sub Total (S\$)						1,723.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	70.00	70.00	0.00	70.00 30
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00 60
3	1	To Transfer Rear Tailgate.	80.00	80.00	0.00	80.00 60
4	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	100.00	0.00	100.00
5	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	100.00	0.00	100.00 80
6	1	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	180.00	180.00	0.00	180.00 <i>X new</i>
7	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	2,500.00	2,500.00	0.00	2,500.00 1400
Gross Labour Cost (S\$)						3,110.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	60.00	0.00	60.00
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	45.00	0.00	45.00 30
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	80.00	80.00	0.00	80.00 40
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	1,800.00	1,800.00	0.00	1,800.00 1400

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
-----	-----	-------------	------	--------	-------	------------

Gross Labour Cost (\$\$) 1,985.00

< END OF ESTIMATES >

Rasul
Hp 90010068

12 days

HS

01/07/19 @ 1840

Remy after repair

email: rasul@lkkauto.com

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : FIRST CAPITAL INSURANCE LTD

PARTICULARS OF CLAIM			
Claim Type:	TP	Ref. No:	YTHQ/TP/1906/016
Policy No:	5105789969	Date of Loss:	26/06/2019
Vehicle Reg. No.:	SJK9298Y	Driveable?	yes
Driver Age:		Third Party Vehicle No.:	SHA555R, SKC79C
Any Injuries?	no	Contact No:	
Insured/Claimant:	MUHAMMAD HAIRULNIZAM BIN SAMAD	Driver:	EMELIA BINTE RABU
Make/Model:	Honda, Stream	Vehicle Reg. Date:	29/03/2019
Vehicle Colour:	WHITE	Engine Number:	R18A1796849
Chassis No:	RN61087361	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss: CHAIN COLLISION
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS	Amount
Parts	13,415.36
Miscellaneous Items	1,723.00
Labour	3,110.00
Paintwork Labour	1,985.00
Towing	0.00
Gross Total(S\$):	20,233.36
GST 7.00%(S\$):	1,416.34
Nett Amount(S\$):	21,649.70

This claim is handled by: Vinnie Lim M H

8/6/7999

hvy parts \$4949.76.

SA \$955.00

Labour \$1730

SIP \$1530

Total \$ 9164.76.

- 2016

\$ 7331.80

= \$ 7300 LIS
12 days

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR TAILGATE <i>bt</i>	0.00	1,160.00	-20.00	928.00
2	1	REAR TAILGATE HINGES LH <i>X</i>	0.00	140.00	-20.00	112.00
3	1	REAR TAILGATE HINGES RH <i>X</i>	0.00	140.00	-20.00	112.00
4	1	REAR TAILGATE LOCK <i>bt</i>	0.00	303.80	-20.00	243.04
5	1	REAR TAILGATE LOCK CATCH <i>X</i>	0.00	55.00	-20.00	44.00
6	1	REAR TAILGATE RUBBER <i>uf</i>	0.00	189.00	-20.00	151.20
7	1	REAR TAILGATE LOGO <i>de</i>	0.00	38.00	-20.00	30.40
8	1	REAR TAILGATE STREAM EMBLEM <i>de</i>	0.00	58.00	-20.00	46.40
9	1	REAR TAILGATE INNER TRIM BOARD	0.00	489.50	-20.00	391.60
10	1	REAR TAILGATE DAMPER LH <i>X</i>	0.00	297.00	-20.00	237.60
11	1	REAR TAILGATE DAMPER RH <i>X</i>	0.00	297.00	-20.00	237.60
12	1	REAR NUMBER PLATE OUTER GARNISH <i>cm</i>	0.00	183.40	-20.00	146.72
13	2	REAR NUMBER PLATE LAMP <i>X</i>	0.00	88.00	-20.00	70.40
14	1	REAR TAILGATE OUTER HANDLE <i>X</i>	0.00	189.00	-20.00	151.20
15	1	REAR WINDSCREEN GLASS MOULDING <i>de</i>	0.00	118.00	-20.00	94.40
16	1	REAR BUMPER <i>de</i>	0.00	1,185.00	-20.00	948.00
17	1	REAR BUMPER SIDE RETAINER LH <i>de</i>	0.00	48.50	-20.00	38.80
18	1	REAR BUMPER SIDE RETAINER RH <i>X</i>	0.00	48.50	-20.00	38.80
19	1	REAR BUMPER BRACKET LH <i>de</i>	0.00	41.40	-20.00	33.12
20	1	REAR BUMPER BRACKET RH <i>de</i>	0.00	41.40	-20.00	33.12
21	1	REAR BUMPER TOWING COVER <i>cm</i>	0.00	25.00	-20.00	20.00
22	1	REAR TAILLAMP RH <i>X</i>	0.00	454.90	-20.00	363.92
23	1	REAR TAILLAMP RH <i>LH see</i>	0.00	454.30	-20.00	363.44
24	1	REAR TAILLAMP PANEL LH <i>repair</i>	0.00	325.00	-20.00	260.00
25	1	REAR TAILLAMP PANEL RH <i>X</i>	0.00	325.00	-20.00	260.00
26	1	REAR END PANEL <i>bt</i>	0.00	685.00	-20.00	548.00
27	1	REAR END PANEL INNER GARNISH	0.00	189.50	-20.00	151.60
28	1	REAR FENDER LH <i>repair</i>	0.00	968.60	-20.00	774.88
29	1	REAR FENDER RH <i>X</i>	0.00	0.00	0.00	0.00
30	1	REAR FENDER INNER TRIM BOARD LH	0.00	628.50	-20.00	502.80
31	1	REAR FENDER INNER TRIM BOARD RH <i>X</i>	0.00	628.50	-20.00	502.80
32	1	REAR EXHAUST SILENCER <i>X</i>	0.00	689.50	-20.00	551.60
33	1	REAR EXHAUST PIPE <i>X</i>	0.00	638.30	-20.00	510.64
34	1	REAR EXHAUST HEAT SHIELD <i>X</i>	0.00	80.00	-20.00	64.00
35	1	FRONT BUMPER <i>de</i>	0.00	635.40	-20.00	508.32
36	1	FRONT BUMPER SIDE RETAINER LH <i>de</i>	0.00	22.00	-20.00	17.60
37	1	FRONT BUMPER SIDE RETAINER RH <i>de</i>	0.00	22.00	-20.00	17.60
38	1	FRONT BUMPER BRACKET LH <i>de</i>	0.00	38.50	-20.00	30.80
39	1	FRONT BUMPER BRACKET RH <i>de</i>	0.00	38.50	-20.00	30.80
40	1	FRONT BUMPER INNER SPONGE	0.00	120.00	-20.00	96.00
41	1	FRONT BUMPER REINFORCEMENT	0.00	437.00	-20.00	349.60
42	1	FRONT BUMPER FOG LAMP LH <i>X</i>	0.00	295.00	-20.00	236.00
43	1	FRONT BUMPER LOWER GRILLE	0.00	80.00	-20.00	64.00
44	1	FRONT GRILLE <i>cm</i>	0.00	220.00	-20.00	176.00
45	1	FRONT GRILLE CHROME MOULDING	0.00	120.00	-20.00	96.00
46	1	FRONT GRILLE EMBLEM	0.00	53.00	-20.00	42.40
47	1	FRONT HEADLAMP HID LH	0.00	983.80	-20.00	771.04
48	1	FRONT HEADLAMP LOWER BRACKET LH	0.00	45.00	-20.00	36.00
49	1	FRONT HEADLAMP PANEL LH	0.00	110.00	-20.00	88.00
50	1	BONNET <i>bt</i>	0.00	680.00	-20.00	544.00
51	2	BONNET HINGES <i>X</i>	0.00	110.00	-20.00	88.00
52	1	BONNET LOCK <i>X</i>	0.00	130.00	-20.00	104.00
53	1	FRONT FENDER LH <i>X</i>	0.00	486.50	-20.00	389.20

4/29/16

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
54	1	FRONT FENDER INNER SHIELD LH X	0.00	80.50	-20.00	64.40
55	1	REAR SPARE TYRE PANEL repair	0.00	880.00	-20.00	704.00
			Total Parts (S\$)	<u>\$4949.76</u>		13,415.36

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR WINDSCREEN SEALANT na	0.00	60.00	0.00	60.00 40
2	1	REAR NUMBER PLATE cut	0.00	45.00	0.00	45.00 35
3	1	REAR BUMPER CLIPS na	0.00	45.00	0.00	45.00
4	1	REAR BUMPER SENSORS (SET) na	0.00	260.00	0.00	260.00 200
5	1	REAR BUMPER LOWER SKIRT (SPORTS) na	0.00	600.00	0.00	600.00 300
6	2	REAR EXHAUST MOUNTING X	0.00	30.00	0.00	30.00
7	1	FRONT NUMBER PLATE na	0.00	45.00	0.00	45.00 35
8	1	FRONT BUMPER LOWER SKIRT (SPORTS) na	0.00	600.00	0.00	600.00 300
9	1	FRONT FENDER INNER SHIELD CLIPS X	0.00	38.00	0.00	38.00
			\$955 Sub Total (S\$)			1,723.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	70.00	70.00	0.00	70.00 30
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00 60
3	1	To Transfer Rear Tailgate.	80.00	80.00	0.00	80.00 60
4	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	100.00	0.00	100.00
5	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	100.00	0.00	100.00 80
6	1	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	180.00	180.00	0.00	180.00 X
7	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	2,500.00	2,500.00	0.00	2,500.00 1400
			\$1730 Gross Labour Cost (S\$)			3,110.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	60.00	0.00	60.00 30
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	45.00	0.00	45.00
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	80.00	80.00	0.00	80.00 40
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	1,800.00	1,800.00	0.00	1,800.00 1400

\$1530

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
-----	-----	-------------	------	--------	-------	---------------

Gross Labour Cost (S\$) 1,985.00

< END OF ESTIMATES >

Rasul

Hp 90010068

12 days

HS

01/07/19 @ 1840

Ready after repair

email: rasul@lkkauto.com

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 11 July 2019 9:23 AM
To: YT(HQ); Rasul (LKKAuto); SUR
Subject: RE: SJK9298Y Finalize

Dear Vinnie,

WITHOUT PREJUDICE

Confirmed Lump Sum \$7300 @ 12 working days.

Kindly send Final invoice and all supporting documents directly to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: YT(HQ) <info@yewteegroup.com>
Sent: Wednesday, 10 July 2019 4:46 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Subject: SJK9298Y Finalize

Hi Rasul,

Attached the after repair photo and our calculation for your attention.

Kindly assist to finalize the repair cost with us soon.

Thank you

Best Regards

Vinnie Lim



Yew Tee Automobile Tech Pte Ltd

HQ:
Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 /6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:
Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg

Branch Office:
39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID: 62562081
Email: info@yewteegroup.com



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19011613/R1vd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 15-07-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 555R	Veh. Inspected	SJK 9298Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004244MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	01/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA STREAM 1.8X A	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	RN61087361	Colour	WHITE	
Odometer	139564	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	HANKOOK	6 mm	
L/H Front Tyre	215/45 R17	HANKOOK	6 mm	
R/H Rear Tyre	215/45 R17	HANKOOK	6 mm	
L/H Rear Tyre	215/45 R17	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/06/2019	Inspection Date	01/07/2019	
Survey held at	YEW TEE AUTOMOBILE TECH PL (HQ) BLK 6 WOODLANDS ROAD 399F YEW TEE IND. ESTATE SINGAPORE 678006			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 9298Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TAILGATE	BENT	1,160.00	1,160.00
1	REAR TAILGATE HINGES LH	SERVICEABLE	140.00	-
1	REAR TAILGATE HINGES RH	SERVICEABLE	140.00	-
1	REAR TAILGATE LOCK	BENT	303.80	303.80
1	REAR TAILGATE LOCK CATCH	SERVICEABLE	55.00	-
1	REAR TAILGATE RUBBER	CUT	189.00	189.00
1	REAR TAILGATE LOGO	NECESSARY	38.00	38.00
1	REAR TAILGATE STREAM EMBLEM	NECESSARY	58.00	58.00
1	REAR TAILGATE INNER TRIM BOARD	SERVICEABLE	489.50	-
1	REAR TAILGATE DAMPER LH	NOT NECESSARY	297.00	-
1	REAR TAILGATE DAMPER RH	NOT NECESSARY	297.00	-
1	REAR NUMBER PLATE OUTER GARNISH	CRACKED	183.40	183.40
2	REAR NUMBER PLATE LAMP	NOT NECESSARY	88.00	-
1	REAR TAILGATE OUTER HANDLE	NOT NECESSARY	189.00	-
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	118.00	118.00
1	REAR BUMPER	DEFORMED	1,185.00	1,185.00
1	REAR BUMPER SIDE RETAINER LH	NECESSARY	48.50	48.50
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	48.50	-
1	REAR BUMPER BRACKET LH	NECESSARY	41.40	41.40
1	REAR BUMPER BRACKET RH	NECESSARY	41.40	41.40
1	REAR BUMPER TOWING COVER	CRACKED	25.00	25.00
1	REAR TAILLAMP RH	NOT NECESSARY	454.30	-
1	REAR TAILLAMP LH	SCRATCHED	454.30	454.30
1	REAR TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	325.00	-
1	REAR TAILLAMP PANEL RH	SERVICEABLE	325.00	-
1	REAR END PANEL	BENT	685.00	685.00
1	REAR END PANEL INNER GARNISH	SERVICEABLE	189.50	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	968.60	-
1	REAR FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-

Report Ref No. CS/FC119011613/R1vd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER INNER TRIM BOARD LH	SERVICEABLE	628.50	-
1	REAR FENDER INNER TRIM BOARD RH	NOT NECESSARY	628.50	-
1	REAR EXHAUST SILENCER	NOT NECESSARY	689.50	-
1	REAR EXHAUST PIPE	NOT NECESSARY	638.30	-
1	REAR EXHAUST HEAT SHIELD	NOT NECESSARY	80.00	-
1	FRONT BUMPER	DEFORMED	635.40	635.40
1	FRONT BUMPER SIDE RETAINER LH	NECESSARY	22.00	22.00
1	FRONT BUMPER SIDE RETAINER RH	NECESSARY	22.00	22.00
1	FRONT BUMPER BRACKET LH	NECESSARY	38.50	38.50
1	FRONT BUMPER BRACKET RH	NECESSARY	38.50	38.50
1	FRONT BUMPER INNER SPONGE	SERVICEABLE	120.00	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	437.00	-
1	FRONT BUMPER FOG LAMP LH	SERVICEABLE	295.00	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	80.00	-
1	FRONT GRILLE	CRACKED	220.00	220.00
1	FRONT GRILLE CHROME MOULDING	NOT NECESSARY	120.00	-
1	FRONT GRILLE EMBLEM	NOT NECESSARY	53.00	-
1	FRONT HEADLAMP HID LH	SERVICEABLE	963.80	-
1	FRONT HEADLAMP LOWER BRACKET LH	SERVICEABLE	45.00	-
1	FRONT HEADLAMP PANEL LH	SERVICEABLE	110.00	-
1	BONNET	BENT	680.00	680.00
2	BONNET HINGES	SERVICEABLE	110.00	-
1	BONNET LOCK	SERVICEABLE	130.00	-
1	FRONT FENDER LH	SERVICEABLE	486.50	-
1	FRONT FENDER INNER SHIELD LH	SERVICEABLE	80.50	-
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	880.00	-
	LESS 20% DISCOUNT		-3,353.84	-1,237.44
			13,415.36	4,949.76
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
1	REAR NUMBER PLATE (SN)	CUT	45.00	35.00
1	REAR BUMPER CLIPS (SN)	NECESSARY	45.00	45.00

Report Ref No. CS/FCI19011613/R1vd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR BUMPER SENSORS (SN)	NOT WORKING	260.00	200.00
1	REAR BUMPER LOWER SKIRT (SPORTS)(SN)	TORN	600.00	300.00
2	REAR EXHAUST MOUNTING (SN)	SERVICEABLE	30.00	-
1	FRONT NUMBER PLATE (SN)	CRACKED	45.00	35.00
1	FRONT BUMPER LOWER SKIRT (SPORTS)(SN)	CRACKED	600.00	300.00
1	FRONT FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	38.00	-
			1,723.00	955.00
	LABOUR			
	TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS,REPLACE DAMAGED PARTS.		70.00	30.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		80.00	60.00
	TO TRANSFER REAR TAILGATE.		80.00	60.00
	TO DISMANTLE AND REFIT REAR WINDSCREEN GLASS.		100.00	100.00
	TO REMOVE AND REFIT CARPET AND TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		100.00	80.00
	TO REMOVE AND REFIT,STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REAR EXHAUST SILENCER AND MOUNTINGS.	NOT NECESSARY	180.00	-
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.INCLUSIVE OF THE REPAIR OF REAR TAILLAMP PANEL LH,REAR FENDER LH,REAR FENDER RH AND REAR SPARE TYRE PANEL.		2,500.00	1,400.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		60.00	60.00
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.		45.00	30.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		80.00	40.00
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		1,800.00	1,400.00
			5,095.00	3,260.00

Report Ref No. CS/FC119011613/R1vd3n2



GRAND TOTAL		20,233.36	9,164.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,300.00

Report Ref No. CS/FCI19011613/R1vd3n2

MARKET VALUE: \$30,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$13,981.00=NETT VALUE: \$16,019.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.