

# SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMD9500P/1906092

27<sup>th</sup> June 2019

The Manager  
Motor Claim Department  
AXA Insurance Pte Ltd  
8 Shenton Way,  
#27-01 AXA Tower  
Singapore 068811

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not added  
2/69  
5/69  
1/7/19  
Teh Jit Adenye

Date of Accident : 27<sup>th</sup> June 2019  
Location : BKE Towards Bukit Panjang Road  
Third Party Claim Vehicle No : GZ 6383 K  
Repair Cost For Vehicle No : SMD 9500 P Toyota Vellfire

## Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear fender RH	1	650.00	\$ 650.00
2	Rear fender cowling RH	1	0.00	\$ 0.00
3	Rear fender cowling clips RH	1set	20.00	\$ 20.00
4	Rear fender glass with moulding RH	1	450.00	\$ 450.00
5	Rear door garnish RH	1	0.00	\$ 0.00
6	Rear bumper fascia	1	280.00	\$ 280.00
7	Rear bumper clips	1set	20.00	\$ 20.00
8	Rear bumper side retainer RH	1	45.00	\$ 45.00
				\$ 1,465.00
			Cost Plus 15%	\$ 219.75
				\$ 1,684.75
9	Rear wheel rim RH (s/net)	1	2,981.60	\$ 2,981.60
10	Rear fender glass sealant (s/net)	1	40.00	\$ 40.00
				\$ 4,706.35

## SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMD9500P/1906092

27<sup>th</sup> June 2019

Balance b/f \$ 5,773.20

### Labour Charges :-

### Amounts

Cut out, renew, knocking & welding rear fender RH, rear corner panel RH, rear door assy RH, remove & install all damage parts & re-align body	\$ 780.00	700
Remove & install rear fender glass	\$ 100.00	✓
Remove & install rear seats, carpets, upholstery & etc	\$ 280.00	✓
Remove & install rear door glass, board & etc	\$ 120.00	✓
Tuff-kote on damage parts	\$ 40.00	✓
Computerise wheel alignment	\$ 120.00	60
Spray painting on damage parts	\$ 1,380.00	800
Check all lighting after repairs	\$ 40.00	20
Labour Charge	\$ 2,860.00	
Total Amount	\$ 8,633.20	

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.