

AS3. REC. BY:

REF: CS/FCI/9011615/Vg d3 n2

Special Instruction:

SUVA/01

marcus

ASSIGNMENT (Office)

From (Person): Karan

of

FCI

Date/Time: 1.7.19 3.35pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLD 6004L

Insured: SHC 2086D

at Workshop m/s Kah Motor

Tel: 6846571

of 15 ubi Road 4

Policy No:

Claim No: D19004264MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 28.6.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 1.7.19 3.43pm

Person Contacted: Lim

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 2086D -X
	SLD 6004L -X
04/7/19 @ 9.35am	revised to Karan Tan by email.

ASSIGNMENT

From:

Date:

3.7.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLD 6004L

at Workshop n/s: Kah motor

of 15 ub road 4

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh: 4.30pm owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

CA / R Soon:

Est. Repairs:

Lump Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:



Vehicle, IN / OUT

Veh No:

SLD6004L

Yr Regn:

6, 16

Type: M / Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A /

Make:

Honda Jazz

c.c. 1498

Colour:

grey

A/C:

Insured / Std / NI / NA

Sp. Reading:

40695

T/Radio:

Insured / Std / NI / NA

Eng/No:

JHMAK58506K203023

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO (YOKO) or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

28/6/19

D.O.L.

3/7/19

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

17/7/19

Action / Instruction

Confirmed find of \$7853.47 with max. amount
Chkd & 7531.75 (4%)

RECEIVED 22 JUL 2019

19/7/2019

Date/Time, File Pass to:

17/7/2019



Prel. Report



Final Report

Date/Time, File Return to:

2)

Days Of Repair:

7

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format:

TR

Lump Sum / L.B.I. (\$

7853.47

Survey Fee:

Transportation:

3 + 45 = 48

Photos:

Others:

TOTAL

170
50
50+50
66
386



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004264MFSH

Date: 04 July 2019

Our Ref: CS/FCI19011615/Uqd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLD 6004L

Please be informed that we had conducted the inspection of the abovementioned vehicle on 03/07/2019 at the premises of M/s KAH MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>10,384.72</u>
Revised Estimate Amount	: S\$ <u>5,757.69</u>
"Check" Items Amount	: S\$ <u>1,170.95</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	01-07-2019	Our Ref No. D19004264MFSH
Accident Date	28-06-2019	Claim Type. Third Party
Insured Vehicle	SHC2086D	Third Party Vehicle. SLD6004L
Survey Location	15 UBI ROAD 4	
Contact Person.	LIM CHOU SIONG	
Contact No.	68465671/ 68465671	Fax No. 67480770
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO SDN BHD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 4 July 2019 9:35 AM
To: 'CWS Motor Claims'; assignments; SUR
Cc: 'Karen Tan'
Subject: RE: SURVEY ASSESSMENT - D19004264MFSH/1
Attachments: CSFCI19011615Uqd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SLD 6004L.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 1 July 2019 3:49 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19004264MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed that vehicle not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 1 July, 2019 3:35 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004264MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

New Cars

Used Cars

Sell My Car


Directory

Products

Insurance

Articles

F



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8A



3.18%P.A \$0 Admin Fees@GV
Finance, 2 Years Warranty.
Monthly From \$688.
GV Credit Pte Ltd [StarAd](#)



Browse by Category ▼

Sort by Date Posted

20 vehicles

honda jazz

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	honda jazz		Any	Any	2016	Any	Any	
	Honda Jazz 1.5A RS		\$65,800	\$8,070 /yr	14-Nov-2016	1,498 cc	25,517 km	
New Arrival! High Spec RS Model With Push Start And Keyless Entry! One Of The Most Popular Hatchback For Economical Usage. Powerful, Reliable & Responsive Engine. 1 Lady Owner Only. Stylish Blue. Very Low Mileage 25,517KM Done. Fully Agent Service & 5 Year Warranty.								
Posted: 03-Jul-2019 Tags: 2016 Honda Jazz, 2016 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda								
	Honda Jazz 1.5A RS		\$62,800	\$8,030 /yr	28-Jul-2016	1,498 cc	54,000 km	
Attractive Interest Rates Starting From 2.28%! 1 Owner Only Gun Metal Grey Jazz! Very Well Taken Care By Previous Owner! Tip Top Condition! Fully Maintained By Kah Motor Since Day 1! Agent Warranty Till 2021! 100% Loan Approval! Flexible Loan Available! Call Directly.								
Posted: 02-Jul-2019 Tags: 2016 Honda Jazz, 2016 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda								
	Honda Jazz 1.5A RS (OPC)		\$52,888	\$6,970 /yr	15-Apr-2016	1,498 cc	48,000 km	
Enjoy Low-Interest Rate Loan Packages. Agent Unit. 5 Years Warranty From Kah Motors. Option To Convert To Normal Plate At \$12,225. One Of The Most Reliable And Fuel Efficient Honda Jazz RS. Low Maintenance. As Good As New. 1 Owner Only. Full Agent Serviced. High Mileage.								
Euro Performance Asia Pte Ltd								
Posted: 01-Jul-2019 Tags: 2016 Honda Jazz, 2016 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda								
	Honda Jazz 1.5A RS		\$63,800	\$8,170 /yr	25-Jul-2016	1,498 cc	37,339 km	
Graded A by STA								
Purchase From An Award Winning Dealership! STA Certified Accident-Free Quality Pre-Owned With Low Mileage And Agent Service History For Peace Of Mind. 100% Loan Approval With Our Flexible In House Financing Options. View Today!								
Cosmo Automobiles								
Posted: 01-Jul-2019 Tags: 2016 Honda Jazz, 2016 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda								
	New Mercedes-AMG GT 4-Door Coupe launched							
The new Mercedes-AMG GT 4-Door Coupe, the brand's new high-performance Gran Turismo offering, has been launched in Singapore. Find out more!								
	Honda Jazz 1.5A RS		\$68,800	\$8,600 /yr	20-Oct-2016	1,498 cc	41,217 km	
By Vicom, Free 6 Months Maintenance And 1 Grooming.;								
Seng Motor								

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1620F
Vehicle Details	
Vehicle No.:	SLD6004L
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	L15B31021239
Chassis No.:	JHMGK5850GX203023
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$16,838.00
Original Registration Date:	23 Jun 2016
First Registration Date:	23 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$11,838.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jun 2026
PARF Rebate Amount:	\$8,878.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,889.00
COE Rebate Amount:	\$33,362.00
Total Rebate Amount:	\$42,240.00

The information contained herein is correct as at 04 Jul 2019

OK



Liberty Insurance Pte Ltd
Registration no. 199002791D
51 Club Street
#03-00 Liberty House
Singapore 069428
Tel: (65) 6221 8611 Fax: (65) 6225 6890
Website: <http://www.libertyinsurance.com.sg>

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate No	SD18V04443 /NPC2 /R00
Form	MX1
Date of Issue	08-MAY-2018
1.Index Mark and Registration No. of Vehicle:	SLD6004L
2.Chassis number of Vehicle:	JHMGK5850GX203023
3.Name of Policyholder:	SEE POH GEOK
4.Effective date of Commencement of Insurance for the purposes of the Act:	23-JUN-2018 00:00 AM
5.Date of Expiry of Insurance:	22-JUN-2020 23:59 PM
6.Persons or Classes of Persons entitled to drive*:	
A) The Policyholder.	
B) Any other person who is driving on the Policyholder's order or with his permission.	
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.	
And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.	
7.Limitations as to use*:	
Use only for social, domestic and pleasure purposes and for the Policyholder's business.	
8.The Policy does not cover:	
A) Use for hire or reward.	
B) Use for racing, pace-making, reliability trials or speed-testing.	
C) Use for the carriage of goods (other than samples) in connection with any trade or business.	
D) Use for any purpose in connection with the Motor Trade.	
*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.	
I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).	
For and on behalf of LIBERTY INSURANCE PTE LTD Approved Insurers	
 _____ Authorised Signature	
For information only:	
COVERAGE :	Comprehensive, Unlimited Windscreen, NCD Protection
SUM INSURED:	MARKET VALUE AT THE TIME OF LOSS
EXCESS:	Section I S\$600, Additional Excess For Young & Inexperienced Drivers S\$3000, Windscreen Excess S\$100
FINANCE COMPANY:	OVERSEA-CHINESE BANKING CORPORATION LTD
PRODUCER NAME:	KAH MOTOR COMPANY SDN BERHAD

PLMJ/PLMJ/16-MAY-18

S1_CI_T1_T3_OE_Template2-Ver1.

16-MAY-18

IDENTITY CARD NO S0061620F



Name:

SEE POH GEOK

施宝玉

Race:

CHINESE

Date of birth:

28-12-1949

Sex:

F

40616701

Country/Place of birth:

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S0061620F

Name: SEE POH GEOK

Birth Date: 28 Dec 1949

Issue Date: 16 Dec 2002

100017877E

6116068



NRIC No: S0061620F

Date of issue:

31-01-2019

Address:

APT BLK 5 MARINE TERRACE
#07-264
SINGAPORE 440005

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE
03 Dec 1974



Licence No: S0061620F

NP 428A

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Kindly Help to arrange
Surveyor to survey this
Vehicle
thanks

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SLD6004L

Chassis No : JHMGK5850GX203023

Model : JAZZ 1.5VTIR CVT 16YM

Owner's Name : SEE POH GEOK

Ins Policy No. :

Date of Accident : 28/6/2019

Document No. : SQT19002854

Date : 29. Jun 2019

Customer No. : WZF002

Svc Advisor : LIM CHOU SIONG

Engine No : L15B31021239

Date | Time : 29. Jun 2019 2:41:23 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: SEE POH GEOK						
	OWNER INSURER: LIBERTY INSURANCE PTE LTD						
	ACC DATE: 28/6/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED						
	TP VEH: SHC2086D						
73127-TY0-000	RUBBER C WINDSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBER WINDSHIELD DAMPER	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPER STD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T5B-Z50ZZ	TAILGATE COMP	1	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHERSTRIP TAILGATE	1	92.30	25	69.22	4.85	74.07
74800-T5S-K61	LOCK ASSY, TAILGATE	1	85.50	25	64.12	4.49	68.61
74813-T5A-003	STRIKER ASSY TAILGATE	1	24.70	25	18.52	1.30	19.82
84440-T5A-J02ZA	LINING ASSY TAILGATE LOWER	1	53.70	25	40.27	2.82	43.09
84441-T5A-003ZB	POCKET TAILGATE LINING PULL	1	5.10	25	3.82	0.27	4.09
75722-T5L-T01	EMBLEM RR.	1	10.90	25	8.17	0.57	8.74
33500-T5A-J02	TAILLIGHT ASSY, R.	1	223.90	25	167.92	11.75	179.67
34150-T5A-J01	LIGHT ASSY, LID	1	81.70	25	61.27	4.29	65.56
90650-SZT-003	GROMMET RR, COMBINATION LIGHT	1	2.50	25	1.87	0.13	2.00
90650-TX6-A01	CLIP RR, COMBINATION LIGHT	1	2.00	25	1.50	0.11	1.61
91626-S0X-A01	GROMMET	1	2.00	25	1.50	0.11	1.61
74890-T5B-911	GARNISH ASSY RR, LICENSE	1	200.60	25	150.45	10.53	160.98
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L (N)	1	45.00		45.00	3.15	48.15
NMRS-4P-TM3040L	4PCS ACT RR, SENSOR	1	320.00		320.00	22.40	342.40

Printed on 30/6/2019 10:52:40 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Registration No : SLD6004L

Chassis No : JHMGK5850GX203023

Model : JAZZ 1.5VTIR CVT 16YM

Owner's Name : SEE POH GEOK

Ins Policy No. :

Date of Accident : 28/6/2019

Document No. : SQT19002854

Date : 29. Jun 2019

Customer No. : WZF002

Svc Advisor : LIM CHOU SIONG

Engine No : L15B31021239

Date | Time : 29. Jun 2019 2:41:23 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
04715-T5B-000ZZ	FACERR.BUMPER	1	502.50	25	376.87	26.38	403.25
71502-T5A-000	GARNISHR.RR.BUMPER	1	14.30	25	10.72	0.75	11.47
71593-T5A-000	SPACERR.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP.BUMPER	5	2.30	25	8.62	0.60	9.22
66100-TAR-T10ZZ	PANEL COMPRR.	1	320.40	25	240.30	16.82	257.12
84521-T5A-901ZA	LID ASSYSAPRE TIRE	1	189.80	25	142.35	9.96	152.31
84550-T5S-M10	BOX ASSYCARGO FLOOR	1	107.00	25	80.25	5.62	85.87
84601-TAR-Z03ZA	LINING ASSYR.TRUNK	1	169.00	25	126.75	8.87	135.62
84640-T5A-003ZA	LINING ASSYRR.PANEL	1	60.80	25	45.60	3.19	48.79
38387-TZ5-A01	ANTENNA ASSYL.F.	1	59.30	25	44.47	3.11	47.58
74940-TZ5-A01	BUZZER ASSYSMART	1	60.40	25	45.30	3.17	48.47
Sum Item					2724.72	190.73	2,915.45
BOSUN	SUNDRIES	1	50.00		50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00		80.00	5.60	85.60
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00		130.00	9.10	139.10
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00		300.00	21.00	321.00
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	320.00		320.00	22.40	342.40
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	320.00		320.00	22.40	342.40
BMI02D	REMOVE & INSTALL REAR COMPARTMENT LININGS, RR1	1	350.00		350.00	24.50	374.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	380.00		380.00	26.60	406.60
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN	1	2400.00		2400.00	168.00	2568.00
BP06R	SPRAY PAINTING ON FLOOR PANEL, RR PANEL, RR BUMPER	1	2900.00		2900.00	203.00	3103.00
BOJSE	BODY JOINT SEALANT.	1	80.00		80.00	5.60	85.60
Sum Labor					7660.00	536.20	8,196.20

Printed on 30/6/2019 10:52:40 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3638

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223


Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLD6004L
Chassis No : JHMGK5850GX203023
Model : JAZZ 1.5VTIR CVT 16YM
Owner's Name : SEE POH GEOK
Ins Policy No. :
Date of Accident : 28/6/2019

Document No. : SQT19002854
Date : 29. Jun 2019
Customer No. : WZF002
Svc Advisor : LIM CHOU SIONG
Engine No : L15B31021239
Date | Time : 29. Jun 2019 2:41:23 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Survey By	<i>marcus, htl</i>						
Date & Time	<i>3/7/19</i>						
Excess	<i>C S Lim</i>						
Status	<i>81006303 (HIC)</i>						
Signature	<i>not signed</i>						
	<i>the job Beru poly.</i>						
	<i>SK 7 dy.</i>						
Total Amount					10,384.72	726.93	11,111.65
Total (Inclusive of GST)							11,111.65



Printed on 30/6/2019 10:52:40 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



16/07/2019 Page 1/2
 (C) SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)

Attn: Marcus (L.K.K.)

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
 255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

7 days

Customer:	WZF002 / MS FIRST CAPITAL	Document No:	SVO19043513
Chassis No:	JHMGK5850GX203023	Printed By:	CSLIM
License No:	SLD6004L	Order Date:	8. July 2019
Mileage:	40824	Order Time:	1:20:23 PM
Engine No:	L15B31021239	Service Advisor:	LIM CHOU SIONG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	incd GST
	TP DIRECT SETTLEMENT (J/NO: 73022)						
	OWNER: SEE POH GEOK						
	OWNER INSURER: LIBERTY INSURANCE PTE LTD						
	ACC DATE: 28/6/2019						
	SURVEYED BY: MARCUS (L.K.K.)						
	DATE: 03/07/2019 @ 16:30PM						
	REF NO: D19004264MFSH						
	TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED						
	TP VEH: SHC2086D						
73127-TY0-000	RUBBER CWINDOWSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDOWSHIELD DAMPER	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T5B-Z50ZZ	TAILGATE COMP	1	730.60	25	547.95	38.36	586.31
75722-T5L-T01	EMBLEMRR.	1	10.90	25	8.17	0.57	8.74
33500-T5A-J02	TAILLIGHT ASSY.R.	1	223.90	25	167.92	11.75	179.67
90650-SZT-003	GROMMETRR.COMBINATION LIGHT	1	2.50	25	1.87	0.13	2.00
90650-TX6-A01	CLIPRR.COMBINATION LIGHT	1	2.00	25	1.50	0.11	1.61
04715-T5B-000ZZ	FACERR.BUMPER	1	502.50	25	376.87	26.38	403.25
91505-TM8-003	CLIP.BUMPER	5	2.30	25	8.62	0.60	9.22
66100-TAR-T10ZZ	PANEL COMPRR.	1	320.40	25	240.30	16.82	257.12
84640-T5A-003ZA	LINING ASSYRR.PANEL	1	60.80	25	45.60	3.19	48.79
	SUM PARTS:				1,483.47	103.84	1,587.31
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BML02I	EXT-YJ	1	80.00		80.00	5.60	85.60
	INSPECT RR LIGHTING MECHANISMS.						
	PERFORM WATER						
	TEST.(N)						
BOBC	0760	1	100.00		100.00	7.00	107.00
	BODY UNDERSIDE COATING (N)						
BA02R	EXT-YJ	1	100.00		100.00	7.00	107.00
	REMOVE & RENEW REVERSE						
	SENSORS-4 PCS (N)						
BP00R	EXT-YBH	1	180.00		180.00	12.60	192.60
	APPLY BODY UNDERSIDE COATING (N).						
BG02D	EXT-YJ	1	300.00		300.00	21.00	321.00
	REMOVE & INSTALL RR. WINDSCREEN.						
	(N)						
BC011R	EXT-YJ	1	320.00		320.00	22.40	342.40
	REMOVE INSTALL & CALIBRATE REAR						
	VIEW CAMERA						
BC012R	0760	1	320.00		320.00	22.40	342.40
	RESET VEHICLE SMART ENTRY SYSTEM						
BMI02D	EXT-YJ	1	280.00		280.00	19.60	299.60
	REMOVE & INSTALL REAR						
	COMPARTMENT LININGS, RR						
	SEATS, TRUNK LININGS, GARNISHES &						
	ETC.(N)						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: JHMGK5850GX203023
License No: SLD6004L
Mileage: 40824
Engine No: L15B31021239

Document No: SVO19043513
Printed By: CSLIM
Order Date: 8. July 2019
Order Time: 1:20:23 PM
Service Advisor: LIM CHOU SIONG

BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	380.00	380.00	26.60	406.60
BKRP02M	EXT-YJ CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM	1	1,960.00	1,960.00	137.20	2,097.20
BP06R	EXT-YBH SPRAY PAINTING ON FLOOR PANEL, RR PANEL, RR BUMPER TAILGATE, RR R FENDER & RR L FENDER	1	2,250.00	2,250.00	157.50	2,407.50
BOJSE	EXT-YJ BODY JOINT SEALANT.	1	80.00	80.00	5.60	85.60
			SUM LABOUR:	6,370.00	445.90	6,815.90
			TOTAL SGD	7,853.47	549.74	8,403.21
Total Payable (SGD)						8,403.21

GST Amount is calculated from individual line(s)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19011615/Uqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 22-07-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2086D	Veh. Inspected	SLD 6004L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004264MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	01/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ (A)	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JHMGK5850GX203023	Colour	GREY	
Odometer	40695	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	YOKOHAMA	7 mm	
L/H Front Tyre	185/55 R16	YOKOHAMA	7 mm	
R/H Rear Tyre	185/55 R16	YOKOHAMA	7 mm	
L/H Rear Tyre	185/55 R16	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/06/2019	Inspection Date	03/07/2019	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 6004L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RUBBER CWINDSHIELD DAMPER (SN)	NECESSARY	8.55	8.55
2	RUBBER WINDSHIELD DAMPER (SN)	NECESSARY	9.75	9.75
1	DAMPERSTD 5X5 (SN)	NECESSARY	6.37	6.37
1	WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	TAILGATE COMP (SN)	BADLY DENTED	547.95	547.95
1	WEATHERSTRIP TAILGATE (SN)	NOT NECESSARY	69.22	-
1	LOCK ASSY,TAILGATE (SN)	NOT NECESSARY	64.12	-
1	STRIKER ASSY TAILGATE (SN)	NOT NECESSARY	18.52	-
1	LINING ASSY TAILGATE LOWER (SN)	NOT NECESSARY	40.27	-
1	POCKET TAILGATE LINING PULL (SN)	NOT NECESSARY	3.82	-
1	EMBLEMRR (SN)	NECESSARY	8.17	8.17
1	TAILGATE ASSY,R (SN)	CUT	167.92	167.92
1	LIGHT ASSYR LID (SN)	NOT NECESSARY	61.27	-
1	GROMMETRR COMBINATION LIGHT (SN)	NECESSARY	1.87	1.87
1	CLIPRR COMBINATION LIGHT (SN)	NECESSARY	1.50	1.50
1	GROMMET (SN)	NOT NECESSARY	1.50	-
1	GARNISH ASSYRR LICENSE (SN)	NOT NECESSARY	150.45	-
1	NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	45.00	-
1	4PCS ACT RR SENSOR (SN)	SERVICEABLE	320.00	-
1	FACERR BUMPER (SN)	DENTED / DEFORMED	376.87	376.87
1	GARNISHR RR BUMPER (SN)	NOT NECESSARY	10.72	-
1	SPACERR RR BUMPER (SN)	NOT NECESSARY	8.62	-
1	SPACERL RR BUMPER (SN)	NOT NECESSARY	8.62	-
5	CLIP,BUMPER (SN)	NECESSARY	8.62	8.62
1	PANEL COMPRR (SN)	BADLY DENTED	240.30	240.30
1	LID ASSYSPARE TIRE (SN)	NOT NECESSARY	142.35	-
1	BOX ASSYCARGO FLOOR (SN)	NOT NECESSARY	80.25	-
1	LINING ASSYR TRUNK (SN)	NOT NECESSARY	126.75	-
1	LINING ASSYRR PANEL (SN)	DEFORMED / TWISTED	45.60	45.60

Report Ref No. CS/FCI19011615/Uqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ANTENNA ASSYL.F (SN)	NOT NECESSARY	44.47	-
1	BUZZER ASSYSMART (SN)	NOT NECESSARY	45.30	-
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	BODY JOINT SEALANT (SN)	NECESSARY	80.00	80.00
			2,854.72	1,583.47
	LABOUR			
	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER.		80.00	80.00
	BODY UNDERSIDE COATING.		100.00	100.00
	REMOVE & RENEW REVERSE SENSORS-4 PCS.		130.00	100.00
	APPLY BODY UNDERSIDE COATING.		250.00	180.00
	REMOVE & INSTALL RR WINDSCREEN.		300.00	300.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA.		320.00	320.00
	RESET VEHICLE SMART ENTRY SYSTEM.		320.00	320.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS,RR.		350.00	280.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST.		380.00	380.00
	CUT OFF & RENEW RR PANEL STRAIGHTEN ALIGN.		2,400.00	1,960.00
	SPRAY PAINTING ON FLOOR PANEL RR PANEL,RR BUMPER.		2,900.00	2,250.00
			7,530.00	6,270.00
GRAND TOTAL			10,384.72	7,853.47
RECOMMENDED COST OF REPAIRS				7,853.47

Report Ref No. CS/FCI19011615/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.