

1/2020

INS. CASE OWNER:

CC 3 /AIG1901

1620 T. 263/

LKK:

IDAC:

Surveyor:

Tom Hich

DOI:

ASSIGNMENT

6/8/19

Date / Time:

11/1/19

Registered in Merimen:

1/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SM 5938B

Name of Insured:

TAN KHEHA MEE EVELIN

Insured Tel No.:

HP:

Excess Sec II :\$S

D.O.A:

30/6/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

3837478856

Policy No.:

1800 04031

Make / Model:

VOLVO

Place of Accident:

SIN MING KO

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SMK 914584



INSRS:

WSP:

Tel:

Liability:

RMKS:

Performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
		Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OH	
		After call ltr to OH:	
		Documentation Check List: Handler	Typist
		Notification ltr (if non-pickup)	
		After call ltr to OH:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Repair Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

Date/ Time

26/11/19
checking

SMK 914584 - 1620 5938B - 1

File pass to type mandate

9/1/2020
1620 5938B

File pass to mk to close

ATA ss - TP claimant's name wrong,
no company stamp.

PRELIMINARY ADVICE	Date/Time:	Sent By:
--------------------	------------	----------

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
--------------	------------	---------------	-------------

Repair Cost:	8/8	\$S 19,031.60	(8 days) Reduction: 20 %	Email ☐ Call ☐
--------------	-----	---------------	---------------------------	--

FINAL SETTLEMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
------------------	------------	---------------	--

Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	27	If NO or B 28, Ass. Lia:
------------------	-------	-----------------------------------	----	--------------------------

Repair Cost:	(w/451)	\$S 20,353.11		COI REAR END 1/1
--------------	---------	---------------	--	------------------

Loss of Rental (LOR):	\$S	(- days)		
-----------------------	-----	-----------	--	--

Loss of Use (LOU):	\$S	600 (S 60 x 10 days)		
--------------------	-----	----------------------	--	--

Loss of Income (LOI):	\$S	(S - x - days)		
-----------------------	-----	----------------	--	--

LOR only ☐ LOU only ☐	☒ LOR + LOU ☐ LOR + LO ☐	(Tick only one)		
---	--	-----------------	--	--

GIA/LTA Search	\$S	2.00		
----------------	-----	------	--	--

Medical:	\$S	-		
----------	-----	---	--	--

Disbursement:	\$S	-	(e.g. Tow/ Independent)	
---------------	-----	---	-------------------------	--

Legal Cost	\$S	-		
------------	-----	---	--	--

Total:	\$S	20,955.11	Global Sum \$S:	
--------	-----	-----------	-----------------	--

FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
---------------	------------	---------------	--

Payee 1:	\$S	20,955.11	Name 1:	PERFORMANCE MOTORS LIMITED
----------	-----	-----------	---------	----------------------------

Payee 2: (Strike if N.A.)	\$S		Name 2:	
---------------------------	-----	--	---------	--

Payee 3: (Strike if N.A.)	\$S		Name 3:	
---------------------------	-----	--	---------	--

COPY SENT
9/1/2020

1) Claim status: Normal/Reject/Private Settle
2) Report Format: 1P
3) Survey fee: \$320

Taufith

Ally

SMK 9/454

2019 April

BYM 2/6E

1499

6/ve
5807

WBA6U1206ED05058

205/55K12

9130K

.8

Chin

pml

Rear o/s

6
6
4/8/19 0345pm

CP/P \$ 19,021.60 (Red 7 8, 158.10/30%)

8 days + 2 PH + 1 Sunday = 11 days
(National day + Hari Raya Haji)

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W SST Reg. No. M2-0020081-X
 Toll-Free Number (1800-2251259)

161, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax: 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax: 63449773

115, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax: 64796001 (AfterSales)
 64796024 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 51760 Page No. : 1 of 6
 Date Estimated : 01/07/2019
 Prepared By : Chua Kee Sin

- ESTIMATE REPAIR FOR -

Performance Premium Selection Ltd
 280 Kampong Arang Road
 East Coast Centre

Singapore 438180

- ACCOUNT - 66

~~MSIG Insurance (S) Pte Ltd~~ AIG
~~4 Shenton Way~~
~~#21-01 SGX Centre 2~~
~~Singapore 068807~~

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK9145U	ED05858	29/04/2019	216i GT	0

DESCRIPTION

Replace right rear side fender rear boot lid, rear bumper and remove attachment etc include knock on accident dent

Spray painting right side rear fender, rear bumper, rear boot lid, floor pan and tail pan

To replace rear windscreen glass.

To conduct water leak tests.

To supply and install rear windscreen solar film.

To remove and install boot compartment carpet and garnish to facilitate repairs.

To supply and install rear right window glass solar film.

To carry out body cavity preservation. (For cut panel).

To carry out body cavity preservation. (2 panel).

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (4x)

Sundries.

VALUE

✓ 5100 7,650.00

✓ 3175 4,082.00

✓ 488 574.00

✓ 63 75.00

451 531.00

230 271.00

361 425.00

451 531.00

200 236.00

451 531.00

✓ 150.00

Total Labour 1: 15,056.00

DESCRIPTION

PLASTIC NUT FOR COARSE THREADED PIN
 BOOTLID
 REAR RH SIDE PANEL - plastic

QTY	PRIC
6	0.80
1	1,204.35
1	1,466.65

VALUE

add 4.80

1,204.35

1,466.65

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2255249)

315, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

244, Kampong Arang Road
East Coast Centre
Singapore 438190
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796451 (AfterSales)
64796424 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 51760
Date Estimated : 01/07/2019
Prepared By : Chua Kee Sin

Page No. : 2 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK9145U	ED05858	29/04/2019	216i GT	0

DESCRIPTION

Positionieru
REINFORCEMENT PLATE UNIVERSAL
Reinforcemen
Reinforcemen
Reinforcemen
T WELD BOLT L=5.4MM
RR BUMPER RH SIDE GUIDE
REAR BUMPER CARRIER
SUPPORT
LEFT PROTECT
RIGHT PROTEC
REAR BUMPER TOWING FLAP EYE PRIMED
REAR BUMPER TRIM STRIP (BLACK)
REAR BUMPER PANEL PRIMED (LINES PDC
SET MOUNTS PDC SENSOR REAR
LETTERING 216 I
GROMMET
PLAQUE 74MM
PLASTIC NUT
BUMP STOP
REAR WINDOW
HOOK AND LOOP FASTENER
REAR RH SIDE WINDOW FIXED (ALU HOCH
RR RH WHEEL HOUSING COVER
BOOTLID SEALING
REAR RH REFLECTOR
Rear light ing
REAR RH LIGHT IN TRUNK LID
RH GUTTER STRIP
DECOUPING RING PDC TORQUE CONVERTER
ULTRASONIC SENSOR GLACIERSILBER(WA8
CAVITY PROTECTION WAX REMOVER 500ML
BLIND RIVET AVIBVLB
SCREW (SF PLUS M5X15)
(DG/SL) BODY ADHESIVE K5B (195ML)
(DG) BODYWORK ADHESIVE K5A (50ML)
(DG) CLEANER R1 (100ML)
(DG) CLEANER R1 (100ML)
(DG) CLEANER R1 (100ML)
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)
PUNCH RIVET N4
(DG/SL) GLASS PRIMER 30ML (VP206)
(DG/SL) GLASS PRIMER 30ML (VP206)

QTY PRIC

1 5.85
1 52.20
1 52.40
1 52.40
1 52.40
10 0.85
1 61.50
1 458.10
1 45.30
1 11.20
1 11.20
1 42.85
1 70.75
1 1,029.50
1 60.35
1 64.10
2 0.75
1 71.25
4 0.85
10 3.50
1 654.35
4 2.85
1 277.00
1 135.05
1 143.00
1 37.90
1 270.50
1 255.65
1 51.95
4 5.05
4 368.80
1 18.45
4 0.55
5 0.55
2 326.80
1 112.70
1 26.15
1 26.15
1 26.15
2 131.55
1 131.55
20 0.55
1 27.85
1 27.85

VALUE

7 5.85
52.20
52.40
52.40
52.40
8.50
61.50
458.10
45.30
11.20
11.20
42.85
70.75
1,029.50
60.35
64.10
1.50
71.25
3.40
35.00
654.35
11.40
277.00
135.05
143.00
37.90
270.50
255.65
51.95
20.20
18.45
4.40
1.65
326.80
112.70
26.15
26.15
26.15
263.10
131.55
19.80
27.85
27.85

Total Parts : 9,210.15

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No. M2-0020081-X
Toll-Free Number: (800-225249)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Raffles Avenue Road
East Coast Centre
Singapore 438188
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64766021 (AfterSales)
64766024 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 51760
Date Estimated : 01/07/2019
Prepared By : Chua Kee Sin

Page No. : 3 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK9145U	ED05858	29/04/2019	2161 GT	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date/Time: 6/8/19 Excess \$0

Surveyor's Name: T. S. S. S. S. Sign: [Signature]

Surveyor's Tel: 97495144 Authorised: Yes/No

Authorised Date: 6/8/19 Time: _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes/No PML Yes/No

Surveyor's E-mail: t.s.s.s.s@lkk.com

No. of Working Days Recommend: 8-10 days

Labour 1	:	15,056.00
Parts	:	9,210.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,698.63
Grand Total	:	25,964.78

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

24384.60

27298.15



Final Report

Estimate No. : **b1 51760**
Date Estimated : **01/07/2019**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
Performance Premium Selection Ltd
280 Kampong Arang Road
East Coast Centre

Singapore 438180

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK9145U	WBA6V12060ED058	29/04/2019	216i GT	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments, rear boot lid and rear right fender etc including to remove and install body parts in order to carry out painting job.	5,100.00	0	5,100.00
To respray rear bumper, rear boot lid, rear right fender, trunk floor panel and tail end panel etc.	3,195.00	0	3,195.00
To remove and install rear windscreen glass to facilitate repair job.	574.00	0	574.00
To conduct water leak tests.	75.00	0	75.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	230.00	0	230.00
To carry out body cavity preservation. (For cut panel).	451.00	0	451.00
To carry out body cavity preservation.	200.00	0	200.00
To check steering geometry and conduct wheel alignment according to BMW specification	451.00	0	451.00
Sundries.	150.00	0	150.00
# To remove and install fuel tank to facilitate repair job including to conduct checks for leak.	451.00	0	451.00 ✓
# To check electrical wiring system at the rear section for proper function.	150.00	0	150.00 ✓
# To replace right trunk floor and tail end panel	1,700.00	0	1,700.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT WITH COLLAR M5	5.30	2	0	10.60
BOOTLID	1,204.35	1	0	1,204.35 ?



Final Report

# TAIL PANEL	355.20	1	0	355.20 ✓
REAR RH SIDE PANEL	1,466.65	1	0	1,466.65 ✓
# RH TRUNK FLOOR	111.60	1	0	111.60
RR BUMPER RH SIDE GUIDE	61.50	1	0	61.50 ?
REAR BUMPER CARRIER	458.10	1	0	458.10 ?
# RR BUMPER RH INNER SIDE GUIDE	67.55	1	0	67.55
REAR BUMPER TRIM STRIP (BLACK)	70.75	1	0	70.75 ?
REAR BUMPER PANEL PRIMED (LINES PDC	1,045.45	1	0	1,045.45 ?
LETTERING 216 I	64.10	1	0	64.10 ?
GROMMET	0.75	2	0	1.50 ?
PLAQUE 74MM	71.25	1	0	71.25 ?
BUMP STOP	3.50	10	0	35.00 ?
REAR RH REFLECTOR	37.90	1	0	37.90 ?
DECOUPING RING PDC TORQUE CONVERTER	5.05	4	0	20.20 ?
BLIND RIVET AVIBVLB	0.55	40	0	22.00 ?
SCREW (SF PLUS M5X15)	0.55	5	0	2.75 ?
(DG/SL) BODY ADHESIVE K5B (195ML)	326.80	2	0	653.60 ?
PUNCH RIVET N4	0.55	20	0	11.00 ?
(DG) BODYWORK ADHESIVE K5A (50ML)	112.70	1	0	112.70 ?
(DG) CLEANER R1 (100ML)	26.15	1	0	26.15 ?
(DG) CLEANER R1 (100ML)	26.15	1	0	26.15 ?
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2	0	263.10 ?
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1	0	27.85 ?
# (S/L) SEAM SEAL 300ML	33.80	2	0	67.60
#				
#				

SUPPLEMENTARY ITEMS

Total Labour :	12,727.00
Total Parts :	6,294.60
Total Labour & Parts :	19,021.60
Deduction for Excess :	
Total Repair Costs less Excess:	19,021.60
GST @7%:	1,331.51
Grand Total :	20,353.11

NO	NO PARTS	DATE	INTERVAL DAYS
FAX TO FAX NO	Tanfikh LHC	27/9/19	8
FAX TO FAX NO			
FAX TO FAX NO			
CONFIRMED DATE			
FILE NO			

LOSS OF USE = \$60 X 10 DAYS
GIA SEARCH FEE - \$2.00



Supplementary

Estimate No. : **b1 51760**
Date Estimated : **01/07/2019**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
Performance Premium Selection Ltd
280 Kampong Arang Road
East Coast Centre

Singapore 438180

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK9145U	WBA6V12060ED058	29/04/2019	216i GT	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
-------------	----------------------------	---------	------

# To remove and install fuel tank to facilitate repair job including to conduct checks for leak.	451.00	0	451.00 ✓✓
# To check electrical wiring system at the rear section for proper function.	150.00	0	150.00 ✓✓
# To replace right trunk floor and tail end panel	1,700.00	0	1,700.00 ✓✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT WITH COLLAR M5	5.30	2	0	10.60 ✓✓
# TAIL PANEL	355.20	1	0	355.20 ✓✓
# RH TRUNK FLOOR	111.60	1	0	111.60 ✓✓
# RR BUMPER RH INNER SIDE GUIDE	67.55	1	0	67.55 ✓✓
# (S/L) SEAM SEAL 300ML	33.80	2	0	67.60 ✓✓

SUPPLEMENTARY ITEMS

Total Labour :	2,301.00
Total Parts :	612.55
Total Labour & Parts :	2,913.55



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG19011620/kb3

11 JULY 2019

TAN KHENG NGEE KELVIN
BLK 446
BRIGHTHILL DRIVE
#09-107
SINGAPORE 570446

Dear Sir/Madam,

**ACCIDENT INVOLVING SLM5938B & SMK9145U ALONG SIN MING ROAD ON
30/06/2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SMK9145U against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

KHANCHNA
Case Handler
DID: 6841-2360
FAX: 6741 4108
Email: khanchna@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	01 Jul 2019 16:47	Clim Dtl Modified	Claimant's Name: -> PERFORMANCE PREMIUM SELECTION . Claimant's ID: -> 200 408061K.	[A] Lau Shu Pei
2	01 Jul 2019 16:47	Clim Veh Model Changed	(204297) BMW 216D 1.5 D Active Tourer (F45) (A).	[A] Lau Shu Pei
3	01 Jul 2019 16:47	Clim Created	Reg No: SMK9145U, Acct Date: 2019/06/30, Claim Type: TP, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), TP Insurer: MSIG Insurance (Singapore) Pte. Ltd. (H Q), Workshop: Performance Motors Limited (Alexandra)	[A] Lau Shu Pei
4	01 Jul 2019 16:47	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
5	01 Jul 2019 16:47	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/07/10	[A] Lau Shu Pei
6	01 Jul 2019 16:47	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.	[A] Lau Shu Pei
7	01 Jul 2019 16:47	Clim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
8	01 Jul 2019 16:47	Label Added	(23):Express.	[A] Lau Shu Pei
9	01 Jul 2019 16:47	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] Lau Shu Pei
10	29 Nov 2019 11:42	Adj Rpt Initiated		[A] HUEY YON
11	29 Nov 2019 11:42	Clim Dtl Modified	JPJ Reg. Date: -> 2019/04/29.	[A] HUEY YON
12	29 Nov 2019 11:42	Clim Details Notified		[A] HUEY YON
13	13 Dec 2019 12:04	Adj Mandate Request	Cur.Req:20955.11:** 8 days recommendation for repair + 1 Public Holiday + 1 Sunday = 10 days	[A] Khanchna Pothuraj
14	13 Dec 2019 12:04	Adj Mandate Request Cancelled		[A] Khanchna Pothuraj
15	13 Dec 2019 12:06	Adj Mandate Request	Cur.Req:20955.11:BOLA 27- head to rear collision. Liability down against Insured, * 8 days recommendation for repair + 1 Public Holiday + 1 Sunday = 10 days	[A] Khanchna Pothuraj

Date From



Date To



Audit Type

None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

DRB Ref No	DRB Date	DRB Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2197118	02 Jul 2019 08:56:13	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	AIG Asia Pacific Insurance Pte. Ltd. (Express)	SMK9145U	SLM59388	11.77
2361277	29 Nov 2019 11:42:30	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMK9145U	SLM59388	11.77

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Tuesday, 17 December 2019 6:26 PM
To: Foo, Chityan
Cc: Admin A
Subject: Mandate Request - TP / 3837747881SG [ACCIDENT INVOLVING SLM5938B (OI) & SMK9145U ON 30/06/2019]

AIG Ref: TP / 3837747881SG
LKK Ref: CC3/AIG19011620/T1kb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLM 5938B (OI) AND SMK 9145U (TP) ON 30/06/2019

We refer to the above matter.

It is a head to rear collision. We are of the opinion that BOLA 27 is applicable. We did clarify with insured the nature of the accident and he is aware of NCD (if any) will be affected.

We seek your approval to offer to Third Party repairer, "**Performance Motors Limited**" as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 29,209.02	\$ 20,353.11
2. Loss of Use (10 days x \$60.00)	\$ 600.00	\$ 600 (10 days x \$60.00)
3. LTA/ GIA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 29,811.02	\$ 20,955.11

**8 days recommendation for repair + 1 Public Holiday + 1 Sunday = 10 days

All the relevant documents had been uploaded in Merimen.

Kindly let us have your mandate in Merimen.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,
Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Thursday, 9 January 2020 10:48 AM
To: PBSP
Cc: Admin A
Subject: RE: VERY PAYMENT REMINDER - SMK9145U & SLM5938B ON 30/06/2019

Without Prejudice

Dear Caroline,

We refer to the above matter and your e-mail below.

We confirm settlement as per your LOD on this matter.

We will expedite the necessary accordingly.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Wishing you a Happy and Prosperous Lunar New Year



Best Regards,

Khanchna Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>

Sent: Thursday, 9 January 2020 10:29 AM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>

Subject: Re: VERY PAYMENT REMINDER - SMK9145U & SLM5938B ON 30/06/2019

Dear All

I have sent you numerous reminders and there is still no reply???

Please advise if you have submitted the package to AIG for payment???

Thank you.

Regards,
Caroline

C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: PBSP <pml-pbsp@simedarby.com.sg>

Sent: Friday, 27 December 2019 8:13 AM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Mei Kwan (LKK Auto) <Meikwan@lkkauto.com>

Subject: Re: VERY PAYMENT REMINDER - SMK9145U & SLM5938B ON 30/06/2019

VERY URGENT REMINDER

From: PBSP <pml-pbsp@simedarby.com.sg>

Sent: Monday, 16 December 2019 3:25 PM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Mei Kwan (LKK Auto) <Meikwan@lkkauto.com>

Subject: VERY PAYMENT REMINDER - SMK9145U & SLM5938B ON 30/06/2019

Dear Khanchna

Have your submitted to AIG for payment yet???

Our invoice has been **outstanding for more than 63 days.**

Thank you.

Regards,
Caroline

C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: PBSP <pml-pbsp@simedarby.com.sg>

Sent: Tuesday, 19 November 2019 4:54 PM

To: CS A Team <cs-a@lkkauto.com>; 甯珺 © <admin-a@lkkauto.com>

Cc: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Subject: Fw: PAYMENT REMINDER - SMK9145U & SLM5938B ON 30/06/2019

From: PBSP

Sent: Tuesday, 5 November 2019 2:52 PM

To: CS A Team <cs-a@lkkauto.com>; 甯瑤 © <admin-a@lkkauto.com>

Cc: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Subject: PAYMENT REMINDER - SMK9145U & SLM5938B ON 30/06/2019

PAYMENT REMINDER

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, Performance Motor Pte Ltd (the third party claimant) of 303 Alexandra Road (159941) (address), owner of SMK 9145U (vehicle no.) hereby authorize Performance Motors Ltd ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SMK 9145U that was damaged pursuant to the accident which occurred on 30/6/2019 (date) along Sin Ming Road (location) involving vehicle no/s SLM 5935B ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 16 (day) of 68 (month) 2019 (year)

✕

Signed by "the third party claimant"
(with chop if applicable)

CHUA KEE SIN
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941



Signed by "the workshop"
(with chop)

Print Received Message

This mail is associated with :

***SMK9145U (3837747881SG)**

[SLM5938B]

TP

PERFORMANCE PREMIUM SELECTION LTD

Jun 30 2019 2:00PM

[TAN KHENG NGEE KELVIN]

Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 02/01/2020 16:01 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$20955.11) - SMK9145U - Claim Handler: Foo, Chit Yan

Approved:20955.11:Above mandate subject to Final Repair Bill, GIA Search Bill in order

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Jul 2019 Edit Reg		06 Aug 2019 00:00 Edit Adj Rpt	S\$19,021.60 Edit Estimates	S\$19,021.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by adjuster\]](#)

Insured:	TAN KHENG NGEE KELVIN, ID: S1687183D		
Main Claimant:	PERFORMANCE MOTORS LTD, Co. Reg. No.: 200408061K		
Vehicle Reg. No.:	SMK9145U	Date of Loss:	30/06/2019 14:00 - :59 [2 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 38377478815G	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SLM5938B	Policy No. (Claimant):	
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 10/07/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (02/01/2020): Alert - Adj Mandate Approved (S\$20955.11) - SMK9145U - Claim Handler: Foo, Chit ...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMK9145U (3837747881SG)
[SLM5938B]
TP
PERFORMANCE MOTORS LTD
Jun 30 2019 2:00PM
[TAN KHENG NGEE KELVIN]
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown													1	Edit				
Photos/Images															3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	13/12/19 11:54	General View													1	Load JPG	☒			
2	13/12/19 11:54	General View													1	Load JPG	☒			
3	13/12/19 11:54	General View													1	Load JPG	☒			
4	13/12/19 11:54	General View													1	Load JPG	☒			
5	13/12/19 11:54	General View													1	Load JPG	☒			
6	13/12/19 11:54	General View													1	Load JPG	☒			
7	13/12/19 11:54	General View													1	Load JPG	☒			
8	13/12/19 11:54	General View													1	Load JPG	☒			
9	13/12/19 11:54	General View													1	Load JPG	☒			
10	13/12/19 11:54	General View													1	Load JPG	☒			
11	13/12/19 11:54	General View													1	Load JPG	☒			
12	13/12/19 11:54	General View													1	Load JPG	☒			
13	13/12/19 11:54	General View													1	Load JPG	☒			
14	13/12/19 11:54	General View													1	Load JPG	☒			
15	13/12/19 11:54	General View													1	Load JPG	☒			
16	13/12/19 11:54	General View													1	Load JPG	☒			
17	13/12/19 11:54	General View													1	Load JPG	☒			
18	13/12/19 11:54	General View													1	Load JPG	☒			
19	13/12/19 11:54	General View													1	Load JPG	☒			
20	13/12/19 11:54	General View													1	Load JPG	☒			
21	13/12/19 11:54	General View													1	Load JPG	☒			
22	13/12/19 11:54	General View													1	Load JPG	☒			
23	13/12/19 11:54	General View													1	Load JPG	☒			
24	13/12/19 11:54	General View													1	Load JPG	☒			
25	13/12/19 11:54	General View													1	Load JPG	☒			
26	13/12/19 11:54	General View													1	Load JPG	☒			
27	13/12/19 11:54	General View													1	Load JPG	☒			
28	13/12/19 11:54	General View													1	Load JPG	☒			
29	13/12/19 11:54	General View													1	Load JPG	☒			
30	13/12/19 11:55	Reinspection Photo													1	Load JPG	☒			
31	13/12/19 11:55	Reinspection Photo													1	Load JPG	☒			
32	13/12/19 11:55	Reinspection Photo													1	Load JPG	☒			
33	13/12/19 11:55	Reinspection Photo													1	Load JPG	☒			
34	13/12/19 11:55	Reinspection Photo													1	Load JPG	☒			
35	13/12/19 11:55	Reinspection Photo													1	Load JPG	☒			
36	13/12/19 11:55	Reinspection Photo													1	Load JPG	☒			
37	13/12/19 11:55	Reinspection Photo													1	Load JPG	☒			
38	13/12/19 11:55	Reinspection Photo													1	Load JPG	☒			
39	13/12/19 11:55	Reinspection Photo													1	Load JPG	☒			
40	13/12/19 11:55	Reinspection Photo													1	Load JPG	☒			

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	13/12/19 11:55	Reinspection Photo	 Load JPG	☒
42	13/12/19 11:55	Reinspection Photo	 Load JPG	☒
43	13/12/19 11:55	Reinspection Photo	 Load JPG	☒
44	13/12/19 11:55	Reinspection Photo	 Load JPG	☒
45	13/12/19 11:55	Reinspection Photo	 Load JPG	☒
46	13/12/19 11:55	Reinspection Photo	 Load JPG	☒
47	13/12/19 11:55	Reinspection Photo	 Load JPG	☒
48	13/12/19 11:55	Reinspection Photo	 Load JPG	☒
49	13/12/19 11:55	Reinspection Photo	 Load JPG	☒
50	13/12/19 11:55	Reinspection Photo	 Load JPG	☒
51	13/12/19 11:55	Reinspection Photo	 Load JPG	☒
52	13/12/19 11:55	Reinspection Photo	 Load JPG	☒
53	13/12/19 11:55	Reinspection Photo	 Load JPG	☒
54	13/12/19 11:55	Reinspection Photo	 Load JPG	☒
55	13/12/19 11:55	Reinspection Photo	 Load JPG	☒
56	13/12/19 11:55	Reinspection Photo	 Load JPG	☒
57	13/12/19 11:55	Reinspection Photo	 Load JPG	☒
58	13/12/19 11:55	Reinspection Photo	 Load JPG	☒
59	13/12/19 11:55	Reinspection Photo	 Load JPG	☒
60	13/12/19 11:56	Reinspection Photo	 Load JPG	☒
61	13/12/19 11:56	Reinspection Photo	 Load JPG	☒
62	13/12/19 11:56	Reinspection Photo	 Load JPG	☒
63	13/12/19 11:56	Reinspection Photo	 Load JPG	☒
64	13/12/19 11:56	Reinspection Photo	 Load JPG	☒
65	13/12/19 11:56	Reinspection Photo	 Load JPG	☒
66	13/12/19 11:56	Reinspection Photo	 Load JPG	☒
67	13/12/19 11:56	Reinspection Photo	 Load JPG	☒
68	13/12/19 11:56	Reinspection Photo	 Load JPG	☒
69	13/12/19 11:56	Reinspection Photo	 Load JPG	☒
70	13/12/19 11:56	Reinspection Photo	 Load JPG	☒
71	13/12/19 11:56	Reinspection Photo	 Load JPG	☒
72	13/12/19 11:56	Reinspection Photo	 Load JPG	☒
73	13/12/19 11:56	Reinspection Photo	 Load JPG	☒
74	13/12/19 11:56	Reinspection Photo	 Load JPG	☒
75	13/12/19 11:56	Reinspection Photo	 Load JPG	☒
76	13/12/19 11:56	Reinspection Photo	 Load JPG	☒
77	13/12/19 11:56	Reinspection Photo	 Load JPG	☒
78	13/12/19 11:56	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/07/19 16:48	TP GIA REPORT	 Load PDF	
2	11/07/19 09:36	LETTER TO OI	 Load PDF	
3	13/08/19 19:26	TP ESTIMATE- MARKED.	 Load PDF	
4	13/12/19 11:02	GIA SEARCH	 Load PDF	
5	13/12/19 11:59	ATA, final repair bill, LTA Search	 Load PDF	
6	10/01/20 15:59	TP COVER NOTE	 Load PDF	
7	10/01/20 18:40	TP GIA REPORT- ADDENDUM	 Load PDF	
8	13/01/20 10:16	WORKSHOP INVOICE	 Load PDF	
9	13/01/20 10:16	AUTHORISATION TO ACT FORM	 Load PDF	
10	13/01/20 10:16	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	02/07/19 08:53	OI GIA REPORT	 Load PDF	
2	27/12/19 10:06	Clear Report	 Load XLSX	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLM5938B (Insd veh)	Model:	BMW 216D 1.5 D ACTIVE
	SMK9145U (TP veh)		TOURER (F45) (A)
Date of Accident:	30/06/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	29,209.02
Final Repair Cost	:	\$	20,353.11
Loss of Use	:	\$	600.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	20,955.11

10.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/~~No~~ BOLA Scenario No: 27

BOLA Liability: 100 (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 20,955.11
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

13 Jan
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19011620/T1KA3Q2

Date: 13/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SMK9145U

Insured Vehicle No : SLM5938B

Date of Loss: 30/06/2019

Nature of Claim: TP

Claim No: 3837747881SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMK9145U

Make & Model: BMW 216D, 1.5 D Active Tourer (F45) (A)

Engine No: 33845616B38A15A

Reg. Date: 29/04/2019 (Man. Year: 2019)

Chassis No: WBA6V12060ED05858

Colour: Silver

Odometer: 5807 km

Engine Capacity: 1499 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R17

Rear Tyre Size: 205/55R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,091.15	6,444.60	3,646.55	36.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,207.00	12,577.00	4,630.00	26.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	27,298.15	19,021.60	8,276.55	30.32
+ GST 7.00/7.00% (S\$)	1,910.87	1,331.51	579.36	30.32
Nett Amount (S\$)	29,209.02	20,353.11	8,855.91	30.32
+ Loss of Use (10.0 x S\$60.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		20,955.11		

INSPECTION

Date of Assignment: 06/08/2019

Date Inspected: 06/08/2019 Inspected At:

 Performance Motors Limited
 (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941

Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	6		*PLASTIC NUT FOR COARSE THREADED PIN	Not Necessary	4.80 FS	*- FS
2	1		*BOOTLID	Bent	1,204.35 FS	*1,204.35 FS
3	1		*REAR RH SIDE PANEL	Bent	1,466.65 FS	*1,466.65 FS
4	1		*POSITIONIERU	Not Necessary	5.65 FS	*- FS
5	1		*REINFORCEMENT PLATE UNIVERSAL	Not Necessary	52.20 FS	*- FS
6	1		*REINFORCEMEN	Not Necessary	52.40 FS	*- FS
7	1		*REINFORCEMEN	Not Necessary	52.40 FS	*- FS
8	1		*REINFORCEMEN	Not Necessary	52.40 FS	*- FS
9	10		*T WELD BOLT L=5.4MM	Not Necessary	8.50 FS	*- FS
10	1		*RR BUMPER RH SIDE GUIDE	Deformed	61.50 FS	*61.50 FS
11	1		*REAR BUMPER CARRIER	Bent	458.10 FS	*458.10 FS
12	1		*SUPPORT	Not Necessary	45.30 FS	*- FS
13	1		*LEFT PROTECT	Not Necessary	11.20 FS	*- FS
14	1		*RIGHT PROTEC	Not Necessary	11.20 FS	*- FS
15	1		*REAR BUMPER TOWING FLAP EYE PRIMED	Not Necessary	42.85 FS	*- FS
16	1		*REAR BUMPER TRIM STRIP (BLACK)	Cut	70.75 FS	*70.75 FS
17	1		*REAR BUMPER PANEL PRIMED (LINES PDC)	Deformed	1,045.45 FS	*1,045.45 FS
18	1		*SET MOUNTS PDC SENSOR REAR	Not Necessary	60.35 FS	*- FS
19	1		*LETTERING 216 I	Necessary	64.10 FS	*64.10 FS
20	2		*GROMMET	Necessary	1.50 FS	*1.50 FS
21	1		*PLAQUE 74MM	Necessary	71.25 FS	*71.25 FS
22	4		*PLASTIC NUT	Not Necessary	3.40 FS	*- FS
23	10		*BUMP STOP	Necessary	35.00 FS	*35.00 FS
24	1		*REAR WINDOW	Not Necessary	654.35 FS	*- FS
25	4		*HOOK AND LOOP FASTENER	Not Necessary	11.40 FS	*- FS
26	1		*REAR RH SIDE WINDOW FIXED (ALU HOCH)	Not Necessary	277.00 FS	*- FS
27	1		*RR RH WHEEL HOUSING COVER	Not Necessary	135.05 FS	*- FS
28	1		*BOOTLID SEALING	Not Necessary	143.00 FS	*- FS
29	1		*REAR RH REFLECTOR	Cracked	37.90 FS	*37.90 FS
30	1		*REAR LIGHTING	Not Necessary	27.50 FS	*- FS
31	1		*REAR RH LIGHT IN TRUNK LID	Not Necessary	255.65 FS	*- FS
32	1		*RH GUTTER STRIP	Not Necessary	51.95 FS	*- FS
33	4		*DECOUPING RING PDC TORQUE CONVERTER	Necessary	20.20 FS	*20.20 FS
34	4		*ULTRASONIC SENSOR GLACIERSILBER(WA8)	Not Necessary	1,475.20 FS	*- FS
35	1		*CAVITY PROTECTION WAX REMOVER 500ML	Not Necessary	18.45 FS	*- FS
36	1		*BLIND RIVET AVIBVLB	Necessary	22.00 FS	*22.00 FS
			40pcs			
37	5		*SCREW (SF PLUS M5X15)	Necessary	2.75 FS	*2.75 FS
38	2		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	653.60 FS	*653.60 FS
39	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Necessary	112.70 FS	*112.70 FS
40	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
41	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
42	1		*(DG) CLEANER R1 (100ML)	Not Necessary	26.15 FS	*- FS
43	2		*(DG/SL) WINDSCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
44	1		*(DG/SL) WINDSCREEN SEALANT (COLD 1 HOUR)	Not Necessary	131.55 FS	*- FS
45	1		*PUNCH RIVET N4	Necessary 20pcs	19.80 FS	*11.00 FS
			36pcs	Only		
46	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
47	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Not Necessary	27.85 FS	*- FS
48	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
49	2		*BLIND RIVET NUT WITH COLLAR M5	Necessary	10.60 FS	*10.60 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*TAIL PANEL	Bent	355.20 FS	*355.20 FS
51	1		*RH TRUNK FLOOR	Bent	111.60 FS	*111.60 FS
52	1		*RR BUMPER RH INNER SIDE GUIDE	Deformed	67.55 FS	*67.55 FS
53	2		*(S/L) SEAM SEAL 300ML	Necessary	67.60 FS	*67.60 FS
					Total Parts (S\$)	10,091.15 6,444.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE RIGHT REAR SIDE FENDER REAR BOOT LID, REAR BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT.	New	7,650.00	5,100.00
2	SPRAY PAINTING RIGHT SIDE REAR FENDER, REAR BUMPER, REAR BOOT LID, FLOOR PAN AND TAIL PAN.	New	4,082.00	3,195.00
3	TO REPLACE REAR WINDSCREEN GLASS.	New	574.00	574.00
4	TO CONDUCT WATER LEAK TESTS.	New	75.00	75.00
5	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM.	New	531.00	0.00
6	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS.	New	271.00	230.00
7	TO SUPPLY AND INSTALL REAR RIGHT GLASS SOLAR FILM.	New	425.00	0.00
8	TO CARRY OUT BODY CAVITY PRESERVATION. (FRONT CUT PANEL)	New	531.00	451.00
9	TO CARRY OUT BODY CAVITY PRESERVATION. (2 PANEL)	New	236.00	200.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS.	New	531.00	451.00
11	TO REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIR JOB INCLUDING TO CONDUCT CHECKS FOR LEAK.	New	451.00	451.00
12	TO CHECK ELECTRICAL WIRING SYSTEM AT THE REAR SECTION FOR PROPER FUNCTION.	New	150.00	150.00
13	TO REPLACE RIGHT TRUNK FLOOR AND TAIL END PANEL.	New	1,700.00	1,700.00
Gross Labour Cost (S\$)			17,207.00	12,577.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >