

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: AIG ASIA PACIFIC INSURANCE PTE LTD

Address: 78, SHENTON WAY, #07-16
S(079120)

Vic

Telephone: 64193000

Fax: 68357416

Email shengyang.lim@aig.comnoormarriesa.abukassim@aig.com

Make/ Model : BMW 523I

Date: 25.06.2019

Chassis No : WBAFP32090C546313

Vehicle No: SMK2002U

Date/Time of Accide 24.06.2019/1540

Date of Reg: 25.10.2010

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	FRONT BUMPER <i>torn</i>	1	\$ 1,280.30		\$ 1,280.30
2	FRONT HEADLAMP LH <i>New</i>	1	\$ 1,280.70		\$ 1,280.70
3	FRONT FENDER LH <i>Repair</i>	1	\$ 850.10		\$ 850.10
4	FRONT FENDER INNER COWLING LH <i>New</i>	1	\$ 244.20		\$ 244.20
5	FRONT FENDER CHROME MOLDING LH <i>New</i>	1	\$ 150.30		\$ 150.30
6	FRONT SIDE MIRROR ASSY LH <i>New</i>	1	\$ 756.10		\$ 756.10
7	FRONT LH RIM <i>Cracked</i>	1	\$ 1,123.40		\$ 1,123.40
8	FRONT ABSORBER LH <i>Bent</i>	1	\$ 645.20		\$ 645.20
9	FRONT ABSORBER MOUNTING LH <i>New</i>	1	\$ 125.30		\$ 125.30
10	FRONT UPPER ARM LH <i>? Bent</i>	1	\$ 556.30		\$ 556.30
11	FRONT LOWER ARM LH <i>Bent</i>	1	\$ 580.20		\$ 580.20
12	FRONT CONTROL ARM LH <i>Bent</i>	1	\$ 502.80		\$ 502.80
13	FRONT CLUSTER ARM LH <i>Bent</i>	1	\$ 568.20		\$ 568.20
14	FRONT KNUCKLE ARM LH <i>Bent</i>	1	\$ 650.10		\$ 650.10
15	FRONT WHEEL HUB BEARING LH <i>Damaged</i>	1	\$ 548.60		\$ 548.60
16	FRONT STEERING RACK <i>New</i>	1	\$ 785.90		\$ 785.90
17	FRONT ANTI ROLL BAR <i>New</i>	1	\$ 698.50		\$ 698.50
18	FRONT ANTI ROLL BAR LINKAGE LH <i>New</i>	1	\$ 185.70		\$ 185.70
19	FRONT TIE ROD LH <i>Bent</i>	1	\$ 245.60		\$ 245.60
20	FRONT TIE ROD END LH <i>Bent</i>	1	\$ 98.50		\$ 98.50
21	FRONT LH DOOR <i>New</i>	1	\$ 968.30		\$ 968.30
Total List Price Cost					\$ 12,844.30

PARTS DISCOUNT 10% \$ 11,559.87

6949.50

6254.55

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	FRONT BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
2	FRONT FENDER INNER COWLING CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
3	FRONT SPORT RIM TYRE LH <i>lt</i>	1	\$ 380.00	\$ 380.00 <i>280</i>
Total Special Nett Items				\$ 440.00

310 .

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE,BEAT ,WELD , REALIGN AND ALIGNE ALL PARTS	\$ 2,000.00
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,800.00
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 200.00
TO REMOVE/ REFIT WIRING CHECKS	\$ 150.00
TO REMOVE/ REFIT /REPLACE FRONT UNDERCARRIAGE	\$ 350.00
TO REMOVE/ REFIT FRONT SENSORS AND DISTANCE SETTLING	\$ 150.00
TO DIANOSSED, CHECK AND REMOVE FAULT CODE	\$ 150.00
TO PERFORM COMPUTERISED ALIGNMENT	\$ 180.00
Total Others Cost	\$ 1,180.00
GRAND TOTAL	
	\$ 16,979.87

CAS GARAGE PTE LTD

UEN 201828067M

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan

Direct Contact: +65 8782 7171

Email: allangoh.cas@gmail.com

Fax : 6509 9501

TEL: 64842220

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
L/S

26/06/19

05 Days.

total: 7864.55

L/S: 6250