

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Hwang Shiang Yi

Date: 04 Jul 2019

**Preliminary Advice**

Vehicle No	: SLH5108G	Accident Date	: 29/06/2019
Make	: NISSAN QASHQAI	Policy No.	: D18MTPV01017572
Assignment Date	: 02/07/2019	Excess	: S\$0.00
Date of Inspection	: 3/7/2019	Est. Duration of Repair	: 3
Inspection At	: AUTOLUTION INDUSTRIAL PTE LTD		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,988.14
Revised Amount	:S\$	995.14
Check Items (Estimated)	:S\$	529.00
Total	:S\$	1,524.14
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	75,000.00
COE / PARF Rebate	:S\$	47,714.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,286.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :