

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0819/2019/DY
Date : 3-Jul-19

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : SJK 2742 Z

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Tan Sok Kwang
Address : 2 Fifth Avenue
#03-14
Singapore 268800
Telephone : (HP) +65 98266103
Type of Claim : Third Party Claims
Policy No. : 1800110346
Vehicle No : **SME 1942 U**
Model Code : A4 Sedan 2.0 TFSI 8W
Model / Year : 21/9/2018
Engine No : CVK0 068360
Chassis No : WAUZZZF41JA232188
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-Jun-19
Place of Accident : Along Upper Thomson Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SME 1942 U

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 1,400.00 750	
3	To respray front bumper and bonnet.	\$ 1,800.00 1100	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 3,872.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 1924 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Regrit</i>	\$ 1,999.00	X
2	FRONT BUMPER FIXING PART <i>new</i>	\$ 258.00	+
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 191.00	+
4	FRONT BUMPER AIR GUIDE - RH <i>new</i>	\$ 56.00	+
5	FRONT BUMPER GRILLE - CENTER	\$ 178.00	+
6	FRONT RADIATOR GRILLE <i>Cracked</i>	\$ 1,227.00	✓
7	FRONT RADIATOR AIR GUIDE GRILLE - RIGHT <i>new</i>	\$ 123.00	+
8	FRONT BUMPER CARRIER <i>new</i>	\$ 733.00	X
9	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	\$ 113.00	X
10	FRONT BUMPER TOP COVER <i>new</i>	\$ 116.00	+
11	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	\$ 34.00	+
12	CAUTION STICKER <i>new</i>	\$ 13.00	+
13	AC STICKER	\$ 7.00	X
14	FRONT BUMPER LOCK CARRIER BRACKET <i>new</i>	\$ 125.00	+
15	FRONT BUMPER SIDE SUPPORT BRACKET - LH / RH <i>new</i>	\$ 51.00	+
16	FRONT HEADLIGHT - RH <i>Cracked</i>	\$ 7,087.00	✓
17	FRONT HEADLIGHT LIFT CYLINDER - RH <i>new</i>	\$ 192.00	+
18	FRONT BUMPER SENSOR <i>new</i>	2 \$ 462.00	+
19	SEAL RING <i>new new</i>	4 \$ 12.00	+
20	AIR DUCT COVER FOR RADIATOR - RH <i>new new</i>	\$ 25.00	+
SUB-TOTAL SPARE PARTS		\$ 13,002.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 1942 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT STEERING WHEEL AIR DUCT COVER - RH <i>OK</i>	\$ 11.00	<i>+</i>
22	RADIATOR AIR GUIDE - UPPER <i>OK</i>	\$ 15.00	<i>+</i>
23	RADIATOR AIR GUIDE - LOWER <i>OK</i>	\$ 19.00	<i>+</i>
24	FRONT NO. PLATE <i>OK</i>	S/N \$ 40.00	<i>✓</i>
25	SUNDRIES <i>?</i>	\$ 400.00	<i>?</i>
TOTAL SPARE PARTS		\$ 13,487.00	
TOTAL LABOUR CHARGES		\$ 3,872.00	
GRAND TOTAL		\$ 17,359.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 04/07/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : ~~Authorise~~ ^{we} Authorised, 04 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant