

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : **b1 51732**  
Date Estimated : **28/06/2019**  
Prepared By : **Joseph Yaguel**

Page No. :

**REPAIR FOR -**  
**Choo Way Jiang**  
**70 Shrewsbury Road**

**- ACCOUNT - 121**  
**AIG Asia Pacific Insurance Pte. Ltd.**  
**78 Shenton Way**  
**#08-16 Chartis Building**  
**Singapore 079120**

**Singapore 307836**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SGA2662M</b>	<b>D967694</b>	<b>22/05/2015</b>	<b>420IA GC</b>	<b>0</b>
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments include knocking out dents caused by the accident	850.00		850.00	
To spray paint front bumper	934.00		934.00	
To check electrical wiring systems at the front section for proper function	150.00		150.00	
To supply front emboss number plate	83.00		83.00	
Sundries	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
INSERT AIR INLET MIDDLE	114.85	1.00		114.85
LICENCE PLATE BASE ECE	69.25	1.00		69.25
FRT BUMPER PANEL PRIMED (SRA)	1,078.65	1.00		1,078.65
# SET MOUNTING PDC/PMA SENSOR FRT *	75.30	1.00		75.30
FRT LH GRILLE (LUXURY)	128.60	1.00		128.60
FRT RH GRILLE (LUXURY)	128.60	1.00		128.60
# PLAQUE 82MM *	71.25	1.00		71.25
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05

# SUPPLEMENTARY ITEMS

Total Labour :	2,097.00
Total Parts :	1,719.55
Total Labour & Parts :	3,816.55
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,816.55
GST @7%:	267.16
Grand Total :	4,083.71