

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 51732  
Date Estimated : 28/06/2019  
Prepared By : Joseph Yaguel

Page No. :

REPAIR FOR -  
Choo Way Jiang  
70 Shrewsbury Road

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

Singapore 307836

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGA2662M	D967694	22/05/2015	420IA GC	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# SET MOUNTING PDC/PMA SENSOR FRT * <i>ne</i>	75.30	1.00		75.30
# PLAQUE 82MM * <i>ne</i>	71.25	1.00		71.25
# (DG/SL) ADHESIVE SET K6 * <i>ne</i>	53.05	1.00		53.05

Total Labour :	0.00
Total Parts :	199.60
Total Labour & Parts :	199.60

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 51732  
Date Estimated : 28/06/2019  
Prepared By : Joseph Yaguel

Page No. :

REPAIR FOR -  
Choo Way Jiang  
70 Shrewsbury Road

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

Singapore 307836

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGA2662M	D967694	22/05/2015	420IA GC	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments include knocking out dents caused by the accident	850.00		850.00	✓
To spray paint front bumper	934.00		934.00	✓
To check electrical wiring systems at the front section for proper function	150.00		150.00	✓
To supply front emboss number plate	83.00		83.00	✓
Sundries	80.00		80.00	✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
INSERT AIR INLET MIDDLE	114.85	1.00		114.85 ✓
LICENCE PLATE BASE ECE	69.25	1.00		69.25 ✓
FRT BUMPER PANEL PRIMED (SRA)	1,078.65	1.00		1,078.65 ✓
# SET MOUNTING PDC/PMA SENSOR FRT *	75.30	1.00		75.30 ✓
FRT LH GRILLE (LUXURY)	128.60	1.00		128.60 ✓
FRT RH GRILLE (LUXURY)	128.60	1.00		128.60 ✓
# PLAQUE 82MM *	71.25	1.00		71.25 ✓
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05 ✓

# SUPPLEMENTARY ITEMS

Total Labour :	2,097.00
Total Parts :	1,719.55
Total Labour & Parts :	3,816.55
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,816.55
GST @7%:	267.16
Grand Total :	4,083.71

## Vic (LKKAuto)

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Thursday, 25 July, 2019 6:29 PM  
**To:** Rasul (LKKAuto); Vic (LKKAuto)  
**Subject:** FINAL REPORT/ SGA2662M  
**Attachments:** Final Report SGA2662M\_2.pdf; Final Report SGA2662M.pdf

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,097.00

Total Parts : 1,719.55

Total Labour & Parts : 3,816.55

Repair days: 3

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

“This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's.”