



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE



CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
LONPAC INSURANCE BHD 100 BEACH ROAD #19-00 SHAW TOWER SINGAPORE 189702 TEL:62962706 Contact No	Cust No/Name	/Lion City Rentals Pte.Ltd
	Reg No/Reg Date	SLG9170D / 18/10/2016
	Date In/Mileage	/ 0
	Chassis No	KNAFX411MH5665391
	Engine No	G4FGGH657349
	Make/Model	KIA/FORTE K3 1.6 A EX BRQ
	Colour/Trim	SWP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000040	Credit	01/07/2019/ 13:15	Bod	303 / Renemer	27477			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S	MIPNT88088	DIAGNOSTIC/SCANNING						250.00
S	MIPNT88088	TO CHECK LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS						80 100.00
S	MIPNT88088	TO TRANSFER REAR BOOT COMPONENTS/MECHANISM						300 600.00
S	MIPNT88088	TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS						300 600.00
S	MIPNT88088	TO APPLY SEALANT KIT ON NEW & REPAIR PANELS						100 200.00
S	MIPNT88088	TO REPLACE REAR BUMPER, REINFORCEMENT, END PANEL, REAR BOOT, ETC						1800 3600.00
S	MIPNT98088	STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS						1600 1680.00
S	MIPNT88088	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS						280.00
S	MIPNT88088	REVERSE SENSOR SET						50.00
M	SUNDRY	C & C LOGO						
M	KS 86611 A7 800	COVER-REAR BUMPER			1.00	688.00	0.00	688.00
M	KS 86695 A7 800	CTR COVER-REAR BUMPER			1.00	347.00	0.00	347.00
M	KS 86690 A7 000	COVER - REAR BUMPER			1.00	42.00	0.00	42.00
M	KS 0G032 50 037A	CLIP- BUMPER			10.00	2.00	0.00	20.00
M	KS 86613 A7 001	LH BRACKET-RR BPR SI			1.00	29.00	0.00	29.00
M	KS 86614 A7 001	RH BRACKET-RR BPR SI			1.00	29.00	0.00	29.00
M	KS 86631 A7 800	BEAM - REAR BUMPER			1.00	318.00	0.00	318.00
M	KS 86636 A7 000	BRACKET-RR BEAM LWR			2.00	5.00	0.00	10.00
M	KS 86635 A7 000	CTR BRACKET-RR BEAM			1.00	5.00	0.00	5.00
M	KS 86633 A7 800	LH BRACKET-RR BEAM U			1.00	3.00	0.00	3.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
LONPAC INSURANCE BHD 100 BEACH ROAD #19-00 SHAW TOWER SINGAPORE 189702 TEL:62962706 Contact No	Cust No/Name	/Lion City Rentals Pte.Ltd
	Reg No/Reg Date	SLG9170D / 18/10/2016
	Date In/Mileage	/ 0
	Chassis No	KNAFX411MH5665391
	Engine No	G4FGGH657349
	Make/Model	KIA/FORTE K3 1.6 A EX BRQ
	Colour/Trim	SWP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000040	Credit	01/07/2019/ 13:15	Bod	303 / Renemer	27477			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	KS 86634 A7 800	RH BRACKET-RR BEAM U	7		1.00	3.00	0.00	3.00
M	KS 86641 A7 800	LH STAY-REAR BUMPER	7		1.00	120.00	0.00	120.00
M	KS 86642 A7 800	RH STAY-REAR BUMPER	7		1.00	120.00	0.00	120.00
M	KS 69100 A7 600	PANEL ASSY - BACK	B-1630	chd.	1.00	274.00	0.00	274.00
M	KS 85770 A7 000W K	TRIM - TRANSVERSE RE	?		1.00	58.00	0.00	58.00
M	KS 69200 A7 070	PANEL ASSY - TRUNK L	Best/3uc		1.00	1491.00	0.00	1491.00
M	KS 86311 A7 030	EMBLEM - CERATO	Mr		1.00	35.00	0.00	35.00
M	KS 87321 A7 000	WEATHERSTRIP - TRUNK	Mr		1.00	100.00	0.00	100.00
M	KS 86310 A7 050	LOGO ASSY - KIA SUB	Mr		1.00	37.00	0.00	37.00

Z NOTES

ACCIDENT ON 29/06/2019 ALONG JALAN LOYANG BESAR
OWNER CLAIMING THIRD PARTY
REQUIRED REPLACEMENT CAR
TP#: GBH2980S TP INS: LONPAC

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

Parts	3,729.00
Labour	0.00
Standard Menu	0.00
Specialist Job	7,310.00
Others(Lub,etc)	0.00
Sundry	50.00
Total(w/o GST)	11,089.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.