

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

KIV

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info			
LONPAC INSURANCE BHD 100 BEACH ROAD #19-00 SHAW TOWER	Cust No/Name	/Lion City Rentals Pte.Ltd		
	Reg No/Reg Date	SLG91700 / 18/10/2016		
	Date In/Mileage			
SINGAPORE 189702	Chassis No	KNAFX411MH5665391		
TEL:62962706	Engine No	G4FGGH657349		
Contact No	Make/Mode1	KIA/FORTE K3 1.6 A EX BRQ		
	Colour/Trim	SWP / WK		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No			
F0000040	Credit	01/07/2019/ 13:15		303 / Renemer		27477			
1 00000	21,0011	Description of Goo			Qty	Unit Price	Disc%	Am	ount
S MIPHTBB	OBB				1 1	9 /			250.00
	TIC/SCANN	ING			Lhoft	1		0.	
S MIPNTES		117410		Not	1100	7		20	100.00
		G/WIRING SYSTEM ON	REAR ACCIDE	NT	2h	1.			
	D AREAS	MANAGEMENT THE PARTY NAMED IN			au	Sepenja		-	
S MIPNTES	088				1.1	, 0 .	1	300	600.00
		BOOT COMPONENTS/ME	CHANISM	11	. slota	serve/0	h	_	
S MIPNT88		The same of the sa		6000	700	. /	7.	300	600.00
TO REMO	VE & RE-1	NSTALL ALL CARPETS,	TRIMMING TO	GIVE	11		(
WAY ACC	ESS REPAI	R ON REAR ACCIDENT	AFFECTED AF	REAS	2000			100	200 00
S MIPHT88					TV 1			100	200.00
TO APPL	Y SEALAN	KIT ON NEW & REPA	IN PANELS	11 122 2	181-16	do .	0		3600.00
5 MIPHTEE				1111111	211-177	3 /	100		2000.00
		BUMPER REINFORCEMEN	NT END PANEL	Lab L	11214	7			
REAR BO					-				
	TEM, REFOR	M, ALIGN ON REAR AC	CIDENI AFFE	TED					
AREAS						1	500		1680.00
5 MIPNT98		w near assessment arr		/10.0		10	100		1000100
		ON REAR ACCIDENT AF	PECTED AREAS	420		-	us		280.00
5 MIPHTBE						2.0	wa		4
	SENSOR S	135					ec		50.00
M SUNDRY C & C L	nen:					-	Jee		
	1 A7 800	COVER-REA	D RUMPED	DIS	1.00	688.00	0.00		688.00
	5 A7 800		-REAR BUMPE	De	1.00	347.00	0.00		347.00
	0 A7 000		EAR BUMPER		1.00	42.00	0.00		42.00
	12 50 037			71	10.00	2.00	0.00		20.00
111	3 A7 001		T-RR BPR SI	11/	1.00	29.00	0.00		29.00
	4 A7 001		T-RR BPR SI	11	1.00	29.00	0.00		29.00
	11 A7 BOO	BEAM - RE		711	1.00	318.00	0.00		318.00
	6 A7 000		R BEAM LWR	Mi	2.00	5.00	0.00		10.00
	5 A7 000		ET-RR BEAM	37	1.00	5.00	0.00		5.00
M KS B663	3 A7 800	IN PRACES	T-RR BEAM U	211	1.00	3.00	0.00		3.00

Confirm & accepted by

·7927.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would edvise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before commencement.



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info			
	Cust No/Name	/Lion City Rentals Pte.Ltd		
LONPAC INSURANCE BHD 100 BEACH ROAD #19-00 SHAW TOWER	Reg No/Reg Date	SLG91700 / 18/10/2016		
	Date In/Mileage			
SINGAPORE 189702	Chassis No	KNAFX411MH5665391		
TEL:6296Z706	Engine No	G4FGGH657349		
Contact No	Make/Mode1	KIA/FORTE K3 1.6 A EX BRQ		
Contract III	Colour/Trim	SWP / WK		

Lecount No	Terms	Date/Time Printed	CSE	Operator		WIP No		
0000040	Credit	01/07/2019/ 13:15	Bod	303 / Renemer		27477		
0000040	Credit	Description of Good			Oty	Unit Price	Disc%	Amount
M KS 69200 M KS 86311 M KS 87321 M KS 86310 Z NOTES ACCIDENT OWNER CL	A7 800 A7 800 A7 600 A7 000W A7 070 A7 030 A7 000 A7 050 ON 29/0 AIMING T	RH BRACKET- LH STAY-REA RH STAY-REA PANEL ASSY K TRIM - TRAN PANEL ASSY EMBLEM - CE WEATHERSTRI LOGO ASSY -	RR BEAM U R BUMPER R BUMPER - BACK SVERSE RE - TRUNK L RATO P - TRUNK KIA SUB	8-1520 - 18-1520 - 18-1520 - 19-15-15-15-15-15-15-15-15-15-15-15-15-15-	1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	3.00 120.00 120.00 274.00 58.00 1491.00 35.00 100.00	0.00 0.00 0.00 0.00	3.00 120.00, 120.00, 274.00, 56.00, 1491.00, 35.00, 100.00, 37.00
						incomp		
	accepted	by			Parts Labour Standary	4 Menu		3,729.0 0.0 0.0
Confirm &					Special	ist Job Lub,etc)		7,310.0 0.0 50.0 11,089.0

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has communeed. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewin the rubber seal or other repair requiring the removal of the windscreen.

Page 2 of 2



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info			
LONPAC INSURANCE BHD	Cust No/Name	/Lion City Rentals Pte.Ltd		
100 BEACH ROAD #19-00	Reg No/Reg Date	SLG91700 / 18/10/2016		
SHAW TOWER	Date In/Mileage	18/07/2019/ 0		
SINGAPORE 189702	Chassis No	KNAFX411MH5665391		
TEL:62962706	Engine No	G4FGGH657349		
Contact No	Make/Model	KIA/FORTE K3 1.6 A EX BRQ		
	Colour/Trim	SWP / WK		

ccount No	Terms	Date/Time Printed	CSE	Operator	10000	WIP No	
0000040	Credit	24/07/2019/ 09:25	Bod	303 / Renemer		27477	
THE REAL	SATE	Description of Goods	/ Services		Qty U	Init Price Disc%	Amount
NOTES SUPPLEMEN		LATCH ASSY -	TRUNK L	to: (sluth	1.00	112.00 0.00	112.0
			sti	ima	te		
Confirm & ac	ccepted b	у		L	Parts Labour Standard Men	u	112. 0. 0.
		RY ITEMY		S	Specialist J Others(Lub,e Surdry	ob	0.0

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has communiced. Occasionally worm or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of SOV of the above estimate is payable before communications of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info			
LONPAC INSURANCE BHD 100 BEACH ROAD #19-00	Cust No/Name	/Lion City Rentals Pte.Ltd			
	Reg No/Reg Date	SLG91700 / 18/10/2016			
SHAW TOWER	Date In/Mileage	15/07/2019/ 66260			
SINGAPORE 189702	Chassis No	KNAFX411MH5665391			
TEL:62962706	Engine No	G4FGGH657349			
Contact No	Make/Model	KIA/FORTE K3 1.6 A EX BRQ			
	Colour/Trim	SWP / WK			

Account I	lo Terms	Date/Time Pr	inted	CSE	Ope	rator		77	WIP No	400	
F0000040	Credit	24/07/2019/	18:30	DS.	303	/ Re	nemer		27477		
et all lights	PRINTER	Description	of Goods I	Services		(18)	ALC: U	Qty	Unit Price	Disc%	Amount
S MIPHT											250.00
	OSTIC/SCAN	ING									20.20
S MIPNT	The second secon				-						80.0
		G/WIRING SYST	EM ON REA	R ACCIDEN	(1						
S MIPNT	TED AREAS										300.0
T. TORRESTOR	107 M 100 M 17	BOOT COMPONE	NTS /MECHA	NTCM							300.0
S MIPNT		DOO! CONFORE	H13/PECHA	11.301							300.0
		INSTALL ALL CA	RPETS/TRI	MMING TO	GIVE						200.0
		R ON REAR ACC									
S MIPHT	88088	Г		п				П			100.0
TO AP	PLY SEALANT	KIT ON NEW &	LREPAIR P	ANEES > [7 17	3	12	576	7		
S MIPNT	88088	SOUDMENT AND A VENT		211	116		6		1		1800.0
TO RE	PLACE REAR	BUMPER, REINEO	RCEMENT	ND/PANELL		ш		66	7		
REAR	BOOT, ETC	KIT ON NEW & BUMPER, REINFO									
AREAS	GHIEM, REPOR	M,ALIGN ON RE	AR ACCIDE	NT AFFECT	ED						
S MIPHT											1600.0
		N REAR ACCIDE	NT AFFECT	FD AREAS							100010
S MIPNT		nem neede		CO TINETIS							280.0
REVER	SE SENSOR S	SET									
M SUNDR	Υ										50.0
	LOG0										
7.	611 A7 800		R-REAR BU					1.00	688.00	0.00	688.0
77 775 500	695 A7 800	2.1.1.1.1	COVER-REA	R BUMPE				1.00	347.00	0.00	347.0
	032 50 037/ 613 A7 001		- BUMPER RACKET-RR	pon cr				1.00	2,00	0.00	29.0
11	614 A7 001		RACKET-RR					1.00	29.00	0.00	29.0
	100 A7 600	1000000	L ASSY -	- Table 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1				1.00	274.00	0.00	274.0
10 000 000	200 A7 070	1 1 1 1 1 1 1 1 1	L ASSY -	The second second				1.00	1491.00	0.00	1491.0
	311 A7 030	2000	EM - CERA	Account of the				1.00	35.00	0.00	35.0
X KS 87	321 A7 000	WEAT	HERSTRIP	- TRUNK				1.00	100.00	0.00	100.0
X KS 86	310 A7 050	1 000	ASSY - K	** ***				1.00	37.00	0.00	37.0

Confirm & accepted by

FINALIZATION

ATTN: MARCUS

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, as signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 1 of 2



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info			
LONPAC INSURANCE BHD	Cust No/Name	/Lion City Rentals Pte.Ltd		
100 BEACH ROAD #19-00	Reg No/Reg Date	SLG91700 / 18/10/2016		
SHAW TOWER	Date In/Mileage	15/07/2019/ 66260		
SINGAPORE 189702	Chassis No	KNAFX411MH5665391		
TEL:62962706	Engine No	G4FGGH657349		
Contact No	Hake/Mode1	KIA/FORTE K3 1.6 A EX BRQ		
	Colour/Trim	SWP / WK		

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	-
0000040	Credit	24/07/2019/ 18:30	DS	303 / Renemer	27477	
-100-11		Description of Good			,Qty Unit Price Disc%	Amount
OWNER CL LOSS OF	ON 29/00 AIMING TH	EATCH ASSY 6/2019 ALONG JALAN L HIRD PARTY TP INS: LONPAC		Par/Slan	4.00 112.00 0.00	112.00
			St	imat	le	
Confirm &	accepted 1	by			rts	3,162.
		y and company stamp		La St Sp Ot Si	bour andard Menu ecialist Job hers(Lub.etc) indry etal(w/o GST)	0. 0. 4,710. 0. 50. 7,922.

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Flease be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 2 of 2