

Alt. CLK

KH



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Repair Estimates

SLN 672 U

Parts	(a) Cost / List Price Items	\$ <u>5728.81</u>	11,156.77
	Plus/Less 25%	\$ <u>1432.20</u>	2,789.19
	Total of Cost / List	\$ <u>4296.61</u>	8,367.58
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	350.00
Total Parts Cost		\$	8,717.58
Labour		\$ <u>1320.00</u>	3,030.00
Total		\$ <u>5616.61</u> ✓ ok	11,747.58

Not Authorized
Resurvey By pain

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
 Company : CLKK
 Survey conducted on : 21/7/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.(b) Recommended Days of Repair : 04 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 21/7/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLN 672 U**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU203556307**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. : **2ZRS040014**

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp RH <i>CM</i>	1	\$2,531.60		✓
2	Headlamp clip <i>na</i>	10	\$40.00		✓
3	Bonnet <i>R</i>	1	\$812.40		X
4	Bonnet lock <i>R</i>	1	\$130.00		X
5	Bonnet hinge LH <i>R</i>	1	\$57.80		X
6	Bonnet hinge RH <i>R</i>	1	\$57.80		X
7	Front support panel RH <i>R</i>	1	\$213.50		X
8	Headlamp panel RH <i>R</i>	1	\$89.20		X
9	Support panel lower <i>R</i>	1	\$387.95		X
10	Support panel centre <i>R</i>	1	\$338.50		X
11	Front bumper <i>CM</i>	1	\$450.80		✓
12	Front bumper clip <i>na</i>	10	\$40.00		✓
13	Front bumper reinforcement - upper <i>R</i>	1	\$711.50		X
14	Front bumper reinforcement - lower <i>R</i>	1	\$245.30		X
15	Front bumper side retainer LH <i>SL</i>	1	\$107.20		X
16	Front bumper side retainer RH <i>CM</i>	1	\$107.20		✓
17	Front bumper sponge - upper <i>SL</i>	1	\$89.81		X
18	Front bumper sponge - lower <i>SL</i>		\$135.70		X
19	Front bumper tow cover RH <i>SL</i>	1	\$25.70		X
20	Front bumper upper grille <i>SL</i>	1	\$321.90		X
21	Front bumper lower grille <i>SL</i>	1	\$148.60		X
22	Fog lamp RH <i>Missing</i> <i>mis</i>	1	\$910.70		✓
23	RH front fender <i>BU</i>	1	\$868.70		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

4649

Spare Parts

Vehicle No. : **SLN 672 U**
Make & Model : **TOYOTA PRIUS**
Chassis No. : **JTDKB3FU203556307**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	RH front fender undershield <i>CM</i>	1	\$195.60		—
25	RH front fender undershield clip <i>Mc</i>	10	\$25.00		—
26	RHF fender wording "HYBRID" <i>Mc</i>	1	\$44.17		—
27	RHF fender quarter garnish <i>Mc</i>	1	\$122.70		—
28	RH front rim <i>Sm</i>	1	\$1,555.10		X
29	RH front tyre <i>Sm</i>	1	\$350.00	S.N	X
30	Washer tank <i>Mc</i>	1	\$195.60		—
31	Washer tank motor <i>CM</i>	1	\$196.74		—
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

779.81

Labour[illegible]

(32)