

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : FWD SINGAPORE PTE LTD
 6 TEMASEK BOULEVARD
 #18-01 SUNTEC TOWER 4
 SINGAPORE 038986

Claim No: MC1900490
Final No: MF1900616
Date: 09 Oct 2019
Policy No: PNPV2018-00012977
Veh Reg No: SCV718L
Make/Model: TOYOTA SIENTA 1.5 A

TEL: 67275700 FAX: 67275799
 ATTN: Motor Claim Department
 Your Ref No: -
 Claim Type: Own Damage
 Accident Date: 28/06/2019

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization) :SCV718L

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 FRONT BONNET	1 PC	750.80	
2 FRONT BONNET EMBLEM	1 PC	69.70	
3 FRONT BONNET INNER LOCK	1 PC	87.61	
4 HEADLAMP LH & RH	2 PC	1,843.20	
5 FRONT GRILLE -CHECK PRICE	1 PC	201.75	
6 FRONT GRILLE CHROME MOULDING LH	1 PC	122.60	
7 FRONT GRILLE CLIPS	8 PC	25.68	
8 FRONT BUMPER	1 PC	982.67	
9 FRONT BUMPER SIDE RETAINER LH & RH	2 PC	133.50	
10 FRONT BUMPER CLIPS	12 PC	46.68	
11 FRONT BUMPER LOWER AIR GRILLE	1 PC	123.60	
12 RADIATOR SUPPORT PANEL ASSY (TOP, BOTTOM, SIDE)	1 PC	893.50	
13 BRACE PANEL	1 PC	97.44	
14 AIR CON CONDENSER	1 PC	1,819.33	
15 RADIATOR	1 PC	1,714.67	
16 RADIATOR FAN MOTOR	1 PC	280.00	
17 RADIATOR FAN COWLING	1 PC	201.66	
18 RADIATOR SIDE AIR GUIDE RH	1 PC	55.39	
19 ENGINE UNDER COVER LH & RH	2 PC	291.20	
20 FRONT FENDER LH & RH COWLING	1 PC	168.75	
21 FRONT FENDER LH & RH COWLING CLIPS	16 PC	35.36	
		9,945.09	
	Less 25%	2,486.27	7,458.82
Special Nett			
22 COOLANT	1 PC	30.00	
23 NUMBER PLATE	1 PC	35.00	
		65.00	65.00
LABOUR			
24 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	20.00	
25 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00	
26 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR FRONT FENDER LH & RH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	600.00	
27 TO SPRAY FRONT BONNET,FRONT BUMPER, FRONT FENDER LH & RH, RADIATOR SUPPORT PANEL	1 PC	720.00	

AH LIM MOTOR COMPANY
 No. 10 Ang Mo Kio Industrial Park 2A
 #01-09 AMK Autopoint Singapore 568047
 Tel: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4
SINGAPORE 038986

TEL: 67275700 FAX: 67275799

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Own Damage

Accident Date: 28/06/2019

Claim No: MC1900490

Final No: MF1900616

Date: 09 Oct 2019

Policy No: PNPV2018-00012977

Veh Reg No: SCV718L

Make/Model: TOYOTA SIENTA 1.5 A

Repair Cost to Vehicle No (For Finalization) :SCV718L

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		1,440.00	1,440.00
		Total	S\$ 8,963.82
		Lump Sum Less 20%	-1,792.76
		Sub Total	S\$ 7,171.06
		Less Repair capped at \$6.6K	-571.06
		Lum Sum Repair	S\$ 6,600.00
		Less Excess	S\$ 500.00
		Amount Before GST	S\$ 6,100.00
		Add GST @ 7%	427.00
		Total Amount Payable	S\$ 6,527.00

TOTAL: SINGAPORE DOLLAR SIX THOUSAND FIVE HUNDRED TWENTY SEVEN ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 03/07/2019

AH LIM MOTOR COMPANY
For **AH LIM MOTOR COMPANY**
No. 10 Ang Mo Kio Industrial Park 2A
Singapore 568047

AUTHORISED SIGNATURE

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Jul 2019)
 Parts: M1-MPV TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ah Lim Motor Company/SCV718L/01/07/2019 16:48
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BONNET -CHECK PRICE	RM	0.00	0.00	*-F ✓
2	1		*FRONT BONNET EMBLEM -CHECK PRICE	RM	0.00	0.00	*-F ✓
3	2		*FRONT BONNET HINGE LH & RH	RM	0.00	0.00	*40.00 F X
4	1		*FRONT BONNET INNER LOCK	D.I	0.00	0.00	*35.00 F ✓
5	2		*HEADLAMP LH & RH -CHECK PRICE	0.00	0.00	0.00	*-F ✓
6	1		*FRONT GRILLE -CHECK PRICE	CPM	0.00	0.00	*-F ✓
7	2		*FRONT GRILLE CHROME MOULDING LH & RH	0.00	0.00	0.00	*96.00 F ✓
8	8		*FRONT GRILLE CLIPS	RM	0.00	0.00	*12.00 F ✓
9	1		*FRONT BUMPER -CHECK PRICE	RM	0.00	0.00	*-F ✓
10	2		*FRONT BUMPER SIDE RETAINER LH & RH	CPM	0.00	0.00	*50.00 F ✓
11	12		*FRONT BUMPER CLIPS	RM	0.00	0.00	*12.00 F ✓
12	1		*FRONT BUMPER REINFORCEMENT -CHECK PRICE	RM	0.00	0.00	*-F X
13	1		*FRONT BUMPER SPONGE	RM	0.00	0.00	*35.00 F X
14	1		*FRONT BUMPER LOWER AIR GRILLE -CHECK PRICE	CPM	0.00	0.00	*-F ✓
15	1		*FRONT BUMPER TOW COVER RH	RM	0.00	0.00	*8.00 F X
16	2		*FOGLAMP LH & RH -CHECK PRICE	N/S	0.00	0.00	*-F X
17	1		*RADIATOR SUPPORT PANEL TOP -CHECK PRICE	RM	0.00	0.00	*-F ✓
18	1		*RADIATOR SUPPORT PANEL BOTTOM -CHECK PRICE	RM	0.00	0.00	*-F ✓
19	2		*RADIATOR SUPPORT PANEL SIDE -CHECK PRICE	RM	0.00	0.00	*-F ✓
20	2		*HEADLAMP SUPPORT PANEL LH & RH -CHECK PRICE		0.00	0.00	*-F ✓
21	1		*BRACE PANEL -CHECK PRICE	RM	0.00	0.00	*-F ✓
22	1		*AIR CON CONDENSER -CHECK PRICE	B.I.P	0.00	0.00	*-F ✓
23	1		*AIR CON CONDENSER PIPE (COND TO COMP) -CHECK PRICE		0.00	0.00	*-F ✓
24	1		*RADIATOR -CHECK PRICE		0.00	0.00	*-F ✓
25	1		*RADIATOR FAN MOTOR		0.00	0.00	*90.00 F ✓
26	1		*RADIATOR FAN COWLING		0.00	0.00	*75.00 F ✓
27	1		*RADIATOR FAN BLADES -CHECK PRICE		0.00	0.00	*-F ✓
28	1		*RADIATOR TOP HOSE -CHECK PRICE	RM	0.00	0.00	*-F X
29	1		*RADIATOR BOTTOM HOSE -CHECK PRICE	RM	0.00	0.00	*-F X
30	2		*RADIATOR SIDE AIR GUIDE	RM N/S CPM	0.00	0.00	*36.00 F ✓
31	2		*ENGINE UNDER COVER LH & RH	CPM	0.00	0.00	*80.00 F ✓
32	2		*HORN		0.00	0.00	*70.00 F ✓
33	1		*FRONT FENDER LH & RH COWLING -CHECK PRICE	CPM	0.00	0.00	*-F ✓
34	16		*FRONT FENDER LH & RH COWLING CLIPS	RM	0.00	0.00	*16.00 F ✓
35	1		*COOLANT	RM	0	0.00	*30.00 FS ✓
36	1		*NUMBER PLATE	RM	0	0.00	*35.00 FS ✓

F=Franchise part. S=SpcNett.

Total Parts (S\$) **720.00**

Ah Lim Motor Company/SCV718L/01/07/2019 16:48. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00 <i>201</i>
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	New	100.00 ✓
3	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR FRONT FENDER LH & RH; INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	800.00 <i>600</i>
4	TO SPRAY FRONT BONNET; FRONT BUMPER; FRONT FENDER LH & RH; RADIATOR SUPPORT PANEL	New	800.00 <i>720</i>
Gross Labour Cost (S\$)			1,740.00

Ah Lim Motor Company/SCV718L/01/07/2019 16:48. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : FWD SINGAPORE PTE LTD
 6 TEMASEK BOULEVARD
 #18-01 SUNTEC TOWER 4
 SINGAPORE 038986

TEL: 67275700 FAX: 67275799

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Own Damage

Accident Date: 28/06/2019

Estimate No: MC1900490

Date: 29 Jun 2019

Policy No: PNPV2018-00012977

Veh Reg No: SCV718L

Make/Model: TOYOTA SIENTA 1.5 A

Estimate Repair Cost to Vehicle No :SCV718L

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 FRONT BONNET -CHECK PRICE	1 PC	750.80	
2 FRONT BONNET EMBLEM -CHECK PRICE	1 PC	69.70	
3 FRONT BONNET HINGE LH & RH	2 PC	109.80	
4 FRONT BONNET INNER LOCK	1 PC	87.61	
5 HEADLAMP LH & RH -CHECK PRICE	2 PC	1,843.20	
6 FRONT GRILLE -CHECK PRICE	1 PC	201.75	
7 FRONT GRILLE CHROME MOULDING LH & RH	2 PC	245.20	
8 FRONT GRILLE CLIPS	8 PC	25.68	
9 FRONT BUMPER -CHECK PRICE	1 PC	982.67	
10 FRONT BUMPER SIDE RETAINER LH & RH	2 PC	133.50	
11 FRONT BUMPER CLIPS	12 PC	46.68	
12 FRONT BUMPER REINFORCEMENT -CHECK PRICE	1 PC	326.70	
13 FRONT BUMPER SPONGE	1 PC	98.64	
14 FRONT BUMPER LOWER AIR GRILLE -CHECK PRICE	1 PC	123.60	
15 FRONT BUMPER TOW COVER RH	1 PC	27.20	
16 FOGLAMP LH & RH -CHECK PRICE	2 PC	472.66	
17 RADIATOR SUPPORT PANEL TOP -CHECK PRICE	1 PC	0.0000	
18 RADIATOR SUPPORT PANEL BOTTOM -CHECK PRICE	1 PC	893.50	
19 RADIATOR SUPPORT PANEL SIDE -CHECK PRICE	2 PC	0.0000	
20 HEADLAMP SUPPORT PANEL LH & RH -CHECK PRICE	2 PC	0.0000	
21 BRACE PANEL -CHECK PRICE	1 PC	97.44	
22 AIR CON CONDENSER -CHECK PRICE	1 PC	1,819.33	
23 AIR CON CONDENSER PIPE (COND TO COMP) -CHECK PRICE	1 PC	467.61	
24 RADIATOR -CHECK PRICE	1 PC	1,714.67	
25 RADIATOR FAN MOTOR	1 PC	280.00	
26 RADIATOR FAN COWLING	1 PC	201.66	
27 RADIATOR FAN BLADES -CHECK PRICE	1 PC	123.15	
28 RADIATOR TOP HOSE -CHECK PRICE	1 PC	56.70	
29 RADIATOR BOTTOM HOSE -CHECK PRICE	1 PC	61.33	
30 RADIATOR SIDE AIR GUIDE	2 PC	110.78	
31 ENGINE UNDER COVER LH & RH	2 PC	291.20	
32 HORN	2 PC	230.60	
33 FRONT FENDER LH & RH COWLING -CHECK PRICE	1 PC	168.75	
34 FRONT FENDER LH & RH COWLING CLIPS	16 PC	35.36	
		12,097.47	
	Less 25%	3,024.37	9,073.10
Special Nett			
35 COOLANT	1 PC	30.00	

AH LIM MOTOR COMPANY
 No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 Tel: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4
SINGAPORE 038986

TEL: 67275700 FAX: 67275799

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Own Damage

Accident Date: 28/06/2019

Estimate No: MC1900490

Date: 29 Jun 2019

Policy No: PNPV2018-00012977

Veh Reg No: SCV718L

Make/Model: TOYOTA SIENTA 1.5 A

Estimate Repair Cost to Vehicle No :SCV718L

Description	Quantity	List Price	Amount
		S\$	S\$
36 NUMBER PLATE	1 PC	35.00	
		65.00	65.00
LABOUR			
37 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
38 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00	
39 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR FRONT FENDER LH & RH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	
40 TO SPRAY FRONT BONNET,FRONT BUMPER, FRONT FENDER LH & RH, RADIATOR SUPPORT PANEL	1 PC	800.00	
		1,740.00	1,740.00
		Total	S\$ 10,878.10
		Add GST @ 7%	761.47
		Total Amount Payable	S\$ 11,639.57

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND SIX HUNDRED THIRTY NINE AND CENTS FIFTY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 FAX: 6483 6170
AUTHORISED SIGNATURE