

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4
SINGAPORE 038986

TEL: 67275700 FAX: 67275799

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Own Damage

Accident Date: 28/06/2019

Estimate No: MC1900490

Date: 29 Jun 2019

Policy No: PNPV2018-00012977

Veh Reg No: SCV718L

Make/Model: TOYOTA SIENTA 1.5 A

Estimate Repair Cost to Vehicle No :SCV718L

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 FRONT BONNET -CHECK PRICE	1 PC	750.80	
2 FRONT BONNET EMBLEM -CHECK PRICE	1 PC	69.70	
3 FRONT BONNET HINGE LH & RH	2 PC	109.80	
4 FRONT BONNET INNER LOCK	1 PC	87.61	
5 HEADLAMP LH & RH -CHECK PRICE	2 PC	1,843.20	
6 FRONT GRILLE -CHECK PRICE	1 PC	201.75	
7 FRONT GRILLE CHROME MOULDING LH & RH	2 PC	245.20	
8 FRONT GRILLE CLIPS	8 PC	25.68	
9 FRONT BUMPER -CHECK PRICE	1 PC	982.67	
10 FRONT BUMPER SIDE RETAINER LH & RH	2 PC	133.50	
11 FRONT BUMPER CLIPS	12 PC	46.68	
12 FRONT BUMPER REINFORCEMENT -CHECK PRICE	1 PC	326.70	
13 FRONT BUMPER SPONGE	1 PC	98.64	
14 FRONT BUMPER LOWER AIR GRILLE -CHECK PRICE	1 PC	123.60	
15 FRONT BUMPER TOW COVER RH	1 PC	27.20	
16 FOGLAMP LH & RH -CHECK PRICE	2 PC	472.66	
17 RADIATOR SUPPORT PANEL TOP -CHECK PRICE	1 PC	0.0000	
18 RADIATOR SUPPORT PANEL BOTTOM -CHECK PRICE	1 PC	893.50	
19 RADIATOR SUPPORT PANEL SIDE -CHECK PRICE	2 PC	0.0000	
20 HEADLAMP SUPPORT PANEL LH & RH -CHECK PRICE	2 PC	0.0000	
21 BRACE PANEL -CHECK PRICE	1 PC	97.44	
22 AIR CON CONDENSER -CHECK PRICE	1 PC	1,819.33	
23 AIR CON CONDENSER PIPE (COND TO COMP) -CHECK PRICE	1 PC	467.61	
24 RADIATOR -CHECK PRICE	1 PC	1,714.67	
25 RADIATOR FAN MOTOR	1 PC	280.00	
26 RADIATOR FAN COWLING	1 PC	201.66	
27 RADIATOR FAN BLADES -CHECK PRICE	1 PC	123.15	
28 RADIATOR TOP HOSE -CHECK PRICE	1 PC	56.70	
29 RADIATOR BOTTOM HOSE -CHECK PRICE	1 PC	61.33	
30 RADIATOR SIDE AIR GUIDE	2 PC	110.78	
31 ENGINE UNDER COVER LH & RH	2 PC	291.20	
32 HORN	2 PC	230.60	
33 FRONT FENDER LH & RH COWLING -CHECK PRICE	1 PC	168.75	
34 FRONT FENDER LH & RH COWLING CLIPS	16 PC	35.36	
		12,097.47	
	Less 25%	3,024.37	9,073.10
Special Nett			
35 COOLANT	1 PC	30.00	

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Ind. Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4
SINGAPORE 038986

TEL: 67275700 FAX: 67275799

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Own Damage

Accident Date: 28/06/2019

Estimate No: MC1900490

Date: 29 Jun 2019

Policy No: PNPV2018-00012977

Veh Reg No: SCV718L

Make/Model: TOYOTA SIENTA 1.5 A

Estimate Repair Cost to Vehicle No :SCV718L

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
36 NUMBER PLATE	1 PC	35.00	
		65.00	65.00
LABOUR			
37 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
38 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00	
39 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR FRONT FENDER LH & RH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	
40 TO SPRAY FRONT BONNET,FRONT BUMPER, FRONT FENDER LH & RH, RADIATOR SUPPORT PANEL	1 PC	800.00	
		1,740.00	1,740.00
		Total	S\$ 10,878.10
		Add GST @ 7%	761.47
		Total Amount Payable	S\$ 11,639.57

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND SIX HUNDRED THIRTY NINE AND CENTS FIFTY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
Singapore 568047
AUTHORISED SIGNATURE
TEL: 6483 1244 FAX: 6483 6170