

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 6650S

DATE 1/7/2019 8:38

MAKE :

MODEL : MERCEDES BENZ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			\$ 2,470.00
	Boot Lid Lamp (RH)			\$ 655.00
	Boot Lid Lock			\$ 275.00
	Boot Lid 'E220' Emblem			\$ 54.30
	Boot Lid Star Logo			\$ 45.00
	Boot Lid 'CDI' Emblem			\$ 54.30
	Rear Bumper			\$ 1,510.00
	Rear Bumper Reinforcement			\$ 1,150.00
	Rear Bumper Bracket Lower (LH/RH)		\$ 135.00	\$ 270.00
	Rear Bumper Bracket Top (LH/RH)		\$ 125.00	\$ 250.00
	Rear Bumper Retainer Mounting (LH/RH)		\$ 115.00	\$ 230.00
	Rear Bumper Lower Cover			\$ 325.00
	Taillamp (RH)			\$ 1,280.00
	Rear Panel End			\$ 1,380.00
	Rear Panel Inner Garnish			\$ 240.00
	Rear Panel Inner Garnish Clip (10pcs)			\$ 40.00
	SUB TOTAL			\$ 10,228.60
	LESS 20%			\$ 2,045.72
	DISCOUNTED TOTAL			\$ 8,182.88
	Boot Lid Sovereign' Sticker			\$ 25.00
	Rear Bumper Sensor			\$ 388.00
	Rear Bumper Rubber Mat			\$ 50.00
				\$ 463.00
	Labour Charge			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,820.00
	ESTIMATE TOTAL			\$ 10,465.88
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Chines

Quang

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Ka Li 1/7/19
1/7/19 10:45h.
3 days
4/5
After Repair photo

400
\$ 1,000.00
\$ 600.00
\$ 50.00
\$ 50.00
\$ 120.00

Nett
Nett
Nett

400
20
20
30