

7447

Form 1000

ASS. REC. BY:

REF:

CS/U0119011674/Kqd307

Special Instructions:

Surveyor

ASSIGNMENT (Office)

From (Person): Jenny Lew

of

U01

Date/Time:

2/7/2019

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SKA 6656H

Insured:

at Workshop n/s

Alan's United

Tel:

6453 8686

of

Blk 7 S/m #01-76

Policy No:

Claim No:

M12D1088 1907

Sum Insured:

Excess:

750

Make of Vch:

D.O.A.

24/6/2019.

(Client's Record)

CA / REV /

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction ( ) Estimate
	<u>SKA 6656H. -X</u>
<u>02/2/19 @ 2.16pm</u>	<u>revert to Jenny by email. (repairer asking is \$30k)</u>
<u>02/2/19 @ 6pm</u>	<u>Jenny informed <del>me</del> up to \$24k b ex: \$750 and the owner willing to top-up the difference.</u>
<u>02/2/19 @ 5.56pm</u>	<u>informed wksp clt on is \$24k b ex: \$750 and the owner willing to top-up the difference by email.</u>

ASS. REC. BY:

REF:

U02/ CS/003 19011874/k2013

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

N/A

Excess:

7500

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

883k without tax

IDAC Accident Report:

890k with tax

Consistent? Yes or No

GIA / PR Soon:

Consistent? Yes or No

Est. Repairs:

24 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKA 66564

Yr Regn:

10, 09

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mer E260 C161 c.c 1796

Colour:

M. Black

A/C: Insured / Std / NI / NA

Sp. Reading:

153582

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

W00 2120482A OF 4840

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

245/40 ZR18

R:

285/35 ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

5

mm

L/Bal.

4

mm

L/Bal.

5

mm

D.O.A.

24/6/19

D.O.I.

2/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

8/19

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

LS \$24000, 24 days (Red \$75765.80, 52%).

RECEIVED 13 AUG 2019

Date/Time, File Pass to?



: Prel. Report

11/13/18 MMSH



: Final Report

Date/Time, File Return to?

Days Of Repair:

24

Resurvey No. of Trip:

2

Survey Fee:

39x25=975

250+975

Transportation:

60

80+80

63

Fuel:

Others:

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format:

OD

Lump Sum / I.B.I. (\$

24000

1508

## Nivitha (LKK Auto)

---

**From:** LEW JENNY <jennylew@uoi.com.sg>  
**Sent:** Tuesday, 2 July 2019 9:34 AM  
**To:** kennychan@alanutd.com; assignments; SUR  
**Subject:** RE: ATTACHED SKA6656H REPAIR ESTIMATE,GIA REPORT FOR ARRANGE OWN DAMAGED CLAIM SURVEY  
**Attachments:** SKM\_284e19062913140.zip

Dear Kenny,

We will arrange LKK to survey the vehicle.

Dear Denise,

Please arrange to survey the vehicle at Alan's United Auto Pte Ltd.  
Excess: S\$750

Thank You.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079908  
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3859 | Email • [jennylew@uoi.com.sg](mailto:jennylew@uoi.com.sg)

### UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

---

**From:** kennychan@alanutd.com [mailto:kennychan@alanutd.com]  
**Sent:** Saturday, 29 June, 2019 2:12 PM  
**To:** LEW JENNY <jennylew@uoi.com.sg>  
**Subject:** ATTACHED SKA6656H REPAIR ESTIMATE,GIA REPORT FOR ARRANGE OWN DAMAGED CLAIM SURVEY

Dear Jenny

Attached SKA6656H repair estimate ,GIA report for arrange own damaged claim survey at our workshop , thank you

Regards  
Kenny  
Alan's United Auto Pte Ltd  
64538686

*Kenneth*

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Wednesday, 3 July 2019 5:56 PM  
**To:** kennychan@alanutd.com; alan khong chin wah  
**Cc:** SUR  
**Subject:** OD VEHICLE SKA 6656H (DOA: 24/06/2019)  
**Attachments:** UOI OD Template.pdf

Dear Sir/Madam,

As instructed by our client, please proceed to repair the insured vehicle **SKA 6656H** at repair cost **\$24,000** on **Lump Sum basis and the owner will top-up the difference (Excess \$750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Shiau Chan (LKKAUTO)

---

**From:** LEW JENNY <jennylew@uoi.com.sg>  
**Sent:** Wednesday, 3 July 2019 5:00 PM  
**To:** Shiau Chan (LKKAUTO); assignments; SUR  
**Subject:** RE: ATTACHED SKA6656H REPAIR ESTIMATE, GIA REPORT FOR ARRANGE OWN DAMAGED CLAIM SURVEY / M12D10881907  
**Attachments:** OD Template.zip

Dear Shiau Chan,

Please proceed with the repair authorisation up to S\$24,000.00.  
Excess: S\$750.00

I have contacted insured, he is willing to top up the difference.

Enclosed the discharge voucher for client due execution.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909  
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • [jennylew@uoi.com.sg](mailto:jennylew@uoi.com.sg)

### UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

---

**From:** Shiau Chan (LKKAUTO) [mailto:[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)]  
**Sent:** Wednesday, 3 July, 2019 2:16 PM  
**To:** LEW JENNY <jennylew@uoi.com.sg>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: ATTACHED SKA6656H REPAIR ESTIMATE, GIA REPORT FOR ARRANGE OWN DAMAGED CLAIM SURVEY

Dear Jenny,

Enclosed herewith preliminary advice of SKA 6656H.  
Repairster asking for repair cost at Lump Sum \$30,000.00.

We have not authorise repair.  
Kindly advise on claim number.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 2 July 2019 10:48 AM

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Wednesday, 3 July 2019 2:16 PM  
**To:** 'LEW JENNY'; assignments; SUR  
**Subject:** RE: ATTACHED SKA6656H REPAIR ESTIMATE,GIA REPORT FOR ARRANGE OWN DAMAGED CLAIM SURVEY  
**Attachments:** CSUOI19011674Kqd3.pdf

Dear Jenny,

Enclosed herewith preliminary advice of SKA 6656H.  
Repairer asking for repair cost at Lump Sum \$30,000.00.

We have not authorise repair.  
Kindly advise on claim number.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 2 July 2019 10:48 AM  
**To:** 'LEW JENNY' <[jennylew@uoi.com.sg](mailto:jennylew@uoi.com.sg)>; kennychan@alanutd.com; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: ATTACHED SKA6656H REPAIR ESTIMATE,GIA REPORT FOR ARRANGE OWN DAMAGED CLAIM SURVEY

Dear Jenny,

Thank you for the assignment.

Best Regards,

**Celine Fong**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** LEW JENNY [<mailto:jennylew@uoi.com.sg>]  
**Sent:** Tuesday, 2 July 2019 9:34 AM  
**To:** kennychan@alanutd.com; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: ATTACHED SKA6656H REPAIR ESTIMATE,GIA REPORT FOR ARRANGE OWN DAMAGED CLAIM SURVEY

Dear Kenny,

We will arrange LKK to survey the vehicle.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 03<sup>rd</sup> July 2019

Our Ref: CS/UOI19011674/Kqd3

The Motor Claims Department  
United Oversea Insurance

Attn: Jenny

Dear Sirs/Mdm

**PRELIMINARY ADVICE OF VEHICLE NO. SKA 6656H**


We thank you for the instruction on 02/07/2019.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 02/07/2019 at the premises of M/s ALAN'S UNITED and have the following to report:-

Workshop Estimate Amount	: S\$	<u>49,765.80</u>	.
Revised Estimate Amount	: S\$	<u>29,600.40</u>	.
"Check" Items Amount	: S\$	<u>18,499.00</u>	.
Market Value	: S\$	<u>85,000.00</u>	.
LTA Reimbursement Value	: S\$	<u>60,189.00</u>	.
Nett Value	: S\$	<u>24,811.00</u>	.

Description of Damage:

The vehicle sustained damages at the rear and front portion.



Comments/ Present Status:

Damages consistent.

Repairer asking for repair cost at Lump Sum \$30,000.00.

We have not authorize repair.

Yours faithfully

KONG SENG CHEONG  
Licensed Appraiser



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 02/07/2019

Our Ref: CS/UOI19011674/Kqd3

The Motor Claims Department  
United Overseas Insurance Ltd

Dear Sir/Mdm

**AMENDMENT PRELIMINARY ADVICE OF VEHICLE NO. SKA 6656H**


We thank you for the instruction on 2/7/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 2/7/2019 at the premises of M/s Alan's United and have the following to report: -

Workshop Estimate Amount	: S\$ 49,765.80
Revised Estimate Amount	: S\$ 29,600.40
"Check" Items Amount	: S\$ 18,499.00
Total	: S\$ 48,099.40
Market Value	: S\$ 83,000.00
LTA Reimbursement Value	: S\$ 60,189.00
Nett Value	: S\$ 22,811.00

**Description of Damage:**

The vehicle sustained damages  
at the rear and front portion



Days of repair: 24

**Comments/ Present Status:**

Damages Consistent.  
Repair Cost uneconomical.

Yours faithfully  
Kenneth  
Automotive Assessor



> Back to OneMotoring

#### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	7941Z
<b>Vehicle Details</b>	
Vehicle No.:	SKA6656H
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jul 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 200CGI
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	27186030003103
Chassis No.:	WDD2120482A074840
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$56,031.00
Original Registration Date:	15 Oct 2009
First Registration Date:	15 Oct 2009
Transfer Count:	0
Actual ARF Paid:	\$56,031.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Oct 2019
PARF Rebate Amount:	\$28,015.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	31 Mar 2029
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$33,018.00
COE Rebate Amount:	\$32,174.00
<b>Total Rebate Amount:</b>	<b>\$60,189.00</b>

The information contained herein is correct as at 02 Jul 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/06/2019 14:06
Date Of Accident	24/06/2019 19:45
Exact Location Of Accident	ANG MO KIO AVENUE 6 TO LENTOR AVENUE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA6656H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN GIM HENG
NRIC No	S1827941Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97899830
Alternative Phone No	OTHERS-97899830

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200 CGI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	UNITED OVERSEAS INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DHOM120013851501
Cover Note Number	

### Driver

Name of Driver	TAN GIM HENG
NRIC No	S1827941Z
Date Of Birth	19/10/1967
Occupation	INDOOR
Date Of Driving Pass	28/01/1988
Driving Experience	31 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97899830
Fax Number	
Contact Number	OTHERS-97899830
Email Address	NOEMAIL

Address	BLK 326 SEMBAWANG CRESCENT #06-52
Postcode	750326
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	SEMPAWANG NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH TRAFFIC POLICE
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GT6259T
Vehicle Make/Model/Colour	NISSAN NV350
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LIM YOK SENG
NRIC/Passport Number	S2538362A
Contact Number	
Address	
Postcode	
Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number	SKS9526K
Vehicle Make/Model/Colour	NISSAN SYLPHY
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN HENG WANG
NRIC/Passport Number	S1769826E
Contact Number	96878805
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

26 JUN 2019

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature


Name:

Jenny Lim

NRIC/FIN No.:

S6927273H

## SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT ATTACHED

Police Report : T/20190625/2002

P/S: AFTER THE ACCIDENT, I WAS FELT WHOLE-BODY WAS PARALYSIS IN SIDE MY VEHICLE FOR FEW MINUTE. AND AFTER I, GET BACK TO NORMAL THEN I MANAGED TO GET OUT FROM MY VEHICLE, I HAVE 5 DAYS MC GIVEN BY DOCTOR THE NEXT DAY AFTER I HAVE CONSULT DOCTOR.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date &amp; Time

26 JUN 2019

©IABAC SketchPlanForm\_V3

Driver's Signature

(If driver is not the policyholder)

Date &amp; Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Jenny Lim  
S6927273H



# SINGAPORE POLICE FORCE



T/20190625/2002

Police Station Of Origin:  
Sembawang N.P.C  
4 Sembawang Crescent SINGAPORE  
757633  
Tel No: 1800-5549999

1 of 4

Report No. T/20190625/2002

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 25/06/2019 00:51	Vide Report No.: F/20190624/0141	Station Diary No.: 14
--	-------------------------------------	--------------------------

**Informant's Particulars**

Name of Informant: TAN GIM HENG			Address: APT BLK 326 SEMBAWANG CRESCENT #06-52 SINGAPORE 750326		
ID Type / ID No.: NRIC NO / S1827941Z			Contact No.: Home/Office: Mobile: 97899830		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 51	Date of Birth: 19/10/1967	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Motor vehicle mechanic			Driving Licence Information: Class: 3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Non-Injury Attended by Police	Drink Drive: Yes	Date/Time of Accident: 24/06/2019 19:45	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 ANG MO KIO AVENUE 6 LENTOR AVENUE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GT6259T	Van				Slightly Damaged	0
QX470Z	Car				No Damage	0
SKA6656H	Car	MERCEDES BENZ	E 200CGI	Black	Seriously Damaged	0
SKS9526K	Car				Slightly Damaged	2



Police Station Of Origin:  
Sembawang N.P.C  
4 Sembawang Crescent SINGAPORE  
757633  
Tel No: 1800-5549999

Report No. T/20190625/2002

**CONTINUATION OF REPORT**

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKA6656H	UNITED OVERSEAS INSURANCE LIMITED	DHOM120013851501	15/10/2017	14/10/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	TAN GIM HENG		ID No.	S1827941Z
Related Vehicle	SKA6656H (Car)		Contact No.	97899830
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL
Driver				
Name	Tan Heng Wang		ID No.	S1769826E
Related Vehicle	SKS9526K (Car)		Contact No.	96878805
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL

**Brief Details.**

On 24/06/2019 at about 1945hrs, I was in a stationary position in my vehicle SKA 6656H waiting for the traffic to turn green. There were some vehicles in front of me. Suddenly, a van GT 6259T hit on to the rear of my vehicle. Due to the impact of the accident, my vehicle moved forward and hit onto the rear of vehicle SKS 9526K. I came out of my vehicle to check and discovered that I was involved in a chain accident with another 2 vehicles. There was also a police vehicle QX 470Z at the back of the van GT 6259T. The police officer informed me that they are chasing the van GT 6259T earlier. A few minutes later, traffic police came to assist us. No one was injured in the accident. I was advise by the traffic police to lodge a traffic accident report.

Due to the accident, my vehicle SKA 6656H was towed away to my car serving workshop located at Sin Ming. My car was seriously damage. I am not sure of the damage cost of my vehicle.

I am lodging this report for traffic police actions and insurance claims.





**SINGAPORE  
POLICE FORCE**



T/20190625/2002

Police Station Of Origin:  
Sembawang N.P.C  
4 Sembawang Crescent SINGAPORE  
757633  
Tel No: 1800-5549999

3 of 4

Report No. T/20190625/2002

CONTINUATION OF REPORT

A handwritten signature in black ink, appearing to be "Jeng" or similar, with a stylized flourish.



**SINGAPORE  
POLICE FORCE**



T/20190625/2002

4 of 4

Police Station Of Origin:  
Sembawang N.P.C  
4 Sembawang Crescent SINGAPORE  
757633  
Tel No: 1800-5549999

Report No. T/20190625/2002

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

L /

Sgt 2 MUHAMMAD SADLI BIN RAZALI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

25/06/2019 00:51

Officer In Charge Of Case:

TP / GIT /

Classification Of Case:

SN 064

Contact No.:

Signature:

Authentication Stamp

NP168

Singapore Police Force



TRAFFIC POLICE  
AMENDMENT

Traffic Police Department  
Charge Office  
10 Ubi Avenue 3  
Singapore 408865

NP 168 No.	: T/20190625/2002	Name	: Tan Gim Heng
Accident	: 24/60/2019@1945hrs	Address	: Blk 326 Sembawang Crescent #06-52
Date/Time		NRIC No	: S1827941Z
Vehicle Involve	: GT6259T	Tel No	: 97899830
	: QX470Z	Date	: 26/06/2019
	: SKA6656H		
	: SKS9526K		

Dear Sir / Madam

Accident involving GT6259T, QX470Z, SKA6656H, SKS9526K  
along Along Ang Mo Kio Ave 6 towards Lentor Ave On 24/06/2019 at 1945 hours

With reference to the above, I have on 25/06/2019 (date) 0051 hours (time) make a  
police report at Sembawang NPC (Police Station/NPP/NPC)  
In NP 168 – T/ 20190625/2002

On 26/06/2019 (date), 1955hrs (time) at Sembawang NPC  
(Police Station/NPP/NPC), I make the following amendments to the above report;

Details of MC : 5 days from 25 June to 29 June 2019. MC given on 25 June 2019 by Dr Ho Li  
Chin of Mount Alvernia Hospital.

Yours Faithfully,

(Signature)

#### FOR OFFICIAL USE

If a police officer recorded these amendments, please complete the following.

Name / Rank No	: SSgt T130117 Haziq Hamizi
Date and Time	: 26/06/2019, 1955hrs
Station Diary No	: 87
Signature	:

**SEMBAWANG NPC**  
4 Sembawang Crescent  
Singapore 757633  
Tel: 1880-5542989  
Fax: 66522499



MEMBER OF THE UOB GROUP

United Overseas Insurance Limited

3 Anson Road  
#28-01 Springleaf Tower  
Singapore 079909

Tel (65) 6222 7733  
Fax (65) 6327 3869 / 6327 3870  
Email: ContactUs@uoi.com.sg  
uoi.com.sg

Co. Reg. No. 197100152R

## Certificate of Insurance

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)  
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960  
Road Transport Act, 1987 (Malaysia)  
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

**ORIGINAL**

<b>CERTIFICATE NO.</b>	DH0M120013851501	<b>Excess:</b>	\$1500/-OTHERS \$3000/-APPL TO <25 YRS & OR <3YRS EXP \$100/-WINDSCREEN DAMAGE CLAIM \$750/-NAMED DRIVERS - OPTION 2
<b>Type of Cover</b>	COMPREHENSIVE		
<b>Vehicle Number</b>	SKA6656H		
<b>Name of Insured</b>	TAN GIM HENG		
<b>Restricted Driver(s)</b>	NOT APPLICABLE		

**Period of Insurance** 15 October 2017 to 14 October 2019

**Engine#** 27186030003103  
**Chassis#** WDD2120482A074840

**Hire Purchase** MALAYAN BANKING BHD

PRIVATE CAR - INDIVIDUAL OWNERSHIP [MX 1]  
AUTHORISED DRIVER

- (1) The Insured
- (2) Any other person who is driving on the Insured's order or with his permission
- (3) In the event of the death of the Insured
  - (a) any member of the Insured's family or a paid driver who has been driving the car during the lifetime of the Insured and permission to drive had not been withdrawn prior to the death of Insured and
  - (b) any other person who has been given permission to drive the vehicle prior to the death and such permission had not been withdrawn by the Insured

### LIMITATIONS AS TO USE

Use only for social domestic and pleasure purposes and for the Insured's business

### THE POLICY DOES NOT COVER

Use for hire or reward or racing pace-making reliability trial or speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purposes in connection with the Motor Trade

The carriage of passengers pursuant to car pooling arrangements and payments or any of them made by the passengers thereunder towards the running expenses of any vehicle described in the Schedule shall not be deemed to constitute use for hire or reward

Provided that the person is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

\*Limitation rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles(Third-Party Risks and Compensation) Act (Chapter 189) and part iv of the Road Transport Act, 1987 (Malaysia)

UNITED OVERSEAS INSURANCE LTD

For the Company

FCTTS Date : 19/09/2017

# Enquire Vehicle Registration Details

## Owner Particulars

NRIC/Passport/Company Cert No.:	S1827941Z
Owner ID Type:	Singapore NRIC
Owner Name:	TAN GIM HENG
Registered Address:	APT BLK 326 SEMBAWANG CRESCENT #06-52 SINGAPORE 750326
Mailing Address:	-
Birth Date:	19 Oct 1967

## Vehicle Particulars

Vehicle No.:	SKA6656H
Previous Vehicle No.:	-
Effective Date of Ownership:	15 Oct 2009
Original Regn Date:	15 Oct 2009
Registration Date:	15 Oct 2009
Year of Manufacture:	2009
Vehicle Type:	Passenger Motor Car
Vehicle Scheme:	-
Vehicle Attachment 1:	No Attachment
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 200CGI
Primary Colour:	Black
Secondary Colour:	-
Passenger Capacity:	4
Chassis No.:	WDD2120482A074840
Engine No.:	27186030003103
Engine Capacity / Power Rating:	1796 cc / -
Maximum Power Output:	135.0 kW (181 bhp)
Propellant:	Petrol
Max Unladen Weight:	1615 kg
Maximum Laden Weight:	2150 kg
Open Market Value:	\$56,031.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Oct 2019
Minimum PARF Benefit:	\$28,015.00
No. of Transfers:	0
IU Label No.:	1123427733
COE No.:	2009110103000530R
COE Expiry Date:	31 Mar 2029
COE Category:	B - Car (1601cc & above)
COE Registration Category:	B - Car (1601cc & above)
Quota Premium (QP) / Prevailing Quota Premium:	\$18,109.00 / -
PQP Paid:	\$33,018.00
QP (Regn Cat):	\$18,109.00
OPC Cash Rebate Eligibility:	No
QP during COE Bidding Exercise:	\$18,109.00
Additional Registration Fee Rate:	100.00 %
Actual ARF Paid:	\$56,031.00
Vehicle Lifespan Expiry Date:	No Lifespan
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-
Message:	To renew the COE, the Prevailing Quota Premium payable is that of Category B.

Print

OK

Save as PDF

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06005

Your Reference : DHOM120013851501

Accident Date : 24-Jun-2019

Date : 29-Jun-2019

Our Ref : 219103 / CHAN

PAGE : 1

UNITED OVERSEAS INSURANCE LIMITED  
3 ANSON ROAD  
#28-01 SPRINGLEAF TOWER  
Singapore 079909



*Not Notarised*

*11 Pm 8?*

*24 day,*

*Money B4 paint*

ESTIMATED COST OF REPAIR FOR M/BENZ E200CGI SKA6656H

*Ex \$750*

1 pc	Front bumper fascia (AMG PACK)		<i>Bu</i> 2,038.00	<i>✓</i>
1 pc	Front bumper tow cover		<i>his</i> 95.00	<i>✓</i>
1 pc	Front no.plate garnish		179.00	<i>7/CRH</i>
1 pc	Front bumper sponge		95.00	<i>7/CRH</i>
2 pcs	Front bumper side sponge	@ S\$ 93.00	186.00	<i>7/CRH</i>
2 pcs	Front bumper parking sensor	@ S\$307.00	614.00	<i>7/CRH</i>
1 pc	Front bumper reinforcement		<i>R</i> 917.00	<i>✓</i>
1 pc	Front bumper lower grille		<i>CRH</i> 143.00	<i>✓</i>
1 pc	Radiator grille (AMG PACK)		<i>CRH</i> 1,420.00	<i>✓</i>
1 pc	Radiator top cover		161.00	<i>7/CRH</i>
2 pcs	Front seat head rest	@ \$1127.00	2,254.00	<i>7/CRH</i>
2 pcs	Front seat safety belt	@ \$1621.00	<i>his</i> 3,242.00	<i>✓</i>
2 pcs	Rear seat safety belt	@ S\$659.00	<i>his</i> 1,318.00	<i>✓</i>
2 pcs	Headlamp assy	@ \$1400.00	2,800.00	<i>7/CRH</i>
1 pc	Rear windscreen glass		<i>CRH</i> 1,517.00	<i>✓</i>
1 pc	Rear n/s fender		<i>Bu</i> 2,545.00	<i>✓</i>
1 pc	Rear n/s fender air duct		30.00	<i>7/CRH</i>
2 pcs	Rear fender top garnish	@ S\$ 72.00	<i>CRH</i> 144.00	<i>✓</i>
4 pcs	Rear fender top garnish clip	@ S\$ 4.00	<i>CRH</i> 16.00	<i>✓</i>
1 pc	Rear n/s fender inner shield		220.00	<i>7/CRH</i>
1 pc	Rr n/s fender shield cover		38.00	<i>7/CRH</i>
1 pc	Rear n/s fender inner trim		386.00	<i>7/CRH</i>
1 pc	Boot lid		<i>R</i> 3,134.00	<i>✓</i>
1 pc	Boot lid inner lock		<i>his</i> 572.00	<i>✓</i>
1 pc	Boot lid rubber		<i>his</i> 285.00	<i>50lin 147.50</i>
2 pcs	Boot lid hinge	@ S\$210.00	<i>R</i> 420.00	<i>✓</i>
2 pcs	Boot lid hinge cover	@ S\$ 29.00	58.00	<i>7/CRH</i>
1 pc	Boot lid lock hook		518.00	<i>7/CRH</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To remedy before the Car is Page 2 ...
- To display damaged parts during remedy
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal implication(s) is allowed
- Supplementary work(s) must be remedied and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signed:

Date:

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : DHOM120013851501

Page : 2

1 pc	Boot lid inner trim		220.00	7 ✓ DE
2 pcs	Boot lid stopper	@ S\$ 18.00	36.00	X
1 pc	Boot lid outer chrome		161.00	✓
1 pc	Boot lid open handle		330.00	7 ✓ NO
2 pcs	Boot lid license plate lamp	@ S\$ 32.00	64.00	7 X PVC
2 pcs	Boot lid lamp	@ S\$580.00	1,160.00	N/A
1 pc	Boot lid E200 emblem		91.00	✓
1 pc	Boot lid star logo		53.00	✓
3 pcs	Boot lid star logo rivet	@ S\$ 3.00	9.00	✓
1 pc	Boot lid AMG emblem		216.00	✓
1 pc	Boot lid break down sign		211.00	7 ✓ N/A
1 pc	Break down sign holder		35.00	7 ✓ N/A
1 pc	Rear bumper fascia (AMG)		2,175.00	✓
1 pc	Rear bumper lower spoiler		624.00	✓
1 pc	Rear bumper reinforcement		917.00	✓
2 pcs	Rr bumper reinforcement plate	@ S\$ 40.00	80.00	✓
2 pcs	Rear bumper side retainer	@ S\$ 45.00	90.00	✓
2 pcs	Rear bumper lower bracket	@ S\$ 82.00	164.00	✓
2 pcs	Rear bumper exhaust pipe seal	@ S\$275.00	550.00	7 ✓ N/A
4 pcs	Rear bumper parking sensor	@ S\$307.00	1,228.00	✓
4 pcs	Rr bumper parking sensor seal	@ S\$ 11.00	44.00	✓
1 pc	Rr bumper parking sensor wire		230.00	7 ✓ N/A
2 pcs	Taillamp	@ S\$794.00	1,588.00	✓
2 pcs	Taillamp lower bracket	@ S\$ 82.00	164.00	✓
1 pc	Taillamp inner panel		1,824.00	7 ✓ N/A
1 pc	End panel		1,421.00	✓
1 pc	End panel top garnish		145.00	7 ✓ N/A
1 pc	Rear n/s member		704.00	7 ✓ N/A
1 pc	Rear o/s top side panel		473.00	7 ✓ N/A
1 pc	Rear o/s lower side panel		704.00	7 ✓ N/A
1 pc	Rear n/s side panel		473.00	7 ✓ N/A
1 pc	Rear spare tyre tray		325.00	✓
1 pc	Rear o/s side tray		37.00	7 X PVC
1 pc	Rear n/s side tray		46.00	7 X PVC
1 pc	Rear spare tyre tray grum		260.00	7 ✓ N/A
1 pc	Spare tyre tray inner panel		749.00	7 ✓ N/A
2 pcs	Rear exhaust silencer box	@ \$1833.00	3,666.00	7 ✓ N/A
2 pcs	Rear exhaust box mounting	@ S\$ 16.00	32.00	7 X PVC

Con't Page 3 ...

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : DHOM120013851501

Page : 3

2 pcs Rear exhaust box bracket	@ S\$ 80.00	160.00	? ✓ R3
2 pcs Rear exhaust box coupling	@ S\$ 22.00	44.00	? XSVL
1 pc Centre exhaust convertor		1,232.00	? XSVL
1 pc Rear exhaust top heat seal		127.00	? ✓ B1
1 pc Rear n/s heat seal		97.00	? XSVL
1 pc Rear n/s heat seal (inner)		131.00	? XSVL
1 pc Rear n/s heat seal (inner frt)		49.00	? XSVL
1 pc Rear o/s heat seal (top inner)		97.00	? XSVL
1 pc Rear exhaust heat seat lower		81.00	? ✓ OP

48,662.00

Less 10% : 4,866.20

1 pc Front no.plate with box
1 pc Rear no. plate with box
1 pc Rear w/s glass sealant

43,795.80 45JA  
 50.00 sn  
 50.00 sn 45JA  
 60.00 sn 40JA

To towing

(B11) 100.00 ? ✓

To rewire damaged parts and refocus headlamp beam.

120.00 601

To remove & renew rear windscreen glass and conduct water leak test.

150.00 1201

To remove roof lining, front and rear seats, trim board and carpet

120.00 ✓

To remove and renew exhaust silencer box (rear & centre)

(CV) 120.00 ? ✓

To putty and spray replaced parts

2,400.00 18001

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

2,800.00 20001

Total : S\$49,765.80

Singapore Dollars Forty Nine Thousand Seven Hundred and Sixty Five and Cents Eighty Only



# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : DHOM120013851501

Accident Date : 24-Jun-2019

No. : 06005

Date : 29-Jun-2019

Our Ref : 219103 / CHAN

PAGE : 1

UNITED OVERSEAS INSURANCE LIMITED  
3 ANSON ROAD  
#28-01 SPRINGLEAF TOWER  
Singapore 079909

*24 day*  
*24 day*

*Not within*  
*11 days & 24000*  
*Money B4 paint*  
*Ex 87501*

## ESTIMATED COST OF REPAIR FOR M/BENZ E200CGI SKA6656H

1 pc	Front bumper fascia (AMG PACK)		Bu	2,038.00	✓
① pc	Front bumper tow cover		213	95.00	✓
① pc	Front no.plate garnish		CM	179.00	7✓
1 pc	Front bumper sponge		Sm	95.00	7x
2 pcs	Front bumper side sponge	@ S\$ 93.00	Sm	186.00	7x
2 pcs	Front bumper parking sensor	@ S\$307.00	Sm	614.00	7x
① pc	Front bumper reinforcement		R	917.00	✓
1 pc	Front bumper lower grille		CM	143.00	✓
① pc	Radiator grille (AMG PACK)		CM	1,420.00	✓
① pc	Radiator top cover		CM	161.00	7✓
2 pcs	Front seat head rest	Act R @ \$1127.00		2,254.00	X SVC
2 pcs	Front seat safety belt	@ \$1621.00	In	3,242.00	✓
2 pcs	Rear seat safety belt	@ S\$659.00	In	1,318.00	✓
② pcs	Headlamp assy	my CM @ \$1400.00		2,800.00	7✓
1 pc	Rear windscreen glass		Gr	1,517.00	✓
1 pc	Rear n/s fender		Bu	2,545.00	✓
1 pc	Rear n/s fender air duct		CM	30.00	7✓
2 pcs	Rear fender top garnish	@ S\$ 72.00	CM	144.00	7✓
4 pcs	Rear fender top garnish clip	@ S\$ 4.00	RM	16.00	✓
1 pc	Rear n/s fender inner shield		Sm	220.00	7x
1 pc	Rr n/s fender shield cover		Sm	38.00	7x
1 pc	Rear n/s fender inner trim		CM	386.00	7✓
1 pc	Boot lid		R	3,134.00	✓
1 pc	Boot lid inner lock		In	572.00	✓
1 pc	Boot lid rubber		Dis/In	285.00	50 lin 142.50 SN
2 pcs	Boot lid hinge	@ S\$210.00	R	420.00	✓
2 pcs	Boot lid hinge cover	@ S\$ 29.00	Red	58.00	7✓
1 pc	Boot lid lock hook		R	518.00	7✓

Con't Page 2 ...

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : DHOM120013851501

Page : 2

1 pc Boot lid inner trim		Return	220.00	7 ✓
2 pcs Boot lid stopper	@ S\$ 18.00	Sm	36.00	X
1 pc Boot lid outer chrome		R1	161.00	✓
1 pc Boot lid open handle		But	330.00	7 ✓
2 pcs Boot lid license plate lamp	@ S\$ 32.00	Sm	64.00	7 X
2 pcs Boot lid lamp	@ S\$580.00		1,160.00	✓
1 pc Boot lid E200 emblem		Sm	91.00	✓
1 pc Boot lid star logo		Sm	53.00	✓
3 pcs Boot lid star logo rivet	@ S\$ 3.00	Sm	9.00	✓
1 pc Boot lid AMG emblem		Sm	216.00	✓
1 pc Boot lid break down sign		CM	211.00	7 ✓
1 pc Break down sign holder		CM	35.00	7 ✓
1 pc Rear bumper fascia (AMG)		R1	2,175.00	✓
1 pc Rear bumper lower spoiler		CM	624.00	✓
1 pc Rear bumper reinforcement		R1	917.00	✓
2 pcs Rr bumper reinforcement plate	@ S\$ 40.00	DIT	80.00	✓
2 pcs Rear bumper side retainer	@ S\$ 45.00	CM	90.00	✓
2 pcs Rear bumper lower bracket	@ S\$ 82.00	R1	164.00	✓
2 pcs Rear bumper exhaust pipe seal	@ S\$275.00	MT	550.00	7 ✓ MISSING
4 pcs Rear bumper parking sensor	@ S\$307.00		1,228.00	✓
4 pcs Rr bumper parking sensor seal	@ S\$ 11.00	Sm	44.00	✓
1 pc Rr bumper parking sensor wire		MT	230.00	7 ✓
2 pcs Taillamp	@ S\$794.00		1,588.00	✓
2 pcs Taillamp lower bracket	@ S\$ 82.00	DIT	164.00	✓
1 pc Taillamp inner panel		R1	1,824.00	7 ✓
1 pc End panel		R1	1,421.00	✓
1 pc End panel top garnish		CM	145.00	7 ✓
1 pc Rear n/s member		R1	704.00	7 ✓
1 pc Rear o/s top side panel		R1	473.00	7 ✓
1 pc Rear o/s lower side panel		R1	704.00	7 ✓
1 pc Rear n/s side panel		DIT	473.00	7 ✓
1 pc Rear spare tyre tray		CM	325.00	✓
1 pc Rear o/s side tray		Sm	37.00	7 X
1 pc Rear n/s side tray		Sm	46.00	7 X
1 pc Rear spare tyre tray grum		Sm	260.00	7 ✓ N.E.C
1 pc Spare tyre tray inner panel		R1	749.00	7 ✓
2 pcs Rear exhaust silencer box	@ \$1833.00	R1	3,666.00	7 ✓
2 pcs Rear exhaust box mounting	@ S\$ 16.00	Sm	32.00	7 X

Con't Page 3 ...

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : DHOM120013851501

Page : 3

- 2 pcs Rear exhaust box bracket
- 2 pcs Rear exhaust box coupling
- 1 pc Centre exhaust convertor
- 1 pc Rear exhaust top heat seal
- 1 pc Rear n/s heat seal
- 1 pc Rear n/s heat seal (inner)
- 1 pc Rear n/s heat seal (inner frt)
- 1 pc Rear o/s heat seal (top inner)
- 1 pc Rear exhaust heat seat lower

@ S\$ 80.00	160.00	✓
@ S\$ 22.00	44.00	✓
	1,232.00	✓
	127.00	✓
	97.00	✓
	131.00	✓
	49.00	✓
	97.00	✓
	81.00	✓

Less 10% : 48,662.00  
4,866.20

43,795.80  
43,795.80  
38881.80

- 1 pc Front no.plate with box
- 1 pc Rear no. plate with box
- 1 pc Rear w/s glass sealant

43,795.80  
50.00 sn  
50.00 sn  
60.00 sn

To towing

(Bill) 100.00 ✓

To rewire damaged parts and refocus headlamp beam.

120.00 601

To remove & renew rear windscreen glass and conduct water leak test.

150.00 1201

To remove roof lining, front and rear seats, trim board and carpet

120.00 ✓

To remove and renew exhaust silencer box (rear & centre)

100 ✓  
120.00 7✓

To putty and spray replaced parts

2,400.00 18001

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

2,800.00 20001

Total : S\$49,765.80

Singapore Dollars Forty Nine Thousand Seven Hundred and Sixty Five and Cents Eighty Only

P 38881.80

SN 272.50

L 4300.00

43454.30

8690.86

34763.44

MAX Repair  
4/5mm 24,000.00  
↑  
KENNETH PUS  
CUSHEN 1ks.  
4/5mm 34750.00




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD			Ref : CS/UOI19011674/Kqd3e2	
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Date : 16-08-2019	
			Code : UOI2	
<b>1. Policy Particulars :- OWN DAMAGE</b>				
Insured Veh.			Veh. Inspected	SKA 6656H
Policy No.	DHOM120013851501		Coverage (\$)	0.00
Claim No.	M12D10881907		Excess (\$)	750.00
Assign From	JENNY LEW		Assign Date	02/07/2019
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES BENZ E 200CGI (A)	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	WDD2120482A074840	Colour	METALLIC BLACK	
Odometer	153582	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	245/40Z R18	MICHELIN	4 mm	
L/H Front Tyre	245/40Z R18	MICHELIN	4 mm	
R/H Rear Tyre	265/35Z R18	MICHELIN	5 mm	
L/H Rear Tyre	265/35Z R18	MICHELIN	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	24/06/2019		Inspection Date	02/07/2019
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
<b>5a. Remarks</b>				
A)THE MARKET VALUE IS S\$85,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			24 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 6656H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER FASCIA (AMG PACK)	BUCKLED	2,038.00	2,038.00
1	FRONT BUMPER TOW COVER	MISSING	95.00	95.00
1	FRONT NO. PLATE GARNISH	CRACKED	179.00	179.00
1	FRONT BUMPER SPONGE	SERVICEABLE	95.00	-
2	FRONT BUMPER SIDE SPONGE @\$93.00	SERVICEABLE	186.00	-
2	FRONT BUMPER PARKING SENSOR @\$307.00	SERVICEABLE	614.00	-
1	FRONT BUMPER REINFORCEMENT	BENT	917.00	917.00
1	FRONT BUMPER LOWER GRILLE	CRACKED	143.00	143.00
1	RADIATOR GRILLE (AMG PACK)	CRACKED	1,420.00	1,420.00
1	RADIATOR TOP COVER	CRACKED	161.00	161.00
2	FRONT SEAT HEAD REST @\$1127.00	SERVICEABLE	2,254.00	-
2	FRONT SEAT SAFETY BELT @\$1621.00	JAMMED	3,242.00	3,242.00
2	REAR SEAT SAFETY BELT @\$659.00	JAMMED	1,318.00	1,318.00
2	HEADLAMP ASSY @\$1400.00	MTG CRACKED	2,800.00	2,800.00
1	REAR WINDSCREEN GLASS	CUT	1,517.00	1,517.00
1	REAR N/S FENDER	BUCKLED	2,545.00	2,545.00
1	REAR N/S FENDER AIR DUCT	CRACKED	30.00	30.00
2	REAR FENDER TOP GARNISH @\$72.00	CRACKED	144.00	144.00
4	REAR FENDER TOP GARNISH CLIP @\$4.00	NECESSARY	16.00	16.00
1	REAR N/S FENDER INNER SHIELD	SERVICEABLE	220.00	-
1	RR N/S FENDER SHIELD COVER	SERVICEABLE	38.00	-
1	REAR N/S FENDER INNER TRIM	CRACKED	386.00	386.00
1	BOOT LID	BENT	3,134.00	3,134.00
1	BOOT LID INNER LOCK	JAMMED	572.00	572.00
2	BOOT LID HINGE @\$210.00	BENT	420.00	420.00
2	BOOT LID HINGE COVER @\$29.00	DENTED	58.00	58.00
1	BOOT LID LOCK HOOK	BENT	518.00	518.00
1	BOOT LID INNER TRIM	DEFORMED	220.00	220.00
2	BOOT LID STOPPER @\$18.00	SERVICEABLE	36.00	-
1	BOOT LID OUTER CHROME	BENT	161.00	161.00
1	BOOT LID OPEN HANDLE	DENTED	330.00	330.00
2	BOOT LID LICENSE PLATE LAMP @\$32.00	SERVICEABLE	64.00	-

Report Ref No. CS/UOI19011674/Kqd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199007198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	BOOT LID LAMP @\$580.00	O/S MTG CRACKED / N/S BROKEN	1,160.00	1,160.00
1	BOOT LID E200 EMBLEM	NECESSARY	91.00	91.00
1	BOOT LID STAR LOGO	NECESSARY	53.00	53.00
3	BOOT LID STAR LOGO RIVET @\$3.00	NECESSARY	9.00	9.00
1	BOOT LID AMG EMBLEM	NECESSARY	216.00	216.00
1	BOOT LID BREAK DOWN SIGN	CRACKED	211.00	211.00
1	BREAK DOWN SIGN HOLDER	CRACKED	35.00	35.00
1	REAR BUMPER FASCIA (AMG)	BENT	2,175.00	2,175.00
1	REAR BUMPER LOWER SPOILER	CRACKED	624.00	624.00
1	REAR BUMPER REINFORCEMENT	BENT	917.00	917.00
2	RR BUMPER REINFORCEMENT PLATE @\$40.00	DISTORTED	80.00	80.00
2	REAR BUMPER SIDE RETAINER @\$45.00	CRACKED	90.00	90.00
2	REAR BUMPER LOWER BRACKET @\$82.00	BENT	164.00	164.00
2	REAR BUMPER EXHAUST PIPE SEAL @\$275.00	MISSING	550.00	550.00
4	REAR BUMPER PARKING SENSOR @\$307.00	SHORTED	1,228.00	1,228.00
4	RR BUMPER PARKING SENSOR SEAL @\$11.00	NECESSARY	44.00	44.00
1	RR BUMPER PARKING SENSOR WIRE	CUT	230.00	230.00
2	TAILLAMP @\$794.00	N/S BROKEN / O/S MTG CRACKED	1,588.00	1,588.00
2	TAILLAMP LOWER BRACKET @\$82.00	DISTORTED	164.00	164.00
1	TAILLAMP INNER PANEL	BENT	1,824.00	1,824.00
1	END PANEL	BENT	1,421.00	1,421.00
1	END PANEL TOP GARNISH	CRACKED	145.00	145.00
1	REAR N/S MEMBER	BENT	704.00	704.00
1	REAR O/S TOP SIDE PANEL	BENT	473.00	473.00
1	REAR O/S LOWER SIDE PANEL	BENT	704.00	704.00
1	REAR N/S SIDE PANEL	DISTORTED	473.00	473.00
1	REAR SPARE TYRE TRAY	CRACKED	325.00	325.00
1	REAR O/S SIDE TRAY	SERVICEABLE	37.00	-
1	REAR N/S SIDE TRAY	SERVICEABLE	46.00	-
1	REAR SPARE TYRE TRAY GRUM	NECESSARY	260.00	260.00
1	SPARE TYRE TRAY INNER PANEL	BENT	749.00	749.00
2	REAR EXHAUST SILENCER BOX @\$1833.00	BENT	3,666.00	3,666.00
2	REAR EXHAUST BOX MOUNTING @\$16.00	SERVICEABLE	32.00	-
2	REAR EXHAUST BOX BRACKET @\$80.00	BENT	160.00	160.00

Report Ref No. CS/UOI19011674/Kqd3e2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR EXHAUST BOX COUPLING @\$22.00	SERVICEABLE	44.00	-
1	CENTRE EXHAUST CONVERTOR	SERVICEABLE	1,232.00	-
1	REAR EXHAUST TOP HEAT SEAL	BENT	127.00	127.00
1	REAR N/S HEAT SEAL	SERVICEABLE	97.00	-
1	REAR N/S HEAT SEAL (INNER)	SERVICEABLE	131.00	-
1	REAR N/S HEAT SEAL (INNER FRT)	SERVICEABLE	49.00	-
1	REAR O/S HEAT SEAL (TOP INNER)	SERVICEABLE	97.00	-
1	REAR EXHAUST HEAT SEAT LOWER	DENTED	81.00	81.00
	LESS 10% DISCOUNT		-4,837.70	-4,310.50
			43,539.30	38,794.50
1	BOOT LID RUBBER (50%) (SN)	DISTORTED / DENTED	285.00	142.50
	LESS 10% DISCOUNT		-28.50	-
			256.50	142.50
	<b>SPECIAL NETT ITEMS</b>			
1	FRONT NO. PLATE WITH BOX (SN)	DENTED	50.00	45.00
1	REAR NO. PLATE WITH BOX (SN)	MISSING	50.00	45.00
1	REAR W/S GLASS SEALANT (SN)	NECESSARY	60.00	40.00
			160.00	130.00
	<b>LABOUR</b>			
	TO TOWING.		100.00	100.00
	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM.		120.00	60.00
	TO REMOVE & RENEW REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		150.00	120.00
	TO REMOVE ROOF LINING, FRONT AND REAR SEATS, TRIM BOARD AND CARPET.		120.00	120.00
	TO REMOVE AND RENEW EXHAUST SILENCER BOX (REAR & CENTRE).		120.00	100.00
	TO PUTTY AND SPRAY REPLACED PARTS.		2,400.00	1,800.00
	TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS.		2,800.00	2,000.00
			5,810.00	4,300.00
	<b>GRAND TOTAL</b>		<b>49,765.80</b>	<b>43,367.00</b>

Report Ref No. CS/UOI19011674/Kqd3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			24,000.00
LESS EXCESS			-750.00
NETT LIABILITY			23,250.00

Report Ref No. CS/UOI19011674/Kqd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.