



Labour

No.	Labour Description	Price (SGD)	
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair /replacement parts.	\$ 1,200.00	400
2	Carry out spray painting on affected area, FRT BUMPER, FRT FENDER LH, FRT DOOR LH, RR DOOR LH, LH ROCKER PANEL	\$ 1,600.00	800
3	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 120.00	30
4	To remove and replace LHF under carriage parts	\$ 300.00	+
5	To conduct 4 wheel alignment	\$ 160.00	80
6	To remove and replace dashboard system and internal wiring	\$ 500.00	+
7	To conduct transfer front door mechanism to new door panel	\$ 200.00	80

1390

Labour Total : \$ 4,080.00

Others

No.	Other Description	Price (SGD)	
1	FRT TYRE LH <i>new</i>	\$ 300.00	+

Other Total: 300.00

TOTAL: 18,579.75

GST ( 7%): 1,300.58

GRAND TOTAL : 19,880.33

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor  
Kelvin Chew  
HP: 8292 5595 Fax: 68445185

*Adrian Ling*  
*P/B 01/07/19.*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*05 Dup.*  
*total: 5605.40*