

INS CASE OWNER: KWEE MAY | CC 6 / AXA140 21916 | <sup>MLG n352-1</sup> 1/11/14 | <sup>3.2</sup> LKK: IDAC:

**ASSIGNMENT**

Surveyor: MA DOI: 20/11/14 Assg Date: 20/11/14

Pre-assign / CCU / FTE




Insured Vehicle No.: SKN 2887R Claim No.: C0322959  
 Name of Insured: Goh Kim Tuan Policy No.: VPA/PI510974  
 Insured Tel No.: \_\_\_\_\_ HP: \_\_\_\_\_ Make / Model: Volkswagen  
 Excess Sec II : SS D.O.A: 16/11/14 Place of Accident: Bedok South Rd Towards Upper East Coast Rd

Is driver the owner? ( YES / NO ) Nature of Accident: \_\_\_\_\_  
 If NO, Driver Name / Age: Yong Lai Eng OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO  
 Driver Tel No.: 9640 9670 (V/L: YES / NO Insured Liability : % Final ? Yes / No



SG77992X  
 INSRs: \_\_\_\_\_  
 WSP: EM-1  
 Tel: \_\_\_\_\_  
 Liability: \_\_\_\_\_  
 RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
 WSP: \_\_\_\_\_  
 Tel: \_\_\_\_\_  
 Liability: \_\_\_\_\_  
 RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
 WSP: \_\_\_\_\_  
 Tel: \_\_\_\_\_  
 Liability: \_\_\_\_\_  
 RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
 WSP: \_\_\_\_\_  
 Tel: \_\_\_\_\_  
 Liability: \_\_\_\_\_  
 RMKS: \_\_\_\_\_

Date/ Time	FOR CSO ONLY:	STAGE	DATE / PIC
11/12/14	Is driver the owner? ( YES / NO )	Finalisation:	
Vic	If NO, Driver Name / Age :	Email AIG for OI GIA:	
	Driver's Own Vehicle Number: _____ Insurance Company: _____	Apt letter to OI:	
	<u>SG77992X - X</u>	Call OI:	<u>05/12/14 - VIC</u>
	<u>SKN 2887R - CS/AXA402(846/RV6; DOA: 16/11/14</u>	After call ltr to OI:	<u>1/12/14</u>
	<u>-CC6/AXA1401708/M1r3; DOA: 18/10/14</u>	Type Report:	
02/12/14 5:24PM	SPOKE TO OI. CONFIRMED ACCIDENT DETAILS & WAS TURNING OUT FROM MINOR ROAD.	Prepare Invoice:	
	INFORMED TP CLAIM & NCD ISSUES. OI SAID TO CALL OI (HUSBAND) TO DISCUSS FURTHER.	Others:	
	<b>SMALL LIABILITY CLERE</b>	Documentation Check List:	Handler Typist
02/12/14	OI CALLED IN. INFORMED TP CLAIM. ADVISED TO VEHICLE & Awaiting NCD ISSUES.	OI Apt Ltr:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	<b>FINALISED.</b>	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
25/01/16	SEND PR TO AXA	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	TYPE REPORT WHAT.	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	PENDING TP LOD. REPORT DONE.	Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
25/02/16	TP LOD N.	LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
01/08/16	TYPE REPORT FOR WARRANTY EXTENSION.	Medical Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
06/12/16	RECEIVE WARRANTY VIA EMAIL.	Approval Email:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	TO RESPOND ON AXA'S QUERY.	Payment Breakdown Form:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	29-3-17 LIABILITY IS DOWN, TRY TO SPEED UP, ALSO DONOT DELAY IN RESPONSE TO AXA'S 2ND QUERY DATED 21-12-16	Others:	<input checked="" type="checkbox"/> <input type="checkbox"/>
18/05/17	AXA PROPOSED TO CLOSE FILE & SUBMIT REPORT.		
05-10-17	SINCE AXA INSTRUCTED TO CLOSE PLEASE DO IT ASAP IN ORDER TO CLOSE FILE!		

<b>FINAL SETTLEMENT</b>	Date: <u>8/7/19</u>	Confirm with <u>MR CHIA</u>	(LOW MARKING & RENT 1000)
Repair Cost: (w/gar)	SS 25,145.00	Final Liability	100 % (Agreed / Assessed)
Loss of Rental:	SS 1,600.00 ( 16 days) X @ 100.00	BOLA S/N No. :	9
Loss of Use:	SS - ( \$ x days)	If NO or B 28, Ass. Lia :	
Disbursement:	SS -	Format Type :	<u>WP REPORT TP</u>
Total:	SS 26,745.00	Global Sum: SS	21000 -> <u>Bm-1 Auto CND SETTLEMENT</u>

- SUBMIT SURVEY REPORT. AXA PROPOSED TO TOUR. CLOSE CASE DUE TO INACTIVITY. 9/7/19

INS CASE OWNER: Kwee May CC 6 / AXA140 21916 / M16 / 302 LKK: IDAC:

**ASSIGNMENT**

Surveyor: MA DOI: 20/11/14 Assg Date: 20/11/14

Pre-assign / CCU / FTE



Insured Vehicle No.: SKN 2887R Claim No.: C0322959  
 Name of Insured: Goh Kim Tuan Policy No.: VPA/PIS/0974  
 Insured Tel No.: \_\_\_\_\_ HP: \_\_\_\_\_ Make / Model: Volkswagen  
 Excess Sec II :SS \_\_\_\_\_ D.O.A: 16/11/14 Place of Accident: Bedok South Rd Towards Upper East Coast Rd  
 Is driver the owner? ( YES / NO ) Nature of Accident: \_\_\_\_\_  
 If NO, Driver Name / Age: Hong Lai Eng OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO  
 Driver Tel No.: 9640 9670 (V/L: YES / NO Insured Liability : % Final ? Yes / No



SGZ 2992X  
 INSRs: \_\_\_\_\_ WSP: \_\_\_\_\_ Tel: \_\_\_\_\_ Liability: \_\_\_\_\_ RMKS: \_\_\_\_\_  
 INSRs: \_\_\_\_\_ WSP: \_\_\_\_\_ Tel: \_\_\_\_\_ Liability: \_\_\_\_\_ RMKS: \_\_\_\_\_  
 INSRs: \_\_\_\_\_ WSP: \_\_\_\_\_ Tel: \_\_\_\_\_ Liability: \_\_\_\_\_ RMKS: \_\_\_\_\_  
 INSRs: \_\_\_\_\_ WSP: \_\_\_\_\_ Tel: \_\_\_\_\_ Liability: \_\_\_\_\_ RMKS: \_\_\_\_\_

Date/ Time	FOR CSO ONLY:	STAGE	DATE / PIC
11/12/14	Is driver the owner? ( YES / NO )	Finalisation:	
Vic	If NO, Driver Name / Age :	Email AIG for OI GIA:	
	Driver's Own Vehicle Number: _____ Insurance Company: _____	Apt letter to OI:	
	<u>SGZ 2992X - X</u>	Call OI:	<u>03/12/14 - VIC</u>
	<u>SKN 2887R - CS/AXA14021846/RV6; DVA: 16/11/14</u>	After call ltr to OI:	<u>WSP 30/11</u>
	<u>-CC6/AXA14011708/M1113; DOB: 18/06/14</u>	Type Report:	
	Prepare Invoice:	Others:	
03/12/14 5:24PM	SPOKE TO OI. COMMENTED ACCIDENT DETAILS & WAS TURNING OUT FROM MINOR ROAD. INFORMED TP CLAIM & NCD ISSUES. OI SAID TO CALL OI (HUSBAND) TO DISCUSS FURTHER.	Documentation Check List:	Handler Typist
	<u>BUSIAL LIABILITY CLEAR</u>	OI Apt Ltr:	<input checked="" type="checkbox"/> <input type="checkbox"/>
09:50PM	OI CALLED IN. INFORMED TP CLAIM. AGREED TO SETTLE & AWAITS NCD ISSUES.	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	<u>FINALISED.</u>	Release Voucher:	<input type="checkbox"/> <input type="checkbox"/>
25/01/14	SEND PR TO AXA	Final Repair Bill:	<input type="checkbox"/> <input type="checkbox"/>
	TYPE REPORT FIRST.	Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	PENDING TP LOD. REPORT DONE.	LTA / GIA :	<input type="checkbox"/> <input type="checkbox"/>
25/02/14	TP LOD IN.	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
01/08/16	TYPE REPORT FOR WANDKRE APPROVAL.	Approval Email:	<input type="checkbox"/> <input type="checkbox"/>
06/12/16	OBSC WANDKRE VIA EMAIL.	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	TO RESPOND ON AXA'S QUERY.	Others:	<input type="checkbox"/> <input type="checkbox"/>
29-3-17	LIABILITY IS DOWN. TRY TO SPEED UP. ALSO DONOT DELAY IN RESPONSE TO AXA'S 2ND QUERY DATED 21-12-16		SWAY PHOTO = YES REPAIRMENT " = YES OTHER REPAIR " = YES
18/05/17	AXA PROPOSED TO CLOSE FILE & SUBMIT REPORT.		
05-10-17	SINCE AXA INSTRUCTED TO CLOSE PLEASE DO IT ASAP IN ORDER TO CLOSE FILE.		

FINAL SETTLEMENT	Date:	Confirm with MR CHIA	(NO MAKING A RIGHT TURN)
Repair Cost: (w/gst)	SS 25,145.00	Final Liability 100 % (Agreed / Assessed)	BOLA S/N No.: 9
Loss of Rental:	SS 1,600.00 ( 16 days) X @ 100.00		If NO or B 28, Ass. Lia :
Loss of Use:	SS - ( \$ x days)	Format Type: <u>WP REPORT</u>	
Disbursement:	SS -		<u>\$280.00</u>
Total:	SS 26,745.00	Global Sum: SS	(NO SETTLEMENT)

- SUBMIT SURVEY REPORT. AXA PROPOSED TO TEMP. CLOSE CASE DUE TO INACTIVITY.



VIC 235007z  
16w/1day S (on h):

# EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C  
#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopte ltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Page 1 of 4

TPL/AXA

## ESTIMATE

SGZ 7992 X

Volkswagen Passat

QTY	DESCRIPTION	REMARKS	UNIT PRICE	TOTAL
✓ 1pc	Bonnet	bt	\$ 1396	
✓ 2pc	Bonnet Inner Rubber	@46 HR	\$ 92	
✗ 1pc	Bonnet Upper Lock		\$ 112	✗
1pc	Bonnet Bottom Lock	LA ?	\$ 170	
✓ 1set	Bonnet Insulator Clip	new	\$ 40	
✓ 1pc	Front Bumper	det	\$ 1350	
✓ 2pc	Front Bumper Side Retainer	@55 dis	\$ 116	
✓ 2pc	Front Bumper Attachment Retainer	@55 dis	\$ 116	
✓ 1set	Front Bumper Clip	new	\$ 50	
1pc	Front Bumper Reinforcement	bt ?	\$ 589	
1pc	Front Bumper Lower Reinforcement	bt ?	\$ 229	
1pc	Front Bumper sponge	tovh ?	\$ 136	
✓ 1pc	Front Bumper Lower Grille	dis	\$ 248	
✓ 1pc	Front Bumper Lower Grille Outer Chrome Moulding	dis	\$ 355	
✓ 1pc	Front Bumper No-Plate Base Garnish	det	\$ 72	
1pc	2pc Front Bumper Signal Lamp	OS crn @145	\$ 290	145 NSPC
1pc	2pc Front Bumper Signal Lamp Base Garnish	OS det @85	\$ 170	85 NSPC
2pc	Front Bumper Fog Lamp	@380 OS NS X	\$ 760	280 NSPC
1pc	2pc Front Bumper Fog Lamp Cover	@130 OS det NS	\$ 260	130 NSPC
1pc	2pc Front Bumper Fog Lamp Cover Top Garnish	OS det @120 NS	\$ 240	60 NSPC
✓ 1pc	Front Bumper Lower skirt		\$ 190	dis
✓ 1set	Front Bumper Lower skirt clip		\$ 30	new
3pc	4pc Front Bumper sensor	@30	\$ 120	723 photo
✓ 4pc	Front Bumper sensor Holder	@35	\$ 140	new
			\$	

145 NSPC  
85 NSPC  
280 NSPC  
130 NSPC  
60 NSPC  
dis  
new  
723 photo  
new  
6854

Handwritten notes on the left margin, including checkmarks and some illegible text.

# EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C  
#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Page 2 of 4

TARA

## ESTIMATE

SG27992 X

Volkswagen Passat

✓	1pc	Front Grille	119 ✓	\$ 593	
✓	1pc	Front Grille Badge	112 ✓	\$ 125	
✓	1pc	Front Grille Outer Chrome Pad	112 ✓	\$ 650	
✓	1set	Front Grille Clip	112 ✓	\$ 30	
NS? ✓	OS ✓	Head Lamp	OS swan KIS ? @685 ✓	\$ 1370 ✓	ova
✓	2pc	Head Lamp Bottom Retainer	@45 ✓	\$ 90	dis
✓	2set	Head Lamp Clip	@20 ✓	\$ 40	112
✓	2pc	Front Fender Inner shield	OS diff @133 ✓	\$ 266	133 112
✓	2set	Front Fender Inner shield clip	@30 ✓	\$ 60	112
?	1pc	Support Panel Assy	?	\$ 1007 ✓	ova
?	1set	Horn	?	\$ 210 ✓	ova
?	1pc	Wiper Tank	?	\$ 136 ✓	dis
?	1pc	Wiper Tank Motor	?	\$ 130 ✓	ova
?	1pc	Radiator	?	\$ 720 X	ova
?	2pc	Radiator Top Mounting	@35 ?	\$ 70 ✓	112
?	2pc	Radiator Top Mounting Bracket	@35 ?	\$ 70 ✓	112
?	1pc	Air Con Condenser	?	\$ 890 ✓	bt
X	1pc	Condenser Air Con Pipe	X	\$ 670	ova
X	1pc	Condenser Suction Pipe	X	\$ 670	ova
X	1pc	Condenser Discharge Pipe	X	\$ 495	ova
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	

6323



# EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C  
#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Page 4

T/P/ AMT

## ESTIMATE

SGZ 7992 X

	Special Note		kelulusan Pasir
1pc	Front w/screen Sealant	\$ 60	40 N/A
1pc	ERP Bracket	\$ 15	N/A
1pc	Front M. Plate w/coiler	\$ 70	40 N/A
1pc	Radiator Coolant	\$ 40	N/A
		\$	135
	Hot Air Gun	\$	
	L/S Repair	\$	
	After Paints photo	\$	
	10 w/days	\$	
	20 w/days	\$	
	Labour	\$	
	CKC AUTO (M)	\$	
1	Panel Beating	\$ 4600	10000
2	Spray Painting	\$ 1200	41000
3	Anti Rust	\$ 400	40
4	Check Wiring	\$ 50	30
5	Tuning Fee	\$ 70	960
6	Remove and Install Front w/screen	\$ 440	120
7	Remove and Install Carpet and Seat	\$ 150	80
8	Remove and Install Air Con	\$ 150	120
9	Remove and Install Dash Board	\$ 450	280
10	Reset and Reprogram SRS unit Assy	\$ 480	280
11	Check and Ret Air Bag Friction	\$ 250	150
		\$	
		\$ 35,023.40	
		\$	
		\$	4060

23500 / 2  
16 w/days

31481.40  
- 20%  
25185.12



# EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

M/S AXA Insurance Singapore Pte Ltd  
Motor Claim Department  
8 Shenton Way  
#27-01 AXA Tower  
Singapore 068811

Proforma Invoice : 16/PI00027/3745TP

Date : 25-Feb-2016

Tel No : 68412928  
Attn : Miss Jas

Fax No : 67414108

Date of Accident : 16-Nov-2014  
Our Client's Vehicle Number : SGZ 7992X  
Vehicle Make / Model : VOLKSWAGEN PASSAT  
Our Client / Owner Name : SRI HANIATI BINTE SALLIM

NO.	DESCRIPTION	AMOUNT ( SGD )
1	Lump Sum Repair Cost ( Recommended by LKK Mr Ma)	23,500.00 SR
2	Loss of Rental ( 16 days x \$ 200)	3,200.00 ES
	----- Last Item -----	
	<b>SUB-TOTAL (at this time)</b>	<b>26,700.00</b>
	Subject to 7% GST	1,645.00

**GRAND TOTAL**  
**(at this time)**

**SGD 28,345.00**

SGD ( Twenty-Eight Thousand Three Hundred Forty-Five only )



Authorised Signature and Company Stamp



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC6/AXA14021916/M1ga3s2-1

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN: SASHE

Date : 10-07-2019



Code : AXA2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKN 2887R	Veh. Inspected	SGZ 7992X
Policy No.	VPA/P1510974	Coverage (\$)	0.00
Claim No.	C0322959MC/FA	Excess (\$)	0.00
Assign From		Assign Date	20/11/2014

## 2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN (A)	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	WWWZZZ3CZ7P159711	Colour	BLACK
Odometer	173712	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55R16	TOYO	8 mm
L/H Front Tyre	215/55R16	TOYO	8 mm
R/H Rear Tyre	215/55R16	TOYO	8 mm
L/H Rear Tyre	215/55R16	TOYO	8 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	16/11/2014	Inspection Date	20/11/2014
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **16 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGZ 7992X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BONNET (CONSISTENT)	BENT	1,396.00	1,396.00
2	BONNET INNER RUBBER @ \$46.00 (CONSISTENT)	NECESSARY	92.00	92.00
1	BONNET UPPER LOCK (CONSISTENT)	BENT	112.00	112.00
1	BONNET BOTTOM LOCK (CONSISTENT)	BENT	170.00	170.00
1	SET BONNET INSULATOR CLIP (CONSISTENT)	NECESSARY	40.00	40.00
1	FRONT BUMPER (CONSISTENT)	DEFORMED	1,350.00	1,350.00
2	FRONT BUMPER SIDE RETAINER @ \$58.00 (CONSISTENT)	DISTORTED	116.00	116.00
2	FRONT BUMPER ATTACHMENT RETAINER @ \$58.00 (CONSISTENT)	DISTORTED	116.00	116.00
1	SET FRONT BUMPER CLIP (CONSISTENT)	NECESSARY	50.00	50.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	BENT	589.00	589.00
1	FRONT BUMPER LOWER REINFORCEMENT (CONSISTENT)	BENT	229.00	229.00
1	FRONT BUMPER SPONGE (CONSISTENT)	TORN	136.00	136.00
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	DISTORTED	248.00	248.00
1	FRONT BUMPER LOWER GRILLE OUTER CHROME MOULDING (CONSISTENT)	DISTORTED	355.00	355.00
1	FRONT BUMPER NO. PLATE BOX GARNISH (CONSISTENT)	DEFORMED	72.00	72.00
2	FRONT BUMPER SIGNAL LAMP @ \$145.00 (CONSISTENT)	O/S CRACKED / N/S SERVICEABLE	290.00	145.00
2	FRONT BUMPER SIGNAL LAMP BASE GARNISH @ \$85.00 (CONSISTENT)	O/S DISTORTED / N/S SERVICEABLE	170.00	85.00
2	FRONT BUMPER FOG LAMP @ \$280.00 (CONSISTENT)	O/S CRACKED / N/S SERVICEABLE	560.00	280.00
2	FRONT BUMPER FOG LAMP COVER @ \$130.00 (CONSISTENT)	O/S DISTORTED / N/S SERVICEABLE	260.00	130.00
2	FRONT BUMPER FOG LAMP COVER TOP GARNISH @ \$60.00 (CONSISTENT)	O/S DISTORTED / N/S SERVICEABLE	120.00	60.00
1	FRONT BUMPER LOWER SKIRT (CONSISTENT)	DISTORTED	190.00	190.00
1	SET FRONT BUMPER LOWER SKIRT CLIP (CONSISTENT)	NECESSARY	30.00	30.00
4	FRONT BUMPER SENSOR @ \$241.00 (CONSISTENT)	SHORTED 3PCS ONLY	964.00	723.00

Report Ref No. CC6/AXA14021916/M1ga3s2-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
4	FRONT BUMPER SENSOR HOLDER @ \$35.00 (CONSISTENT)	NECESSARY	140.00	140.00
1	FRONT GRILLE (CONSISTENT)	DISTORTED	592.00	592.00
1	FRONT GRILLE BADGE (CONSISTENT)	NECESSARY	125.00	125.00
1	FRONT GRILLE OUTER CHROME PAD (CONSISTENT)	NECESSARY	650.00	650.00
1	SET FRONT GRILLE CLIP (CONSISTENT)	NECESSARY	30.00	30.00
2	HEAD LAMP @ \$685.00 (CONSISTENT)	O/S GRAZED / N/S CRACKED	1,370.00	1,370.00
2	HEAD LAMP BOTTOM RETAINER @ \$45.00 (CONSISTENT)	DISTORTED	90.00	90.00
2	SET HEAD LAMP CLIP @ \$20.00 (CONSISTENT)	NECESSARY	40.00	40.00
2	FRONT FENDER INNER SHIELD @ \$133.00 (CONSISTENT)	O/S DISTORTED / N/S SERVICEABLE	266.00	133.00
2	SET FRONT FENDER INNER SHIELD CLIP @ \$30.00 (CONSISTENT)	NECESSARY	60.00	60.00
1	SUPPORT PANEL ASSY (CONSISTENT)	CRACKED	1,007.00	1,007.00
1	SET HORN (CONSISTENT)	CRACKED	210.00	210.00
1	WIPER TANK (CONSISTENT)	DISTORTED	136.00	136.00
1	WIPER TANK MOTOR (CONSISTENT)	CRACKED	130.00	130.00
1	RADIATOR (CONSISTENT)	SERVICEABLE	720.00	-
2	RADIATOR TOP MOUNTING @ \$35.00 (CONSISTENT)	NECESSARY	70.00	70.00
2	RADIATOR TOP MOUNTING BRACKET @ \$35.00 (CONSISTENT)	NECESSARY	70.00	70.00
1	AIR CON CONDENSER (CONSISTENT)	BENT	890.00	890.00
1	CONDENSER AIR CON PIPE (CONSISTENT)	SERVICEABLE	670.00	-
1	CONDENSER SUCTION PIPE (CONSISTENT)	SERVICEABLE	670.00	-
1	CONDENSER DISCHARGE PIPE (CONSISTENT)	SERVICEABLE	498.00	-
1	FRONT W/SCREEN (CONSISTENT) }	CRACKED	796.50	796.50
1	SET FRONT W/SCREEN MOULDING (CONSISTENT) }		-	-
1	FRONT W/SCREEN INNER SEAL (CONSISTENT)	NECESSARY	50.00	50.00
2	AIR BAG IMPACT SENSOR @ \$325.00 (CONSISTENT)	ACTIVATED	650.00	650.00
1	FRONT DRIVER AIR BAG (CONSISTENT) }	ACTIVATED	2,535.00	2,535.00
1	FRONT DRIVER AIR BAG COVER (CONSISTENT) }		-	-
1	FRONT PASSENGER AIR BAG (CONSISTENT)	ACTIVATED	2,922.90	2,922.90
1	DASH BOARD (CONSISTENT)	CUT	4,475.00	4,475.00

Report Ref No. CC6/AXA14021916/M1ga3s2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SRS UNIT ASSY (CONSISTENT)	ACTIVATED	1,130.00	1,130.00
2	FRONT SEAT BELT @ \$580.00 (CONSISTENT)	JAMMED	1,160.00	1,160.00
1	STEERING ANGER SENSOR (ADDITIONAL) (CONSISTENT)	SERVICEABLE	390.00	-
			30,198.40	26,176.40
	<b>SPECIAL NETT ITEMS</b>			
1	FRONT W/SCEEN SEALANT (SN) (CONSISTENT)	NECESSARY	60.00	40.00
1	ERP BRACKET (SN) (CONSISTENT)	NECESSARY	15.00	15.00
1	FRONT NO. PLATE W/COVER (SN) (CONSISTENT)	NECESSARY	70.00	40.00
1	RADIATOR COOLANT (SN) (CONSISTENT)	NECESSARY	40.00	40.00
			185.00	135.00
	<b>LABOUR</b>			
	PANEL BEATING.		1,600.00	1,000.00
	SPRAY PAINTING.		1,200.00	1,000.00
	ANTI RUST.		100.00	40.00
	CHECK WIRING.		50.00	30.00
	TOWING FEE.		70.00	60.00
	REMOVE AND INSTALL FRONT W/SCREEN.		140.00	120.00
	REMOVE AND INSTALL CARPET AND SEAT.		150.00	80.00
	REMOVE AND INSTALL AIR CON.		150.00	120.00
	REMOVE AND INSTALL DASH BOARD.		450.00	280.00
	RESET AND REPROGRAM SRS UNIT ASSY.		480.00	280.00
	CHECK AND RESET AIR BAG FUNCTION.		250.00	150.00
			4,640.00	3,160.00
	<b>GRAND TOTAL</b>		<b>35,023.40</b>	<b>29,471.40</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>23,500.00</b>

Report Ref No. CC6/AXA14021916/M1ga3s2-1

MA CHIN FOOK

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.