

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06004

Vehicle Insured : SLQ9262U
Accident Date : 27-Jun-2019

Date : 28-Jun-2019

Our Ref : 219101 (CHINA) / CHAN

PAGE : 1

RAJAN RAJGOPAL
237 ARCADIA ROAD
#08-07
Singapore 289844

Not Authorized
11 Sep @ ?
Resurvey After Paint

7-9 days

ESTIMATED COST OF REPAIR FOR BMWX3 XDRIVE 20I SKL7348H

1 pc	Bonnet		<i>Bu</i> 1,884.70	✓
1 pc	Bonnet logo		<i>nd</i> 106.75	✓
1 pc	Front bumper fascia		<i>Bu</i> 1,400.40	✓
1 pc	Front bumper no.plate garnish		<i>nd</i> 89.25	✓
2 pcs	Front bumper chrome grille	@ S\$145.65	291.30	?
1 pc	Front bumper centre grille		69.90	?
1 pc	Front bumper lower garnish		<i>CM</i> 196.90	✓
1 pc	Front bumper tow cover		<i>CM</i> 39.80	✓
2 pcs	Front bumper parking sensor	@ S\$251.60	503.20	?
2 pcs	Parking sensor holder	@ S\$ 19.00	38.00	?
1 pc	Front bumper lower garnish		72.30	?
1 pc	Front bumper lower grille		136.90	?
2 pcs	Front bumper nozzle cover	@ S\$ 39.80	<i>Sm</i> 79.60	X
2 pcs	Front bumper nozzle	@ S\$176.50	353.00	?
2 pcs	Headlamp	@ \$2977.45	5,954.90	✓
2 pcs	Headlamp lower bracket	@ S\$204.80	409.60	?
1 pc	Front air intake cowling		471.00	?
1 pc	Front bumper reinforcement		697.10	?
1 pc	Front bumper sponge		126.70	?
2 pcs	Front seat headrest assy	@ S\$756.40	1,512.80	?
1 pc	Tail gate		<i>Bu</i> 1,952.40	✓
1 pc	Tail gate glass inner seal		<i>nd</i> 107.60	✓
1 pc	Tail gate BMW logo		<i>nd</i> 76.60	✓
1 pc	Tail gate "X3" emblem		<i>nd</i> 69.70	✓
1 pc	Rear bumper fascia		<i>Bu</i> 1,530.20	✓
1 pc	Rear centre pad		<i>nd</i> 322.40	✓
2 pcs	Rear bumper tow cover	@ S\$ 36.60	73.20	✓
1 pc	Rear bumper centre garnish		183.40	?

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLQ9262U

Page : 2

4 pcs Rear bumper parking sensor	@ S\$288.20	1,152.80	?
2 pcs Rear parking sensor o ring	@ S\$ 12.00	24.00	?
2 pcs Rear bumper reflector	@ S\$114.70	229.40	X
1 pc Rear bumper under cover		190.80	?
1 pc Rear bumper reinforcement		596.60	?
1 pc Rear bumper sponge		123.90	?
1 pc Rear bumper inner parts		175.00	?
2 pcs Rear reinforcement bracket	@ S\$125.00	250.00	?
1 pc Rear end panel		597.10	?
1 pc Rear spare tyre panel		1,790.80	X
1 pc Rear exhaust chrome pipe		176.60	✓

		24,056.60	
Less 10% :		2,405.66	

1 pc Front no.plate with box		21,650.94	453m
1 pc Rear w/s glass sealant		50.00	sn
1 pc Rear no.plate with box		60.00	sn 403m
		50.00	sn X
To rewire damaged parts and refocus headlamp beam.		120.00	401
To remove & refix rear windscreen glass and conduct water leak test.		150.00	120
To remove roof lining, front and rear seats, trim board and carpet		120.00	801
To apply undersealing		100.00	601
To remove and refix exhaust silencer box		100.00	?
To putty and spray replaced parts		1,800.00	11001
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts		2,200.00	?

Total :		S\$26,400.94	
		=====	

Singapore Dollars Twenty Six Thousand Four Hundred and Cents Ninety Four Only