

Kd

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06004

Vehicle Insured : SLQ9262U
Accident Date : 27-Jun-2019

Date : 28-Jun-2019

Our Ref : 219101 (CHINA) / CHAN

PAGE : 1

RAJAN RAJGOPAL
237 ARCADIA ROAD
#08-07
Singapore 289844

Not Authorized
11 Day @ 16,550/-
Resurvey After Paint 9 days

ESTIMATED COST OF REPAIR FOR BMWX3 XDRIVE 20I SKL7348H

1 pc	Bonnet		By	1,884.70	✓
1 pc	Bonnet logo		nd	106.75	✓
1 pc	Front bumper fascia		Bm	1,400.40	✓
1 pc	Front bumper no.plate garnish		nd	89.25	✓
2 pcs	Front bumper chrome grille	@ S\$145.65	CM	291.30	71
1 pc	Front bumper centre grille		nd	69.90	71
1 pc	Front bumper lower garnish		CM	196.90	✓
1 pc	Front bumper tow cover		CM	39.80	✓
2 pcs	Front bumper parking sensor	@ S\$251.60	Sh	503.20	71
2 pcs	Parking sensor holder	@ S\$ 19.00	nd	38.00	✗
1 pc	Front bumper lower garnish		nd	72.30	71
1 pc	Front bumper lower grille		CM	136.90	71
2 pcs	Front bumper nozzle cover	nd @ S\$ 39.80	Bm	79.60	✗
2 pcs	Front bumper nozzle	@ S\$176.50	CM	353.00	71
2 pcs	Headlamp	nd @ S\$2977.45		5,954.90	✓
2 pcs	Headlamp lower bracket	@ S\$204.80	R	409.60	7X
1 pc	Front air intake cowling		CM	471.00	71
1 pc	Front bumper reinforcement		By	697.10	71
1 pc	Front bumper sponge		CM	126.70	71
2 pcs	Front seat headrest assy	nd @ S\$756.40		1,512.80	71
1 pc	Tail gate		By	1,952.40	✓
1 pc	Tail gate glass inner seal		nd	107.60	✓
1 pc	Tail gate BMW logo		nd	76.60	✓
1 pc	Tail gate "X3" emblem		nd	69.70	✓
1 pc	Rear bumper fascia		Bm	1,530.20	✓
1 pc	Rear centre pad		nd	322.40	✓
2 pcs	Rear bumper tow cover	nd @ S\$ 36.60		73.20	✓
1 pc	Rear bumper centre garnish	nd @ S\$ 183.40	nd	183.40	71

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLQ9262U

Page : 2

4 pcs Rear bumper parking sensor	Shot @ S\$288.20	1,152.80	only
2 pcs Rear parking sensor o ring	Mc @ S\$ 12.00	24.00	only
2 pcs Rear bumper reflector	Sn @ S\$114.70	229.40	X
1 pc Rear bumper under cover		190.80	X
1 pc Rear bumper reinforcement		596.60	X
1 pc Rear bumper sponge		123.90	X
1 pc Rear bumper inner parts w/s		175.00	X
2 pcs Rear reinforcement bracket	@ S\$125.00	250.00	X
1 pc Rear end panel		597.10	X
1 pc Rear spare tyre panel		1,790.80	X
1 pc Rear exhaust chrome pipe		176.60	X
		24,056.60	
Less 10% :		2,405.66	

20041.40
2004.14
18037.26

- 1 pc Front no.plate with box
- 1 pc Rear w/s glass sealant
- 1 pc Rear no.plate with box

21,650.94 45sn
50.00 sn
60.00 sn 40sn
50.00 sn X

To rewire damaged parts and refocus headlamp beam.

120.00 40l

To remove & refix rear windscreen glass and conduct water leak test.

150.00 120l

To remove roof lining, front and rear seats, trim board and carpet

120.00 80l

To apply undersealing

100.00 60l

To remove and refix exhaust silencer box

100.00 XX

To putty and spray replaced parts

1,800.00 1100l

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

2,200.00 ? 1200 ✓

Total : S\$26,400.94

Singapore Dollars Twenty Six Thousand Four Hundred and Cents Ninety Four Only

L/Sum
16650.00
@ 5
→ to days
KENNETH PLS COMPANY
7/10/5

P18037.26
SN 85.00
L 2700.00
20822.26
4154.45
16657.81