

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

INDIA INTERNATIONAL INSURANCE PTE LTD

64, Cecil Street #04/05

IOB BUILDING

S,pore 049711

Accident date:28/06/2019

Date:01/07/2019

Estimate cost to repair vel: SLQ9402H (SORENTO) claims under vel: G3G 5425P

Not Actual
 2/5/19
 2/7/19
 Take photo of damage -
 9 day!

1pce tail gate	\$ 1,178.00	505/500 ✓
1pce tail gate emblem	69.00	nu ✓
1pce tail gate sorento plate	28.00	nu ✓
1pce tail gate GT plate	65.00	nu ✓
1pce tail gate cc plate	15.00	nu ✓
1pce tail gate windscreen sealant	140.00	nu 405.N
1set tail gate tape form	55.00	nu 305.N
1pce tail gate top lock	652.00	JM/nu ✓
1pce tail gate lower lock	28.00	11 X
1pce tail gate trim cover	298.00	?
2pcs tail gate dampers@\$874	1,748.00	11 X
1pce tail gate reverse camera	864.00	?
1pce tail gate rubber	128.00	9w1 ✓
2pcs tail gate hinges@\$33	66.00	11 X
2pcs tail gate reflectors@\$751	1,502.00	nu/scene o/s?
2pcs tai lamps@\$687	1,374.00	?
1pce rear bumper top	696.00	Dis ✓
1pce rear bumper lower	650.00	Dis ✓
1pce rear bumper reinforcement	392.00	?
4pcs rear bumper reverse sensors@\$215	860.00	5w1 2pcs
2pcs rear bumper reflectors@\$129	258.00	?
1pce rear bumper lower spoiler	103.00	Dis ✓
10pcs rear bumper inner clips@\$6	60.00	nu ✓
1pce rear exhaust pipe	892.00	11 X
2pcs rear exhaust pipe rubbers@\$30	60.00	11 X
1pce rear panel	526.00	?
1pce rear panel lower lock cover	69.00	6w1 ✓
1pce rear tool box holder	571.00	page1 ?

SOON SAN MOTOR TRADING

Bik.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

INDIA INTERNATIONAL INSURANCE PTE LTD

64, Cecil Street #04/05

IOB BUILDING

S,pore 049711

Accident date:28/06/2019

Date:01/07/2019

Estimate cost to repair vel:SLQ9402H (SORENTO) Claim under vel:413675425P

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 2		
1pce tail gate wiper motor	\$ 398.00	11 X
2pcs rear bumper side holders@\$35	70.00	ok ✓
1pce bonnet	1,374.00	3uc ✓
1pce bonnet lock	204.00	2u1 ✓
1pce front griller	795.00	?
2pcs head lamps@\$2,210	4,420.00	?
1pce front camera	450.00	shhd ✓
1pce griller top cover	171.00	11 X
1pce front bumper top	769.00	20/20 ✓
1pce front bumper lower	650.00	?
1pce front bumper reinforcement	551.00	?
4pcs front bumper sensors@\$215	860.00	shhd 2pcs
1pce front bumper spoiler	220.00	11 X
1pce front bumper lower griller	122.00	?
2pcs bonnet hinges@\$98	196.00	ok ✓
	\$24,597.00	
Less 5% 102	1,229.85	
	\$23,367.15	
2pcs rear & front number plate with cover	200.00	ok 80
Rear & front sticker (assessor)	500.00	ok 380
To rustproof front & rear	300.00	120
To remove/refit rear windscreen	140.00	120
To dismantle/renew tail gate	150.00	80
To focus head lamp & wiring	100.00	30
To remove/refit rear interior to effect repair	100.00	80
To dismantle/renew front & rear sensors	150.00	50
To dismantle/renew accident portion	2,500.00	1200

To spray paint

2,500.00
TOTAL \$ 30,067.15

1800