

SOON SAN MOTOR TRADING

Bik.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

INDIA INTERNATIONAL INSURANCE PTE LTD

64, Cecil Street #04/05

IOB BUILDING

S,pore 049711

Accident date:28/06/2019

Date:01/07/2019

Estimate cost to repair veh: SLQ9402H (SORENTO) claims under veh: G3G 5425P

*NOT Aced
re
d/s #15,500/
2/7/19
The ph. Along -
10 day!*

| | | | |
|--|------------|-------------|-------------------|
| 1pce tail gate | | \$ 1,178.00 | 50550 ✓ |
| 1pce tail gate emblem | | 69.00 | re ✓ |
| 1pce tail gate sorento plate | | 28.00 | re ✓ |
| 1pce tail gate GT plate | | 65.00 | re ✓ |
| 1pce tail gate cc plate | | 15.00 | re ✓ |
| 1pce tail gate windscreen sealant | | 140.00 | re 405.N |
| 1set tail gate tape form | | 55.00 | re 305.N |
| 1pce tail gate top lock | 485 | 652.00 | 3m/ru. ✓ |
| 1pce tail gate lower lock | | 28.00 | n1 X |
| 1pce tail gate trim cover | | 298.00 | re ✓ |
| 2pcs tail gate dampers@\$874 | | 1,748.00 | n1 X |
| 1pce tail gate reverse camera | | 864.00 | n1 X |
| 1pce tail gate rubber | | 128.00 | 7w. ✓ |
| 2pcs tail gate hinges@\$33 | | 66.00 | n1 X |
| 2pcs tail gate reflectors@\$751 | 615x2=1230 | 1,502.00 | n1 scene o/s re ✓ |
| 2pcs tai lamps@\$687 | | 1,374.00 | re ✓ |
| 1pce rear bumper top | 605 | 696.00 | n1 ✓ |
| 1pce rear bumper lower | 565 | 650.00 | n1 ✓ |
| 1pce rear bumper reinforcement | 341 | 392.00 | re ✓ |
| 4pcs rear bumper reverse sensors@\$215 | 187 | 860.00 | shrd 2905 374 |
| 2pcs rear bumper reflectors@\$129 | | 258.00 | n1 X |
| 1pce rear bumper lower spoiler | | 103.00 | n1 ✓ |
| 10pcs rear bumper inner clips@\$6 | | 60.00 | re ✓ |
| 1pce rear exhaust pipe | | 892.00 | n1 X |
| 2pcs rear exhaust pipe rubbers@\$30 | | 60.00 | n1 X |
| 1pce rear panel | | 526.00 | re ✓ |
| 1pce rear panel lower lock cover | | 69.00 | cu7 ✓ |
| 1pce rear tool box holder | | 571.00 | re ✓ |

605

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

INDIA INTERNATIONAL INSURANCE PTE LTD

64, Cecil Street #04/05

IOB BUILDING

S,pore 049711

Accident date:28/06/2019

Date:01/07/2019

Estimate cost to repair vel:SLQ9402H (SORENTO) Claim under vel:4134 5425F

LKK Auto Consultants hence notify the Repairer of the following:

- * Repaired parts must be resurveyed after spray painting
- * Repaired parts must be resurveyed during resurvey
- * Repaired parts must be resurveyed to confirmation
- * Repaired parts must be on a "Without Prejudice" basis
- * Repaired parts must be allowed
- * Repaired parts must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer

Signature:

| Page 2 | | |
|--|-------------|--------------------|
| 1pce tail gate wiper motor | \$ 398.00 | 11 X |
| 2pcs rear bumper side holders@\$35 | 70.00 | Ref |
| 1pce bonnet <i>1634</i> | 1,374.00 | 3uc ✓ |
| 1pce bonnet lock | 204.00 | 2u1 ✓ |
| 1pce front grille | 795.00 | 2u ✓ |
| 2pcs head lamps@\$2,210 <i>2210</i> | 4,420.00 | 2u ✓ |
| 1pce front camera | 450.00 | shhd ✓ 300 S.W |
| 1pce griller top cover | 171.00 | 11 X |
| 1pce front bumper top | 769.00 | 20/ae ✓ |
| 1pce front bumper lower | 650.00 | 2u ✓ |
| 1pce front bumper reinforcement <i>450</i> | 551.00 | 2u ✓ |
| 4pcs front bumper sensors@\$215 <i>1650</i> | 860.00 | shhd 2pc ✓ 200 S.W |
| 1pce front bumper spoiler | 220.00 | 11 X |
| 1pce front bumper lower griller | 122.00 | 11 X |
| 2pcs bonnet hinges@\$98 | 196.00 | 2u ✓ |
| | \$24,597.00 | <i>16362</i> |
| Less 5% <i>102</i> | 1,229.85 | |
| | \$23,367.15 | |
| 2pcs rear & front number plate with cover | 200.00 | 2u 80 S.W |
| Rear & front sticker (assessor) | 500.00 | 2u 380 S.W |
| To rustproof front & rear | 300.00 | 100 |
| To remove/refit rear windscreen | 140.00 | 120 |
| To dismantle/renew tail gate | 150.00 | 80 |
| To focus head lamp & wiring | 100.00 | 300 |
| To remove/refit rear interior to effect repair | 100.00 | 80 |
| To dismantle/renew front & rear sensors | 150.00 | 50 |
| To dismantle/renew accident portion | 2,500.00 | 1200 |

To spray paint

2,500.00
TOTAL \$ 30,007.15 *1800*

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

INDIA INTERNATIONAL INSURANCE PTE LTD

64, Cecil Street #04/05

IOB BUILDING

S,pore 049711

Accident date: 28/06/2019

Date: 03/07/2019

To supplementary

Estimate cost to repair vel: SLQ 9402H (SORENTO) claims under vel: GBG 5425P.

| | | |
|--------------------------------|-----------|--------|
| 1pce front number plate holder | \$ 68.00 | Torn ✓ |
| 1pce front bonnet rubber | 42.00 | ru ✓ |
| 1pce front bumper inner sponge | 119.00 | Torn ✓ |
| | \$ 229.00 | |
| Less 5% <i>10%</i> | 11.45 | |
| Total | \$ 217.55 | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

P-16591
102
P-14931-90
S.N. 1030.00
Labor - 3460.00

19471.9
207

15537