

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
 BEDOK NORTH AVE 4,
 #01-2008/10/12 SINGAPORE 489977
 TEL: 6441 5655 FAX: 6441 5355/6243 8121
 R.O.C No: 200104141D GST Reg. No. 20-0104141-D

*not added
 lhh
 2/5/19
 Hdy,
 11/7/19
 when job allow 12*

TO : SXXX3392J
 RAJINIGANTH S/O MANI
 BLK 613B BEDOK RESERVOIR ROAD
 #13-1370
 SINGAPORE 472613
 TEL : FAX :
 PH: 97979596
 ATTN :

ESTIMATE BILL

Number : EB00005197
Date : 26/06/2019
Case No : AD00010515
Vehicle No : SJC4060R
Chassis: JF1GD5KJ37G072295
Year of Mfr 2007
Policy No
Model : SUBARU IMPREZA

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	BOOTLID <i>2</i>	1.0	654.30	20	523.44
2	BOOTLID EMBLEM <i>net</i>	1.0	65.80	20	52.64
3	BOOTLID LOGO - SUBARU <i>net</i>	1.0	48.50	20	38.80
4	BOOTLID LOGO - IMPREZA <i>net</i>	1.0	48.50	20	38.80
5	BOOTLID HINGE RH <i>11</i>	1.0	54.50	20	43.60
6	BOOTLID HINGE LH <i>11</i>	1.0	54.50	20	43.60
7	BOOTLID RUBBER <i>TM</i>	1.0	90.50	20	72.40
8	END PANEL	1.0	528.70	20	422.96
9	REAR BUMPER <i>20</i>	1.0	588.70	20	470.96
10	REAR BUMPER REINFORCEMENT	1.0	110.00	20	88.00
11	REAR BUMPER RETAINER RH <i>321</i>	1.0	60.30	20	48.24
12	REAR BUMPER RETAINER LH <i>11</i>	1.0	60.30	20	48.24
13	REAR BUMPER CLIP <i>net</i>	3.0	3.90	20	9.36
14	REAR NUMBER PLATE LAMP <i>11</i>	1.0	38.60	20	30.88
15	REAR FENDER LAMP RH <i>tail lamp o/s one 412.80</i>	1.0	421.80	20	337.44
List Price - Parts Sub Total					2,269.36
16	REAR FENDER RH - REPAIR <i>2 X</i>	1.0			
17	SPARE TYRE PANEL - REPAIR <i>2 X</i>	1.0			
18	REAR NUMBER PLATE <i>321</i>	1.0	30.00	0	30.00
19	REAR NUMBER PLATE HOLDER <i>321</i>	1.0	30.00	0	30.00
20	REVERSE SENSOR <i>short</i>	1.0	280.00	0	280.00
21	REAR BUMPER SPOILER RH <i>11</i>	1.0	480.00	0	480.00
22	BOOTLID SPOILER <i>11</i>	1.0	1,250.00	0	1,250.00
Special Nett Price - Parts Sub Total					2,070.00
Parts Total					4,339.36
23	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,000.00	0	1,000.00
24	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,200.00	0	1,200.00
25	ANTI-RUST COATING	1.0	350.00	0	350.00
26	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
27	WIRING	1.0	40.00	0	40.00
Labour 1 Sub Total					2,740.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
 BEDOK NORTH AVE 4,
 #01-2008/10/12 SINGAPORE 489977
 TEL : 6441 5655 FAX : 6441 5355/6243 8121
 R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX3392J
 RAJINIGANTH S/O MANI
 BLK 613B BEDOK RESERVOIR ROAD
 #13-1370
 SINGAPORE 472613
 TEL : FAX :
 PH : 97979596
 ATTN :

ESTIMATE BILL

Number : EB00005197
Date : 26/06/2019
Case No : AD00010515
Vehicle No : SJC4060R
Chassis: JF1GD5KJ37G072295
Year of Mfr 2007
Policy No
Model : SUBARU IMPREZA

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
	<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: auto;"> <p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>				
SINGAPORE DOLLARS : SEVEN THOUSAND FIVE HUNDRED SEVENTY-FOUR AND CENTS NINETY-TWO ONLY			Less Excess		0.00
			SUBTOTAL		7,079.36
			GST 7.00%		495.56
			TOTAL		7,574.92

Date of accident : 14/06/2019 04:40 PM. Place : 3000 ANG MO KIO AVENUE 3

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

 CUSTOMER SIGNATURE

 AUTHORISED SIGNATURE