

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355 6243 8121
R.O.C No. 200104141D GST Reg. No. 20-0104141-D

TO : SXXX3392J
RAJINIGANTH S O MANI
BLK 613B BEDOK RESERVOIR ROAD
#13-1370
SINGAPORE 472613
TEL: FAX:
PH: 97979596
ATTN:

ESTIMATE BILL

Number : EB00005197
Date : 26/06/2019
Case No : AD00010515
Vehicle No : SJC4060R
Chassis: JF1GD5KJ37G072295
Year of Mfr 2007
Policy No
Model : SUBARU IMPREZA

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	BOOTLID	1.0	654.30	20	523.44
2	BOOTLID EMBLEM	1.0	65.80	20	52.64
3	BOOTLID LOGO - SUBARU	1.0	48.50	20	38.80
4	BOOTLID LOGO - IMPREZA	1.0	48.50	20	38.80
5	BOOTLID HINGE RH	1.0	54.50	20	43.60
6	BOOTLID HINGE LH	1.0	54.50	20	43.60
7	BOOTLID RUBBER	1.0	90.50	20	72.40
8	END PANEL	1.0	528.70	20	422.96
9	REAR BUMPER	1.0	588.70	20	470.96
10	REAR BUMPER REINFORCEMENT	1.0	110.00	20	88.00
11	REAR BUMPER RETAINER RH	1.0	60.30	20	48.24
12	REAR BUMPER RETAINER LH	1.0	60.30	20	48.24
13	REAR BUMPER CLIP	3.0	3.90	20	9.36
14	REAR NUMBER PLATE LAMP	1.0	38.60	20	30.88
15	REAR FENDER LAMP RH	1.0	421.80	20	337.44
List Price - Parts Sub Total					2,269.36
16	REAR FENDER RH - REPAIR	1.0			
17	SPARE TYRE PANEL - REPAIR	1.0			
18	REAR NUMBER PLATE	1.0	30.00	0	30.00
19	REAR NUMBER PLATE HOLDER	1.0	30.00	0	30.00
20	REVERSE SENSOR	1.0	280.00	0	280.00
21	REAR BUMPER SPOILER RH	1.0	480.00	0	480.00
22	BOOTLID SPOILER	1.0	1,250.00	0	1,250.00
Special Nett Price - Parts Sub Total					2,070.00
Parts Total					4,339.36
23	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,000.00	0	1,000.00
24	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,200.00	0	1,200.00
25	ANTI-RUST COATING	1.0	350.00	0	350.00
26	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
27	WIRING	1.0	40.00	0	40.00
Labour 1 Sub Total					2,740.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008 10 12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355 6243 8121
R.O.C No. 200104141D GST Reg. No. 20-0104141-D

TO : SXXX3392J
RAJINIGANTH S/O MANI
BLK 613B BEDOK RESERVOIR ROAD
#13-1370
SINGAPORE 472613
TEL : FAX :
PH : 97979596
ATTN :

ESTIMATE BILL

Number : EB00005197
Date : 26/06/2019
Case No : AD00010515
Vehicle No : SJC4060R
Chassis : JF1GD5KJ37G072295
Year of Mfr 2007
Policy No
Model : SUBARU IMPREZA

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
SINGAPORE DOLLARS : SEVEN THOUSAND FIVE HUNDRED SEVENTY-FOUR AND CENTS NINETY-TWO ONLY			Less Excess		0.00
			SUBTOTAL		7,079.36
			GST 7.00%		495.56
			TOTAL		7,574.92

Date of accident : 14/06/2019 04:40 PM. Place : 3000 ANG MO KIO AVENUE 3

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE