



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

18 July 2019

QUOT201907-000039

HHTPCLAIMS19-119

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET, #04-00 / #05-00

IOB BUILDING

SINGAPORE 049711

Attn: Motor Claims Department

*Steve (LKK) 30/7/19, 11.00am
5 4 days
L/S, Reng AR spy*

ACCIDENT INVOLVING SLE4629S & SHC8744Z ON 30/06/2019 ALONG CANBERRA DRIVE AT ABOUT 1510 HOURS

Insured : LIM YEAN GUAN
Vehicle Registration No. : SLE4629S
Vehicle Make : HONDA
Vehicle Model : VEZEL 1.5X CVT
Vehicle Chassis No. : RU11200802
Policy No. : M0008089
Date of Accident : 30/06/2019

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Door (RH) / <i>OD</i>		\$ 930.60
2	1	Rear Door Sash Tape (RH) / <i>npc</i>		\$ 35.00
3	1	Rear Door Strip (RH) <i>x</i>		\$ 39.80
4	1	Rear Door Stone Guard Tape (RH) / <i>npc</i>		\$ 45.00
5	1	Rear Fender Arch Garnish (RH) / <i>DR</i>		\$ 150.00
6	1	Rear Fender Inner Shield (RH) <i>x</i>		\$ 123.50
7	10	Rear Fender Inner Shield Clip <i>x</i>	\$ 3.90	\$ 39.00
8	1	Side Skirt (RH) / <i>CUT</i>		\$ 377.50
9	1	Rear Wheel Bearing (RH) <i>✓</i> DAM		\$ 263.50
				\$ 2,003.90
				Less 20%
				\$ 400.78
				\$ 1,603.12

10 1 Rear RH Rim / *CUT* NETT \$ 350.00

To dismantle & change rear RH door, RH side skirt, knocking & pull straight rear RH fender and all area affected by accident \$ 800.00 *450*

To perform wire checking \$ 20.00 *✓*

To do wheel alignment \$ 100.00 *60*

To dismantle & refit rear RH undercarriage \$ 150.00 *100*

To dismantle & transfer rear RH door mechanism and fitting to new door \$ 60.00 *50*

To spray rear RH bumper, rear RH fender, rear RH door and all area affected by accident \$ 800.00 *500*

CONTINUE NEXT PAGE



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

18 July 2019

QUOT201907-000039

HHTPCLAIMS19-119

ACCIDENT INVOLVING SLE4629S & SHC8744Z ON 30/06/2019 ALONG CANBERRA DRIVE AT ABOUT 1510 HOURS

Estimate Repair List for vehicle SLE4629S - HONDA VEZEL 1.5X CVT

S/N	Quantity	Description	Unit Price S\$	Amount S\$
				\$ 3,883.12
			7% GST	\$ 271.82
			Total	\$ 4,154.94

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

 

Authorised by Claims Dept.