

India - LKK



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Repair Estimates

SLM 3083 E

*Not Authorized  
Purview B4 paint*

<b>Parts</b>	(a) Cost / List Price Items	\$	<u>2,253.65</u>
	Plus/Less 25%	\$	<u>563.41</u>
	<b>Total of Cost / List</b>	\$	<u><u>1,690.24</u></u>
	(b) Nett Price Items		_____
	Less		_____
	<b>Total of Nett Item</b>		_____
	(c) Special Nett Items		_____
<b>Total Parts Cost</b>		\$	<u><u>1,690.24</u></u>
<b>Labour</b>		\$	<u><u>1,530.00</u></u>
<b>Total</b>		\$	<u><u>3,220.24</u></u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kennerth

Company : LKK

Survey conducted on : 2/7/18 at \_\_\_\_\_

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Sc Date: 2/7/18



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Spare Parts

Vehicle No. : SLM 3083 E  
 Make & Model : TOYOTA PRIUS  
 Chassis No : JTDKB3FU103554516

Submit By : Carmen Lim  
 Year Manufacture : 2017  
 Engine No. : \_\_\_\_\_

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH wing mirror (motor)	1			
2	RH wing mirror (glass)	1	\$1,374.20		✓
3	RH wing mirror (signal lamp)	1			
4	RH wing mirror (cover)	1	\$87.40		?
5	RHF door glass	1	\$670.30		✓
6	RHF door glass outer moulding	1	\$121.75		✓
7	RHF door quarter glass pillar	1	TBA		X
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

