

Khanchana

Section A - Accident Details

Registration Number	SHB1005A
Case Reference Number	TAX/06/19/2105
Registration Date	7/5/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	LOON PENG PUI
Type of Accident	Head to Rear
Accident Date and Time	28/6/2019 1:35 PM
Accident Reported Date and Time	28/6/2019 2:29 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24102198
Special Instruction to ARC, if any	TP
Prepared Date and Time	30/6/2019 10:10 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$945.00	\$750.00
Total Spray Cost	\$1,836.00	\$850.00
Total Spare Part Cost	\$8,585.21	\$3,679.66
Total Other Cost	\$1,060.00	\$270.00
TOTAL COST	\$12,326.21	\$5,549.66
Lump Sum Total	\$12,350.00	\$5,550.00 (L/S)
Number of Repair Days	7.0	6.0
Prepared / Adjusted By	Tuck Foo Kok	STEVE CHEN (LKK) / AIG
ARC / Surveyor Sign Off Date	05/07/2019 5:56 PM	05/07/2019 3:01 PM
Signature		
Remarks	L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
30 Woodlands Industrial Park East, Singapore
TAX Number: S3083523
Company Telephone Number: 64621623
Accident Reporting Number: 6861622

Date Generated: 18/07/2019

User ID: i_Parkson

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1907-0175	Invoice Number	
Quotation Date	10.07.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$845.00	\$750.00
Total Labour	\$845.00	\$750.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$100.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$100.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$180.00	\$150.00
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,836.00	\$850.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$30.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$20.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$30.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$100.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
Total Other Costs	\$1,080.00	\$270.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47955	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace ✓
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace ✓
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace ✓
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given X
		52016-47050	ARM SUB-ASSY. RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace ✓
		55997-30070	ANTENNA ELECTRICAL LOWER REAR SENSOR REVERSE	0.00	\$157.40	0.00	\$0.00	Replace	Check X
				1.00	\$180.00	0.00	\$180.00	Replace	Replace ✓
		52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace	Replace ✓



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
22 Woodlands Industrial Park East, Singapore
Estimate Number: 434552
Estimate Telephone Number: 68620211
Accident Reporting Number: 68620270

Date Generated: 16/07/2016
User ID: 1000000

52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace	✓
52562-47021	BUMPER SEAL RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given	✓
52591-47021	BUMPER SEAL RR RH	0.00	\$85.70	0.00	\$0.00	Replace	Not Given	✓
76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	✓
76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given	✓
76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given	✓
58308-47211	UNDER COVER SUB-ASSY, RR FLOOR	1.00	\$514.50	25.00	\$385.88	Replace	Replace	✓
58307-47050	END PANEL	1.00	\$802.10	25.00	\$451.58	Replace	Replace	✓
64718-47031B0	END PANEL COVER DECK TRIM HOLE	1.00	\$46.10	25.00	\$34.58	Replace	Replace	✓
64718-47031B0	END PANEL COVER DECK TRIM RR	0.00	\$121.10	0.00	\$0.00	Replace	Check	✓
	SEALANT SSKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Replace	✓
64983-47020	BOX, DECK FLOOR, RR	0.00	\$849.70	0.00	\$0.00	Replace	Check	✓
58418-47030B3	BOX, RR FLOOR, BOARD	0.00	\$679.60	0.00	\$0.00	Replace	Check	✓
58311-47021	SPARE TYRE PANEL	1.00	\$567.70	100.00	\$0.00	Replace	Repair	✓
58338-12090	REINFORCEMENT, RR	1.00	\$34.60	25.00	\$25.95	Replace	Replace	✓
67009-47241	TAILGATE ASSY	1.00	\$1,007.90	25.00	\$755.93	Replace	Replace	✓
75573-47080	TAILGATE DOOR GLASS Moulding, RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓
75574-47020	TAILGATE DOOR GLASS Moulding, LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓
75575-47020	MOULDING BACK WINDOW, LOWER NO.1	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓
	SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00	Replace	Replace	✓
68810-47010	TAILGATE DOOR HINGE LH/RH	0.00	\$58.30	0.00	\$0.00	Replace	Not Given	✓
68960-0W532	TAILGATE DOOR STAY LH	0.00	\$241.50	0.00	\$0.00	Replace	Not Given	✓
68950-0W542	TAILGATE DOOR STAY RH	0.00	\$241.50	0.00	\$0.00	Replace	Not Given	✓
69350-47020	TAILGATE DOOR LOCK	1.00	\$444.10	25.00	\$333.08	Replace	Replace	✓
69415-47020	TAILGATE LOCK, COVER	0.00	\$15.70	0.00	\$0.00	Replace	Not Given	✓
69431-47010	STRIKER, BACK DOOR	0.00	\$48.50	0.00	\$0.00	Replace	Not Given	✓
67881-47022	TAILGATE DOOR WEATHER STRIP	1.00	\$353.40	25.00	\$265.05	Replace	Replace	✓
67751-47040C0	TAILGATE TRIM, LOWER	0.00	\$180.70	0.00	\$0.00	Replace	Check	✓
67750-47071C0	TAILGATE, BOARD ASSY	0.00	\$246.90	0.00	\$0.00	Replace	Check	✓
76801-47070-80	TAILGATE OUTSIDE GARNISH	0.00	\$504.90	0.00	\$0.00	Replace	Check	✓
75310-47020	EMBLEM REAR	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	✓
86790-47040	CAMERA ASSY, TELEVISION, RR	0.00	\$1,436.60	0.00	\$0.00	Replace	Not Given	✓
75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	✓
75442-47030	NAME PLATE (PRUIS)	0.00	\$80.80	0.00	\$0.00	Replace	Not Given	✓
75443-47030	NAME PLATE (TOYOTA)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	✓
	NUMBER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace	✓
	NUMBER PLATE FRAME	1.00	\$12.00	25.00	\$6.00	Replace	Replace	✓
	STICKER DECAL SMRT	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	✓
	STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	✓
61604-47090	FENDER RR/RH	1.00	\$766.80	100.00	\$0.00	Replace	Repair	✓
	STICKER DECAL SMRT	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	✓
	STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	✓
81821-47030	TROUGH, BACK DOOR	0.00	\$110.90	0.00	\$0.00	Replace	Not Given	✓
52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Not Given	✓
81551-47180	TAIL LAMP RH	1.00	\$557.80	10.00	\$502.02	Replace	Replace	✓



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
20 Woodlands Industrial Park St, Singapore
TAX Number: 00001900
Estimate Reference Number: 0000001
Report Reference Number: 0000001

Date Generated: 16/07/2016
User ID: P00000

		52583-47010	TAIL LAMP BRACKET, LH	0.00	\$30.70	0.00	\$0.00	Replace	Not Given	X
		81581-47170	TAIL LAMP LH	0.00	\$548.40	0.00	\$0.00	Replace	Not Given	X
Total					\$12,719.91		\$4,049.43			
Added Spare Parts / Material Usage After Surveyor Signed off										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		67750-47071C0	TAILGATE, BAORD ASSY	1.00	\$246.90	25.00	\$185.18	Replace	Replace	✓
		53016-47030	ARM SUB-ASSY. RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace	✓
		76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$88.58	Replace	Replace	✓
		76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace	✓
Total					733.60		\$50.14			

4599.57

-20%

3679.66

+ 750.00

+ 1120.00

5549.66

L/s \$5550/-

Case Details

Case Reference Number : TAX/06/19/2105

Company Type : SMRT Taxi Pte Ltd

Insurance Company Name : AIG Asia Pacific

Type of Repair : Accident Repair

Estimation ID : EST-7504-ID

Insurance Pte Ltd

Accident Date and Time : 28/06/2019 05:35

Vehicle Registration Number : SHB1005A

Assigned By : Taxi Claims Manager Team

AM

Vehicle Age(In Months) : 61

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spares Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Quantity	Surveyor Approval	
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)			Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER REAR	1	458.90	458.90	25.00	343.93	Replace	1	343.9	Replace • <i>DD</i>
One Time Key In	Main			BUMPER CLIPS	10	1.81	18.10	25.00	12.08	Replace	10	12.08	Replace • <i>MC</i>
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.0	Replace • <i>MC</i>
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	206.70	206.70	25.00	154.27	Replace	1	154.2	Replace • <i>DD</i>
One Time Key In	Main			ARM SUB-ASSY. RH BUMPER LH	1	129.60	129.60	25.00	104.70	Replace	0	0	Not Give • <i>NAIX</i>
One Time Key In	Main			ARM SUB-ASSY. RH BUMPER RH	1	129.60	129.60	25.00	104.70	Replace	1	104.7	Replace • <i>BT</i>
One Time Key In	Main			ANTENNAELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Check • <i>X NAIX</i>
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.0	Replace • <i>OR</i>
One Time Key In	Main			BUMPER SIDE RETAINER RL/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace • <i>OR</i>
One Time Key In	Main			BUMPER SIDE RETAINER RL/RH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace • <i>OR</i>
One Time Key In	Main			BUMPER SEAL, RH LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Give • <i>X NAIX</i>

Total Spares Part Cost 10,181.39

Surveyor Total 4,949.41

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(£)	List Price(£)	Dis(%)	Final Price(£)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(£)	Repair/Replace
One Time Key In	Main			BUMPER SEAL, RR RH	1	66.70	66.70	25.00	49.99	Replace	0	0	Not Give • X NM
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.30	72.30	25.00	54.19	Replace	0	0	Not Give • X NM
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give • X NM
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give • X NM
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	314.50	314.50	25.00	235.88	Replace	1	265.8	Replace • / CRU
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	1	451.5	Replace • / ON
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	1	34.58	Replace • / CRU
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	0	0	Check • X NM
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace • / MC
One Time Key In	Main			BOX, DECK FLOOR, RR	1	949.70	949.70	25.00	711.28	Replace	0	0	Check • X NM
One Time Key In	Main			BOX, RR FLOOR, BOARD	1	879.60	879.60	25.00	659.70	Replace	0	0	Check • X NM
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	1	0	Repair • X R
One Time Key In	Main			REINFORCEMENT, RR	1	34.80	34.80	25.00	25.95	Replace	1	25.95	Replace • / ON
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	715.9	Replace • / ON
One Time Key In	Main			TAILGATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace • / MC
One Time Key In	Main			TAILGATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace • / MC
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace • / MC

Total Spare Part Cost 10,181.38

Surveyor Total 4,048.41

Lump Sum Discount (%) 25.00

Lump Sum Dis (%) 20

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.0	Replace • / MC
One Time Key In	Main			TAILGATE DOOR HINGE LHRH	1	58.30	58.30	25.00	43.72	Replace	0	0	Not Give • X MM
One Time Key In	Main			TAILGATE DOOR STAY LH	1	241.50	241.50	25.00	181.12	Replace	0	0	Not Give • X MM
One Time Key In	Main			TAILGATE DOOR STAY RH	1	241.50	241.50	25.00	181.12	Replace	0	0	Not Give • X MM
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	1	333.0	Replace • / OT
One Time Key In	Main			TAILGATE LOCK COVER	1	15.70	15.70	25.00	11.77	Replace	0	0	Not Give • X MM
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0	Not Give • X MM
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	253.40	253.40	25.00	189.05	Replace	1	253.0	Replace • / TM
One Time Key In	Main			TAILGATE TRIM, LOWER	1	180.70	180.70	25.00	135.52	Replace	0	0	Check • X MM
One Time Key In	Main			TAILGATE, BACK ASSY	1	246.90	246.90	25.00	185.18	Replace	0	0	Check • X MM
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	379.67	Replace	0	0	Check • X MM
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	0	0	Not Give • X MM
One Time Key In	Main			CAMERA ASSY, TELEVISION, RR	1	1,436.60	1,436.60	15.00	1,221.94	Replace	0	0	Not Give • X MM
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give • X MM
One Time Key In	Main			NAME PLATE (PHEV)	1	60.80	60.80	25.00	45.60	Replace	0	0	Not Give • X MM
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give • X MM
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace • / OT

Total Spare Part Cost 10,181.38

Surveyor Total 4,049.41

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Disc(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	25.00	9.00	Replace	1	9.00	Replace • / COT
One Time Key In	Main			STICKER DECAL SMRT	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give • X / M
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.80	21.80	25.00	16.20	Replace	0	0	Not Give • X / M
One Time Key In	Main			FENDER RR/RH	1	768.80	768.80	25.00	576.10	Replace	1	0	Repair • X R
One Time Key In	Main			STICKER DECAL SMRT	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give • X / M
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.80	21.80	0.00	21.80	Replace	0	0	Not Give • X / M
One Time Key In	Main			TROUGH, BACK DOOR	1	110.90	110.90	25.00	83.18	Replace	0	0	Not Give • X / M
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0	Not Give • X / M
One Time Key In	Main			TAIL LAMP RH	1	507.80	507.80	10.00	502.02	Replace	1	502.0	Replace • / R
One Time Key In	Main			TAIL LAMP BRACKET, LH	1	30.70	30.70	25.00	23.02	Replace	0	0	Not Give • X / M
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	0	0	Not Give • X / M
Total Spare Part Cost									10,181.38	Surveyor Total 4,049.81			
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20			
Final Spare Part Cost									8,145.10	Final Sur Total 3,228.53			

Labour's Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	845.00	750	
Total:			845.00	750.00	

Spray Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200.00	
2	Main	TO RESPRAY BUMPER BEAM	180.00	100	

			Recommendation(\$)	Adjustment(\$)
3	Main	TO RESPRAY REAR PANEL	180.00	100
4	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	100
5	Main	TO RESPRAY TAIL GATE	278.00	200
6	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0
7	Main	TO RESPRAY REAR FENDER RH	180.00	150
8	Main	TO RESPRAY TROUGH BACK DOOR RH	180.00	0
Total:			1,836.00	850.00

Other Cost Detail

S.No	Coating Type	Job Scope	SMART Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00	
2	Main	TO TEST AND REPAIR REVERSE SENSOR SYSTEM	120.00	20	
3	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	30.00	
4	Main	TO INSPECT RR LIGHTING MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	25	
5	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	30	
6	Main	TO REMOVE AND REPAIR REAR WINDSCREEN	240.00	100.00	
7	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	
8	Main	TO WASH AND VACUUM	60.00	0.00	
9	Main	TO REPLACE SUNDRY PARTS	100.00	20	
Total:			1,060.00	275.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	8,145.10	3,239.53
Total Labour Cost	845.00	750.00
Total Spray Painting	1,836.00	850.00
Other	1,060.00	270.00
Overall Total	11,886.10	5,109.53
Lump Sum Repair Option	-	✓
Lump Sum Total	11,900.00	5,100.00

Surveyor Approved Amount

\$,100.00

No. of Repair Days

7

8

Remarks

L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com

Surveyor Name

STEVE CHEN

Signature



Survey Date

01/07/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLEMENT PARTS

Contractor:			
Accident Case Number	TAX/06/19/2105	Date of Collection	1 / 1
Vehicle No	S4B 1005 A	Date of Request	03/07/2019
Vehicle Model	TOYOTA PROUS	Number of Days to Extend (If any)	2 0

S/N	Part Number	Part Description	Quantity	Unit Price
		ARM SUB ASSY, REAR BUMPER	1H 1pc	104.70 / 00
		Bumper Lip COVER REAR RH	1pc	88.58 / CRU
		Bumper Lip REAR	1pc	171.68 / CRU
		TAILGATE / BOARD ASSY	1pc	185.18 / BR

<<<Please submit photographs for damaged parts>>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission