

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SGG 6365M**
 Model : Mazda 2
 Year : _____
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Tailgate	1	\$ 838.50	\$ 838.50	DPV
2	Tailgate logo	1	\$ 54.30	\$ 54.30	} NEC
3	Tailgate emblem 'Mazda'	1	\$ 48.20	\$ 48.20	
4	Tailgate emble '2'	1	\$ 38.00	\$ 38.00	
5	Tailgate emblem 'SP'	1	\$ 42.50	\$ 42.50	
6	Tailgate outer garnish	1	\$ 88.90	\$ 88.90	
7	Tailgate reflector Lh	1	\$ 290.10	\$ 290.10	} BRV
8	Tailgate reflector Rh	1	\$ 290.10	\$ 290.10	
9	Tailgate lock assy	1	\$ 251.00	\$ 251.00	JMV
10	Tailgate striker	1	\$ 88.00	\$ 88.00	BTV
11	Tailgate weather strip	1	\$ 108.00	\$ 108.00	DISV
12	Tailgate inner trim board	1	\$ 205.20	\$ 205.20	BRV
13	Tailgate windscreen moulding	1	\$ 128.00	\$ 128.00	NECV
14	Rear bumper	1	\$ 482.20	\$ 482.20	BRV
15	Rear bumper side retainer	2	\$ 33.80	\$ 67.60	NECV
16	Rear bumper reflector	2	\$ 66.50	\$ 133.00	NNX
17	Rear bumper bracket	2	\$ 50.80	\$ 101.60	NNX
18	Rear end panel	1	\$ 334.60	\$ 334.60	BTV
19	Rear end panel top garnish	1	\$ 96.00	\$ 96.00	BRV
20	Spare tyre panel	1	\$ 704.20	\$ 704.20	NNX
21	Spare tyre panel top board	1	\$ 154.90	\$ 154.90	NNX
22	Taillamp Lh	1	\$ 390.60	\$ 390.60	BRV
23	Taillamp lower panel Lh	1	\$ 219.80	\$ 219.80	RX
24	Taillamp Rh	1	\$ 390.60	\$ 390.60	BRV
25	Taillamp lower panel Rh	1	\$ 219.80	\$ 219.80	RX

Parts Sub Total : \$ 4234.20 5,765.70

20% Discount \$ 846.84 1,153.14

PARTS TOTAL : \$ 3387.36 4,612.56

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 60.00	\$ 60.00	NNX
2	Tailgate windscreen inner seal	1	\$ 80.00	\$ 80.00	NEC
3	Tailgate windscreen sealant	1	\$ 100.00	\$ 60.00 100.00	✓
4	Reverse sensor with module	1	\$ 400.00	\$ 200.00 400.00	✓
5	Rear end panel sealant	1	\$ 100.00	\$ 60.00 100.00	✓
6	Spare tyre panel insulator pad	1	\$ 280.00	\$ 280.00	NECV
7	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00	✓
8	Taillamp clips	2	\$ 50.00	\$ 60.00 100.00	✓
9	Rear end panel top garnish clips	1	\$ 50.00	\$ 30.00 50.00	✓
10	Taillamp seal	2	\$ 80.00	\$ 160.00	NEC

SPECIAL NETT TOTAL : \$ 800.00 1,380.00

Nos.	LABOUR	S\$
1	R&B tailgate component	\$ 50.00 100.00

2	R&R reverse sensor	\$ 60.00 100.00	/
3	R&R upholstery	\$ 50.00 100.00	/
4	Mount bench work	\$ 300.00	NNX
5	Panel beat	\$ 800.00 1400.00	
6	Rust proofing	\$ 60.00 150.00	
7	Spray painting	\$ 850.00 1,400.00	
LABOUR TOTAL :		\$ 1820.00	3,550.00

PARTS TOTAL : \$ 4,612.56
 SPECIAL NETT TOTAL : \$ 1,380.00
 LABOUR TOTAL : \$ 3,550.00
GRAND TOTAL : \$ 9,542.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Resurvey on 5/7/19
 Lump sum repair
 Repair days 6

Parts 3387.36
 SN 800.00
 Labour 1820.00

 6007.36
 @ 20% 1201.47

 4805.89

L/s 4,800/2