

ASS. REC. BY:

REF:

CS/FCI/19011698/K1td3n2

Special Instruction:

Surveyor:

Kabin

ASSIGNMENT (Office)

From (Person):

Serene

of

FCI

Date/Time:

2/7/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 8711Z

Insured:

SHC 1499C

at Workshop m/s

Premier Automotive

Tel:

65446689.

of

23 Changi South Ave 2 #03-02.

Policy No:

Claim No:

D19004277MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

1/4/2019.

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 1499C: CS/FCI/K005620/btd3q2 D.O.A: 22/03/2018

SHB 8711Z: CS/ICS/18005480/btd3n2 D.O.A: 16/03/2018

5/7-

Revised via email preli advise.

Surrey: Kelvin

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHB 87112 Yr Regn: 25 Nov, 2013Type: M. Car / M. Cycle / Bus / Van / Lorry / ~~Tr~~ / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c. 1600Colour: Silver A/C: Ins / Std / NI / NASp. Reading: 459883 T/Radio: Ins / Std / NI / NA

Eng/No: _____

C/No: KNAH M414ME5 452065Gen. Cond: Good / ~~Ex~~ / Poor / BurntSteering: Ins / Jammed / Leaked / Burnt orBrake: Ins / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/65 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or HarakaFront 7 mm Rear 7 mmR/Bal. 7 mmL/Bal. 7 mmD.O.A. 1/7/19 D.O.I. 2/7/19Survey held at Pre-Ins

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s Rec

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
8/7/19	Checked PIP \$920/20y. (Red: 3753. 30% 80% to) FC2
	40
	RECEIVED 6 JUL 2019

Date/Time, File Pass to?

☐

: Preli. Report

1) Q17 Typist☒

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 2Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

135
50
50
20
255

Report Format: TPLump Sum / (S) 920



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004277MFSH

Date: 5/7/2019

Our Ref: CS/FCI19011698/K1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 8711Z

Please be informed that we had conducted the inspection of the abovementioned vehicle
2/7/2019 at the premises of M/s Premier Automotive have the following to report: -

Workshop Estimate Amount	: S\$ <u>4,673.30</u>
Revised Estimate Amount	: S\$ <u>920.00</u>
"Check" Items Amount	: S\$ <u>0.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the
n/s rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kalvin

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	01-07-2019	Our Ref No. D19004277MFSH
Accident Date	01-07-2019	Claim Type. Third Party
Insured Vehicle	SHC1499C	Third Party Vehicle. SHB8711Z
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	VINCENT CHUA	
Contact No.	0/ 65446689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: NO EST. COR.	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Calvin

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 5 July 2019 10:57 AM
To: 'CWS Motor Claims'
Cc: Admin-D (LKKAuto); 'Serene Ler'
Subject: RE: SURVEY ASSESSMENT - D19004277MFSH/1
Attachments: PRELI ADVISED SHB 8711Z.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHB 8711Z**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 2 July, 2019 12:35 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004277MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire Transaction History**Transaction History Details**

Log Date/Time:	25 Nov 2013 / 10:12:45	Receipt No.:	AACCK001-AX239-131125-000009
Asset Type:	Vehicle	Transaction Amount:	\$75,658.00
Asset ID:	SHB8711Z	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20131125101245184366		
Vehicle No.:	SHB8711Z		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	25 Nov 2013		
Original Registration Date:	25 Nov 2013		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414ME5452065		
Engine No.:	D4FDDH308771		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2013		
Open Market Value:	\$19,721.00		
Minimum PARF Benefit:	\$7,332.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	25 Nov 2013 10:12:45		
COE No.:	2013112501000903H		
COE Expiry Date:	24 Nov 2021		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$63,297.00		
Lifespan Expiry Date:	24 Nov 2021		
Owner ID Type:	Company		

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

2-Jul-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8711 Z

1 pc	Rear n/s door <i>X repair</i>	\$ 791.00
2 pc	Rear n/s door hinges @ \$34.00 <i>X 50</i>	\$ 68.00
1 pc	Rear n/s fender <i>X repair</i>	\$ 1,205.00
1 pc	Rear windscreen moulding <i>X n</i>	\$ 87.00
1 pc	n/s rocker panel garnish <i>X repair</i>	\$ 286.00
		\$ 2,437.00
Less 10%		
		\$ 2,193.30

S/NETT

1 set	n/s door stickers <i>mc</i>	\$ 100.00
1 pc	Rear n/s fender sticker <i>mc</i>	\$ 60.00
1 set	Sealant <i>X n</i>	\$ 50.00
Sundry		
To dismantle / refit old windscreen glass onto new moulding		\$ 50.00 <i>20</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ 120.00 <i>X n</i>
To labour charge for dismantle and renew the accident damaged parts. To heat/weld & cut rear n/s fender. Including knock-out, straighten, repair, reshape and adjust of the n/s rocker panel garnish, rear n/s door, etc		\$ 180.00 <i>X n</i>
To putty and spray painting on rear n/s door, n/s rocker panel garnish, rear n/s fender		\$ 1,200.00 <i>200</i>
To apply rustproofing on the repaired and replaced panels.		\$ 600.00 <i>500</i>
		\$ 120.00 <i>X n</i>
		\$ 4,673.30

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Kalish (K/K)

2/7/19 1705L
2 P
LH
At the Repair p.k

87
t

0•c
100•+
60•+
0•=
160•*

0•c

20•+
200•+
540•+
=
760•*

760•+
160•+
=
920•*/

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ated to Federation Internationale Des Experts En Automobile

NCE LTD

Ref : CS/FCI19011698/K1td3n2

Date : 08-07-2019



ORE 068877

Code : FCI2

Policy Particulars :- THIRD PARTY CLAIM

I99C

Veh. Inspected

SHB 8711Z

Coverage (\$)

0.00

Excess (\$)

0.00

Claim No. D19004277MFSH

Assign From SERENE

Assign Date

02/07/2019

2. Vehicle Particulars & Condition

Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	KNAGM414ME5452065	Colour	SILVER
Odometer	459883	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R16	HANKOOK	7 mm
L/H Front Tyre	205/65 R16	HANKOOK	7 mm
R/H Rear Tyre	205/65 R16	HANKOOK	7 mm
L/H Rear Tyre	205/65 R16	HANKOOK	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/07/2019	Inspection Date	02/07/2019
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8711Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR N/S DOOR	TO REPAIR SEE LABOUR	791.00	-
2	REAR N/S DOOR HINGES @\$34.00	SERVICEABLE	68.00	-
1	REAR N/S FENDER	TO REPAIR SEE LABOUR	1,205.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	87.00	-
1	N/S ROCKER PANEL GARNISH	TO REPAIR SEE LABOUR	286.00	-
	LESS 10% DISCOUNT		-243.70	-
			2,193.30	-
SPECIAL NETT ITEMS				
1	SET N/S DOOR STICKERS (SN)	NECESSARY	100.00	100.00
1	REAR N/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SET SEALANT (SN)	NOT NECESSARY	50.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			260.00	180.00
LABOUR				
	TO DISMANTLE/REFIT OLD WINDSCREEN GLASS ONTO NEW MOULDING.	NOT NECESSARY	120.00	-
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT/WELD & CUT REAR N/S FENDER. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE N/S ROCKER PANEL GARNISH, REAR N/S DOOR, ETC.		1,200.00	200.00
	TO PUTTY AND SPRAY PAINTING ON REAR N/S DOOR, N/S ROCKER PANEL GARNISH, REAR N/S FENDER.		600.00	540.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			2,220.00	740.00

Report Ref No. CS/FCI19011698/K1td3n2



GRAND TOTAL		4,673.30	920.00
RECOMMENDED COST OF REPAIRS			920.00

Report Ref No. CS/FCI19011698/K1td3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.