

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 7069R

DATE 1/7/2019 15:23

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 544.50
	Front Bumper Bracket Top (RH) ?			\$ 22.40
	Front Bumper Bracket (RH) ?			\$ 24.60
	Headlamp (RH) X			\$ 1,388.00
	Front Fender (RH) X repair			\$ 566.30
	Front Fender Shield (RH) X			\$ 175.90
	Front Fender Retainer X			\$ 24.60
	SUB TOTAL			\$ 2,746.30
	LESS 20%			\$ 549.26
	DISCOUNTED TOTAL			\$ 2,197.04
	Labour Charge			
	Panel Beating			\$ 400.00 200
	Spray Painting Charge		400	\$ 600.00
	Wiring			\$ X 50.00
	Tuff Kote			\$ X 50.00
	TOTAL LABOUR			\$ 1,100.00
	ESTIMATE TOTAL			\$ 3,297.04
Ka hui (VICI) 2/7/19 1130 hr. 2 Dgs 4/5 Alto Rep & Lto KK Auto Consultants hence notify the Repaired of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplier item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				