

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB3953A

DATE: 1. Jul. 2019

MAKE : HYUNDAI

MODEL : IONIQ

DOA: 29. Jun. 2019

EQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER <i>X Rep</i>			\$459.40
1	REAR BUMPER CENTRE MOLDING ASSY <i>—</i>			\$451.25
1	REAR BUMPER LOWER CENTRE MOLDING ASSY <i>X</i>			\$270.10
1	REAR BUMPER REINFORCEMENT <i>?</i>			\$294.80
10	REAR BUMPER CLIPS <i>?</i>		\$2.20	\$22.00
SUB TOTAL				\$1,497.55
LESS 20%				\$299.51
DISCOUNTED TOTAL				\$1,198.04
1	REVERSE SENSOR <i>X</i>			\$135.70
1	REAR NUMBER PLATE <i>—</i>			\$25.00
1	REAR NUMBER PLATE CASING <i>X —</i>			\$30.00
				Nett
				Nett
				Nett
				\$190.70
Labour Charge				
1	Panel Beating			200 \$300.00
1	Spray Painting Charge			200 \$300.00
1	Wiring Charge			X \$50.00
1	Tuff Kote			X \$50.00
1	Remove/refix reverse sensor			X \$100.00
TOTAL LABOUR				\$800.00
ESTIMATE TOTAL				\$2,188.74
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants is hence notify the Repairer of the following:

- To resurvey damaged part(s) during resurvey
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and approved to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Larry Ng

Kalin 10/16

1/7/19

2 hrs

PIP

After Rep in pht