SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACC	SIDE	II S	AL	ΞM	ENI

Date Of Report 29/06/2019 10:49
Date Of Accident 28/06/2019 13:10

Exact Location Of Accident UPPER CHANGI RD EAST FILTERING LEFT INTO SIMEI AVE

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJT8317K

Insured/Policyholder

Name Of Registered Owner HOME CITY RENTAL 1

Co Reg No 53322849B
Email Address NOEMAIL

Mobile Phone No

Alternative Phone No OFFICE-90183679

Vehicle Particulars

Manufacturer HONDA

Model HONDA CIVIC 1.8L 5AT

Exact Purpose for which vehicle was being used at

time of accident

t PVT HIRE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE HIRE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage THIRD PARTY

Fleet Policy NO

Policy Number 5109318831-000005

Cover Note Number 21/6/19-20/6/20

Driver

Name of Driver CHUA KAI WEE, DESMINE

 NRIC No
 S8618572E

 Date Of Birth
 12/06/1986

 Occupation
 INDOOR

 Date Of Driving Pass
 07/02/2006

Driving Experience 13 YEARS AND 4 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-92767273

Fax Number

Contact Number

EMail Address DESMINE.CHUA@GMAIL.COM

Address

BLK 758B WOODLANDS RISE #10-92

Postcode

732785

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

NO

Was any body injured in the Accident? Was any injured conveyed to hospital by

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes.Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER SKETCH ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

FOOTAGE WITH REPAIRER

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHA7324U

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

榮記車廠

WENG KEE MOTOR

BLK 1019, #01-366 YISHUN IND. PARK A, SINGAPORE 768761 TEL: 68541273 FAX: 67568193 EMAIL: wkmotor@ymail.com

DATE: 2-7-2019

REPAIR ESTIMATE

VEHICLE:

SJT 8317 K

MODEL:

Honda Civic

S/n	Description of part	Qty	Estimate	
1	Rear boot lid ()	1	698.80	
2	Rear boot lid round stopper × MM	2	24.00	
3	Rear boot lid long stopper X MM	2	30.00	
4	Rear boot weather strip / TN	1	126.60/	
5	Rear boot lock mechanism / NT	1	116.80 /	
6	Rear boot lid lock catch X MM [M]	1	45.00	
7	Rear boot lid lock catch X NM Rear boot lid light LH/RH * / RM LH X CHTM	^(N) 12	393.34 145-90	
8	Rear boot logo / //(1	45.80	
9	Tailgate emblem 'Civic' / 1 ^{PC}	1	47.60	
10	Tailgate emblem '1.8' / N ² C	1	43.10 /	
11	Tailgate emblem 'i-vtec' / N/C	1	47.60	
12	Rear fender inner trim RH/LH X MM	2	342.30	
13	Rear fender inner trim RH/LH clip - set $\propto MM$	2	80.00	
14	Rear bumper $\nearrow \qquad \emptyset \emptyset$	1	728.90	
15	Rear bumper clip - set / ///	1	60.00 70	
16	Rear bumper side retainer RH/LH / If	. 2	130.00	
17	Rear tail lamp panel RH X M/V	2	256.00	
18	Rear tail lamp RH / CUT	21	534.22 267-11/	
19	Rear tail lamp clip - set / PC	21	60.00 30/	
20	Rear tail lamp lower backet RH/LH X	2	91.40	
21	Rear end panel & / 00 - Pharto.	1	363.30 /	
22	Rear end panel top garnish / Cf.	1	96.80 /	
23	Rear end panel top garnish clip - set / h/c	. 1	40.00 10/	
24	Spare tyre board X MM	1	275.00	
25	Exhaust silencer X	1	594.00	
		Sub-total 1	5,270.56	
	Apple 1	Discount 20%	4,216.45 2928. 31	
	Steve CLKK) With Anjudic 8322 8813 B Cokys	2/7/19.1.	31 pm - 20%	
	5777 8817 # Colors	21.11110 F	2342-64	
	8322 8813 \$ 6 chys		2542-04	
Ch	ve Chin@ KK and o com L/S			
Ry AL Spy				
	M	- 1/7		
	V	- 1		

榮記車戲 WENG KEE MOTOR

BLK 1019, #01-366 YISHUN IND. PARK A, SINGAPORE 768761 TEL: 68541273 FAX: 67568193 EMAIL: wkmotor@yinail.com

26	boot lid sealant / NPC	1	30.00	20 (
27	rear end panel sealant / //(1	30.00	320/
28	Tail lamp sealant X ///	2	20.00	
29	Tail lamp pad X NM	2	20.00	
30	Rear exhaust silencer gasket X	· 1	65.00	
31	Car number plate rear X MM	1	50.00	9
32	Reverse sensor / BR	. 1	250.00	200/
		Sub-total 2	465.00	7
		Parts total	4,681.45	240
				,

	Labour	
33	To straighten and panel beating rear frame members. To	900.00 600
	cut/weld rear RH/LH tail lamp and rear end panel. To remove	too
	and refit above parts.	600
34	To putty, re-spray painting and polish affected areas.	900.00
35	To remove and transfer rear boot lid components.	100.00 30
36	To check and rectify wiring system.	80.00 30
37	To remove and replace reverse sensor and check	80.00 20
38	To remove and replace exhaust silencer	80.00 X
39	Remove and replace interior upholstery	150.00 20
40	To rust proof affected areas.	60.00 JO
	Lab ar total	2,350.00
	Parts & Labour total	7,031.45

P- 2342.64 N- 249 L- 1330 3912.64 L/5-3/30-01 = 3/50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

WENG KEE MOTOR

Signature:

Date: