*/03/2002 ASS, REC, BY:		REF: CS III 1961	HO Etd3	Special	letraction:
Surveyor:	The same of the sa	ASSIGNME			
From (Person)	Gabriel	of <u>A</u>		Dat	re/Time 2 7 3019
Estimated Cos	t:	W-17-17-17-17-17-17-17-17-17-17-17-17-17-	Bill to:		
OD (TP) WS	TP RES / OD	RES/EVA/INV/MV/C	3		
To Inspect Ve	hicle No: ST	T8317 K	3	Insured:	SHA 7324 U
at Workshop r	n/s Weng 1	cee Motor		Tel:	29816818
of BIK tol	9 Vishung	nd PKA #01-366			
Policy No:			Claim No:	MCT	19060729
Sum Insured:			Excess:		
Make of Veh;	development of the second			D.0	P102/3/8C A.D
CA / REV	REP. / REV 2	4 HRS		1	H.O.D. Endorsement:
Date/Time:	27	Person Contacted:	Victor	Vehi	icle (IN)LOUT
Date/Time	Action/Instruct	ion (/) Estimate			
	SHA 73241	0: cs III 10016110	Abn p	11: 4.0.	108 20te
	STT 8319 K	(· ×	AND THE RESIDENCE OF THE PARTY		

REF:

Cheonghoh Law Corporation

(Incorporated with limited liability)
Co. Reg No.201108070G

Blk 53 Chin Swee Road #03-05 . Singapore 160053

Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

In reply please quote our Reference Number

Our Ref: LCH.lg/YIP1-90475,19

01 07 19

BY FAX NO. 62244174 AND BY HAND India International Insurance Pte Ltd 64 Cecil Street #05-00 IOB Building Singapore 049711 BY CERTIFICATE OF POSTING Comfort Transportation Pte Ltd 383 Sin Ming Drive GAS Building Singapore 575717 BY CERTIFICATE OF POSTING

Dear Sirs

We are instructed by Home City Rental 1 to notify you of a road traffic accident on 28.06.19 at about 1:10 pm at Upper Changi Road East / Left to Simei Ave involving our client's vehicle registration number SJT 8317 K and vehicle registration number SHA 7324 U driven by your insured driver/you/your driver at the material time. A copy of the Singapore accident statement filed is available.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

For the avoidance of doubt, our client will be claiming for compensation for loss of use/rental of a replacement vehicle in the instances enumerated in the State Courts Practice Direction Amendment No. 1 of 2016 paragraphs 7.1 and 7.2 of the Appendix C of the Pre-action Protocol for Non-Injury Motor Accident Cases which compensation is additional to any other claim for loss of use/rental of a replacement vehicle which our client may make against your insured and/or your insured's driver and or you/your driver.

Yours faithfully

Cheonghoh Law Corporation

encs:

This is a computer-generated document and requires no signature

cc: client (via e-mail/fax only) - SJT 8317 K

Nivitha (LKK Auto)

From:

Motor Claim - III < motorclaim@iii.com.sg>

Sent:

Tuesday, 2 July 2019 11:27 AM

To:

Cheonghoh Law; 'sur@lkkauto.com'; Admin-D (LKKAuto)

Cc:

Pooi Chin Han Daniel

Subject:

RE: PRS for SJT 8317 K accident involving vehicle SHA 7324 U on 28 June 2019

along Upper Changi Road East / Left to Simei Ave (Our ref: LCH.lg/YIP1-90475.19)

0648_001.pdf Attachments:

Dear Sir / Mdm.

Please conduct a survey on TP vehicle SJT8317K and let us have your report urgently.

This claim will be handled by Daniel.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards, **Gabriel Wee**



64 Cecil Street; #05 - IOB Building Singapore 049711 Tel: 6347 6100, Ext - 248

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]

Sent: 02 July, 2019 10:17 AM

To: Motor Claim - III < motorclaim@iii.com.sg>

Subject: Re: PRS for SJT 8317 K accident involving vehicle SHA 7324 U on 28 June 2019 along Upper Changi Road

East / Left to Simei Ave (Our ref: LCH.lg/YIP1-90475.19)

Dear Sirs.

We refer to the above matter and to your email dated 1 July 2019.

Our client hereby nominate LKK Auto Consultant Pte Ltd of your said email to conduct the prerepair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Kindly contact the person in charge Mr Victor Wong at 81821895 of Weng Kee Motor at Blk 1019 Yishun Industrial Park A #01-366 Singapore 768761 for the said survey of SJTb 8317 K (vehicle in workshop).

Kindly proceed to do the needful.

Veh In- Store

From: roaming26@singtel.com.sg

Subject: Attached Image

Date: 1 July 2019 at 1:48:47 PM SGT

To: "mail@cheonghoh" <mail@cheonghoh.sg>

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission

or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment. India International Insurance Pte Ltd.

Registration No. 198703792-K

81821895

荣記車廠

WENG KEE MOTOR

BLK 1019, #01-366 YISHUN IND. PARK A, SINGAPORE 768761 TEL: 68541273 FAX: 67568193 EMAIL: wkmotor@ymail.com

DATE: 2-7-2019

REPAIR ESTIMATE

VEHICLE:

SJT 8317 K

MODEL:

Honda Civic

S/n	Description of part	Qty	Estimate	
1	Rear boot lid (/ 00	1	698.80 /	
2	Rear boot lid round stopper × MM	2	24.00	
3	Rear boot lid long stopper X MM	2	30.00	
4	Rear boot weather strip / TN	1	126.60/	
5	Rear boot lock mechanism / NT	1	116.80 /	
6	Rear boot lid lock catch X MM , CMT	1	45.00	
7	Rear boot lid lock catch X MM Rear boot lid light LH/RH * / RM LH X COTN	1/2	393.34	145-902
8	Rear boot logo / //	1	45.80	
9	Tailgate emblem 'Civic' / 1 ^{PC}	1	47.60	
10	Tailgate emblem '1.8' / 12'C	1	43.10/	
11	Tailgate emblem 'i-vtec' / //C	1	47.60/	
12	Rear fender inner trim RH/LH X MM	2	342.30	
13	Rear fender inner trim RH/LH clip - set × MM	2	80.00	
14	Rear bumper / 10	1	728.90/	/
15	Rear bumper clip - set / //	1	60.00	70/
16	Rear bumper side retainer RH/LH	2	130.00 /	
17	Rear tail lamp panel RH X MV	2	256.00	
18	Rear tail lamp RH / CVT	21		267-11/
19	Rear tail lamp clip - set / NC	21	60.00	70/
20	Rear tail lamp lower backet RH/LH X NM	2	91.40	
21	Rear end panel # 1 / 00 - Phon .	1	363.30 /	
22	Rear end panel top garnish / CRV	1	96.80 /	Course Course
23	Rear end panel top garnish clip - set / //c	1	40.00	10/
24	Spare tyre board X NV	1	275.00	
25	Exhaust silencer X NN	1	594.00	
	(1)	Sub-total 1	5,270.56	
	1 Apple	Discount 20%	4,216.45	2928.31
	Steve CLKK) Wil Aproduc	2/7/19.1.	70 pm	_ 201/2
	C777 8817 # 1 chus	-11/11/11	J. J. I	and the second second
	8322 8813 8 Cokys			2342-64
01	eve chin@ IKK owlo-com L/S			
37	D AL	· G		
	M AF	- 17		
	V			

榮 記 車 廠

WENG KEE MOTOR

BLK 1019, #01-366 YISHUN IND. PARK A, SINGAPORE 768761 TEL: 68541273 FAX: 67568193 EMAIL: wkmotor@yinail.com

26	boot lid sealant / / //c	1	30.00	20/
27	rear end panel sealant / n/c	1	30.00	220/
28	Tail lamp sealant X ///	2	20.00	
29	Tail lamp pad X NM	2	20.00	
30	Rear exhaust silencer gasket × MM	I	65.00	
31	Car number plate rear X MM	- E	50.00	
32	Reverse sensor / BR	1	250.00	200/
		Sub-total 2	465.00	
		Parts total	4,681.45	240

-	a	m	n		-
	464	w	v	м	

33	To straighten and panel beating rear frame members. To cut/weld rear RH/LH tail lamp and rear end panel. To remove and refit above parts.	900.00	600
34	To putty, re-spray painting and polish affected areas.	900.00	500
35	To remove and transfer rear boot lid components.	100.00	30
36	To check and rectify wiring system.	80.00	30
37	To remove and replace reverse sensor and check	80.00	20
38	To remove and replace exhaust silencer	80.00	X
39	Remove and replace interior upholstery	150.00	20
40	To rust proof affected areas.	60.00	30
	Labour total	2,350.00	

	Parts & Labour total	7,031.45	
)_ 2342.64			1330
_ 249			

P- 2342.64 N- 249 L- 1330 3912.64 LS- 3130.01 = 3150

1. 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

WENG KEE MOTOR

Signature:

Date: