

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

LI WEIWEN, KELVIN
c/o 46 Lenton Plain
Singapore 786548

Not Notified
U/Sing & ?
Resurvey After Painting
4-5 days

Date: 1/7/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA HARRIER / SLF2280X		
1 pc	front door LH	<i>By/way</i> 1,865.40 ✓
1 pc	front door chrome moulding LH	<i>net</i> 367.10 ✓
1 pc	front fender LH	<i>By</i> 764.50 ✓
1 pc	front fender dust cover LH	<i>DI</i> 291.10 ✓
1 pc	front knuckle LH	577.40 ?
1 pc	front lower arm LH	434.10 ?
1 pc	front wheel bearing LH	365.70 ?
1 pc	front wheel hub LH	306.10 ?
1 pc	front steering tie rod LH	<i>sum</i> 246.40 X
1 pc	front steering tie rod joint LH	<i>sum</i> 195.60 X
1 pc	front side mirror assy	<i>net/ent</i> 876.40 ✓
sub-total		6289.80
less 25%		1572.45
sub-total		4717.35
1 set	door visor	<i>150.00</i> <i>net</i> 400.00 ✓
1 pc	alloy rim <i>P.1</i>	<i>net</i> 950.00 ✓
1 litre	transmission fluid ATF	<i>net</i> 45.00 X
sub-total		6112.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

	balance brought forward	6,112.35
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	450 800.00
	To check wiring system.	20 40.00
	To remove and install front undercarriage parts to enable repair.	? 260.00
	To machine press wheel bearing.	? 40.00
	To perform 4 wheels computerised alignment.	60 85.00
	To apply putty and spray painting on affected areas.	440 750.00
	To replace alloy rims and perform wheel balancing.	20 40.00
	Total	8,127.35