



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

SLC STERLING LAW CORPORATION

Ref : CC4/LPC19011730/Kha3q2

Advocates & Solicitors

137 Telok Ayer Street #07-05

Hokkien Huay Kuan Building Singapore 068602

Date : 15-04-2020



ON BEHALF OF NG PENG GIAM

Code : L167

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SKA 9310K
Policy No.	Coverage (\$)	0.00
Claim No. SS.19.CIV.20198620.A1251	Excess (\$)	0.00
Assign From	Assign Date	02/07/2019

#### 2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E250 (A)	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WDD2120472A366697	Colour	METALLIC BROWN
Odometer	181921	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40 R18	CONTINENTAL	8 mm
L/H Front Tyre	245/40 R18	CONTINENTAL	8 mm
R/H Rear Tyre	245/40 R18	CONTINENTAL	8 mm
L/H Rear Tyre	245/40 R18	CONTINENTAL	8 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

#### 5. General Information

Accident Date	01/07/2019	Inspection Date	08/07/2019
Survey held at	TROPICAL TECH AUTOMOBILE SERVICES BLK 5032, ANG MO KIO AVENUE 3 #01-303 IND. PARK 2 SINGAPORE 569535		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------