

Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **Lonpac Insurance Bhd**
101 Thomson Road,
#18-01 United Square,
S'pore 307591

Attn : Attention : Motor Claims Third Party Department
Tel : Tel : 62507388
Fax : Fax : 62532058

Estimate bill : TT 46 / 19 / TP / WT

Registration No : SKA9310K

Make / model : MB E250 (212)

Mileage : Date : 02 / 07 / 2019

TRAFFIC CHAIN ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SKA9310K, GBB9095H AND JSR6111 ALONG BOUNDARY RD TWDS LOR CHUAN ON 01 JULY 2019 AT ABOUT 1730 HRS.

2pcs	Rear boot lower stopper garnish	(Each \$46.00)	\$	12	92.00	X
2pcs	Rear boot reflector	(Each \$405.00)	\$	12	810.00	X
1pc	Rear tail-lamp (RH)		\$		756.00	?
2pcs	Rear tail-lamp lower brackets	(Each \$111.00)	\$		222.00	?
1pc	Rear end panel		\$	12	1,673.00	X
1pc	Rear bumper		\$	cm	2,239.00	?
2pcs	Rear bumper chrome mouldings (Side)	(Each \$143.00)	\$	12	286.00	?
1pc	Rear bumper chrome moulding (Centre)		\$	12	189.00	?
4pcs	Rear bumper parktronic sensors	(Each \$311.00)	\$	12	1,244.00	4
4pcs	Rear bumper parktronic sensor seal rings	(Each \$13.00)	\$		52.00	?
1pc	Rear bumper towing cover		\$	12	87.00	X
2pcs	Rear bumper lower brackets	(Each \$27.00)	\$		54.00	?
1pc	Rear bumper lower spoiler		\$	disl	702.00	?
2pcs	Rear bumper side brackets	(Each \$60.00)	\$		120.00	?
1pc	Rear bumper reinforcement		\$		950.00	?
1pc	Rear silencer box		\$	12	2,266.00	X
2pcs	Rear silencer box chrome rings	(Each \$243.00)	\$	12	486.00	X
Sub total :			\$		12,228.00	
Less 10% discount :			\$		1,222.80	
A total :			\$		11,005.20	
Total amount of Page 1 :			\$		11,005.20	

Tropical Tech Automobile Services

*Not withold
11 Day @?
Penny After Pain
3 days*

(Authorised Signature)
William Tan



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **Lonpac Insurance Bhd**
101 Thomson Road,
#18-01 United Square,
S'pore 307591

Attn : Attention : Motor Claims Third Party Department
Tel : Tel : 62507388
Fax : Fax : 62532058

Estimate bill : TT 46 / 19 / TP / WT

Registration No : SKA9310K

Make / model : MB E250 (212)

Mileage : Date : 02 / 07 / 2019

TRAFFIC CHAIN ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SKA9310K, GBB9095H AND JSR6111 ALONG BOUNDARY RD TWDS LOR CHUAN ON 01 JULY 2019 AT ABOUT 1730 HRS.

Remove and transfer rear bumper & necessary attachment spare part items.

Remove and refit rear boot lower stopper garnish, rear boot reflector, rear tail-lamp (RH), rear tail-lamp lower brackets, rear bumper, rear bumper chrome mouldings (Side), rear bumper chrome moulding (Centre), rear bumper parktronic sensors, rear bumper parktronic sensor seal rings, rear bumper towing cover, rear bumper lower brackets, rear bumper lower spoiler, rear bumper side brackets, rear bumper reinforcement, rear silencer box, rear silencer box chrome rings.

Heat / weld / cut / renew rear end panel, heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Alignment Jack.

To check and refit rear tail lamp wiring harness.

Tuff kote rear damaged portion.

Putty / primer application, spray painting rear end panel, rear bumper, rear bumper parktronic sensors, rear bumper towing cover.

Balance amount bought from Page 1 :

Grand final amount :

	300
\$	1,400.00
	20
\$	40.00
\$	20 150.00 X
	450
\$	1,200.00
\$	11,005.20
\$	13,795.20

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

