

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER DIS ✓	0.00	250.00	+10.00	275.00
2	1	REAR BUMPER SIDE RETAINER LH self ✓	0.00	35.00	+10.00	38.50
3	1	REAR BUMPER SIDE RETAINER RH self ✓	0.00	35.00	+10.00	38.50
4	1	REAR BUMPER BRACKET LH 11X ✓	0.00	45.00	+10.00	49.50
5	1	REAR BUMPER BRACKET RH self ✓	0.00	45.00	+10.00	49.50
6	1	REAR BUMPER STAY LH NS & ✓	0.00	70.00	+10.00	77.00
7	1	REAR BUMPER STAY RH NS & ✓	0.00	70.00	+10.00	77.00
8	1	REAR BUMPER REINFORCEMENT AS a ✓	0.00	187.00	+10.00	205.70
9	1	BOOT LID Buc ✓	0.00	370.00	+10.00	407.00
10	1	BOOT LID HINGES LH 2X ✓	0.00	65.00	+10.00	71.50
11	1	BOOT LID HINGES RH 2X ✓	0.00	65.00	+10.00	71.50
12	1	BOOT LID LOGO 111 ✓	0.00	45.00	+10.00	49.50
13	1	BOOT LID LATIO EMBLEM 111 ✓	0.00	55.00	+10.00	60.50
14	1	BOOT LID LOCK TW1 ✓	0.00	83.00	+10.00	91.30
15	1	BOOT LID LOCK CATCH 11X ✓	0.00	0.00	0.00	0.00
16	1	BOOT LID RUBBER TW1 ✓	0.00	83.00	+10.00	91.30
17	1	BOOT LID INNER TRIM BOARD 11X ✓	0.00	97.00	+10.00	106.70
18	1	BOOT LID TOP SPOILER 2X ✓	0.00	245.00	+10.00	269.50
19	1	REAR NUMBER PLATE OUTER CHROME 11X ✓	0.00	137.00	+10.00	150.70
20	2	REAR NUMBER PLATE LAMP 11X ✓	0.00	116.00	+10.00	127.60
21	1	REAR TAILLAMP LH 300 ✓	0.00	137.00	+10.00	150.70
22	1	REAR TAILLAMP RH 300 ✓	0.00	137.00	+10.00	150.70
23	1	REAR TAILLAMP PANEL LH self ✓	0.00	117.00	+10.00	128.70
24	1	REAR TAILLAMP PANEL RH self ✓	0.00	117.00	+10.00	128.70
25	1	REAR TAILLAMP LOWER BRACKET LH 111 ✓	0.00	24.00	+10.00	26.40
26	1	REAR TAILLAMP LOWER BRACKET RH 111 ✓	0.00	24.00	+10.00	26.40
27	1	REAR FENDER LH 2X ✓	0.00	576.00	+10.00	633.60
28	1	REAR FENDER RH self/111 ✓	0.00	576.00	+10.00	633.60
29	1	REAR FENDER INNER SHIELD LH 11X ✓	0.00	26.00	+10.00	28.60
30	1	REAR FENDER INNER SHIELD RH 11X ✓	0.00	26.00	+10.00	28.60
31	1	REAR FENDER INNER TRIM BOARD LH 11X ✓	0.00	230.00	+10.00	253.00
32	1	REAR FENDER INNER TRIM BOARD RH 11X ✓	0.00	230.00	+10.00	253.00
33	1	REAR WINDSCREEN GLASS MOULDING 111 ✓	0.00	60.00	+10.00	66.00
34	1	REAR END PANEL 300/20 ✓	0.00	224.00	+10.00	246.40
35	1	REAR END PANEL INNER GARNISH TW1 ✓	0.00	58.00	+10.00	63.80
36	1	REAR END PANEL KEYLESS SENSOR 11X ✓	0.00	85.00	+10.00	93.50
37	1	REAR SPARE TYRE PANEL 2X ✓	0.00	360.00	+10.00	396.00
38	1	REAR SPARE TYRE BOARD ? ✓	0.00	255.00	+10.00	280.50
39	1	FRONT BUMPER 20 ✓	0.00	276.00	+10.00	303.60
40	1	FRONT BUMPER SIDE RETAINER LH self ✓	0.00	15.00	+10.00	16.50
41	1	FRONT BUMPER SIDE RETAINER RH self ✓	0.00	15.00	+10.00	16.50
42	1	FRONT BUMPER BRACKET LH ? ✓	0.00	95.00	+10.00	104.50
43	1	FRONT BUMPER BRACKET RH ? ✓	0.00	95.00	+10.00	104.50
44	1	FRONT BUMPER LOWER GRILLE ? ✓	0.00	110.00	+10.00	121.00
45	2	FRONT BUMPER FOG LAMP 11X ✓	0.00	440.00	+10.00	484.00
46	1	FRONT BUMPER INNER SPONGE TW1 ✓	0.00	98.00	+10.00	107.80
47	1	FRONT BUMPER REINFORCEMENT 20 ✓	0.00	180.00	+10.00	198.00
48	1	FRONT BUMPER TOWING COVER 11 ✓	0.00	22.00	+10.00	24.20
49	1	FRONT GRILLE ? ✓	0.00	240.00	+10.00	264.00
50	1	FRONT GRILLE CHROME MOULDING 111 ✓	0.00	95.00	+10.00	104.50
51	1	FRONT GRILLE LOGO 111 ✓	0.00	44.00	+10.00	48.40
52	1	FRONT BUMPER UNDER COVER 11X ✓	0.00	110.00	+10.00	121.00
53	1	FRONT HEADLAMP LH 111 ✓	0.00	277.00	+10.00	304.70

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : AXA INSURANCE SINGAPORE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTHQ/TP/1906/018
Policy No:	5087378448-01	Date of Loss:	28/06/2019
Vehicle Reg. No.:	SJT5984D	Driveable?	yes
Driver Age:	29/08/2019	Third Party Vehicle No.:	SLZ9593S, SGB3097H,SLB3881B, SHD6950C
Any Injuries?	no	Contact No:	
Insured/Claimant:	TAY TSE TUAN	Driver:	TAY TSE TUAN

Make/Model:	Nissan, Latio - JN1FAAC11Z0010170	Vehicle Reg. Date:	21/10/2009
Vehicle Colour:	WHITE	Engine Number:	HR15082040B
Chassis No:	JN1BAAC11Z0021073	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss: CHAIN COLLISION
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

Amount

Parts	11,134.20
Miscellaneous Items	1,412.00
Labour	3,410.00
Paintwork Labour	1,785.00
Towing	0.00

Gross Total(S\$):	17,741.20
GST 7.00%(S\$):	1,241.88
Nett Amount(S\$):	18,983.08

This claim is handled by: Vinnie Lim M H

Auto Consultants hence notify
Repairer of the following:
- resurvey before/after spray painting
- display damaged part(s) during resurvey
- parts prices are subject to confirmation
- third party survey is on a "Without Prejudice" basis
- no illegal modification(s) is allowed
- complementary item(s) must be resurveyed and
witnessed by Repairer
Signature:

not Authorised
L/LC Marcus
3/7/19
TOTAL 1055
Nett repair \$2500?
Tel: 62563561

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
54	1	FRONT HEADLAMP RH <i>inc</i>	0.00	277.00	+10.00	304.70
55	1	FRONT HEADLAMP LOWER BRACKET LH <i>11x</i>	0.00	55.00	+10.00	60.50
56	1	FRONT HEADLAMP LOWER BRACKET RH <i>11x</i>	0.00	55.00	+10.00	60.50
57	1	FRONT HEADLAMP PANEL LH <i>1x</i>	0.00	84.00	+10.00	92.40
58	1	FRONT HEADLAMP PANEL RH <i>1x</i>	0.00	84.00	+10.00	92.40
59	1	BONNET <i>inc</i>	0.00	360.00	+10.00	396.00
60	1	BONNET HINGES LH <i>11x</i>	0.00	25.00	+10.00	27.50
61	1	BONNET HINGES RH <i>11x</i>	0.00	25.00	+10.00	27.50
62	1	BONNET LOCK <i>721</i>	0.00	45.00	+10.00	49.50
63	1	BONNET INSULATOR <i>11x</i>	0.00	95.00	+10.00	104.50
64	1	FRONT BRACE PANEL <i>inc</i>	0.00	30.00	+10.00	33.00
65	1	FRONT SUPPORT PANEL <i>1x</i>	0.00	165.00	+10.00	181.50
66	1	FRONT FENDER LH <i>1x</i>	0.00	175.00	+10.00	192.50
67	1	FRONT FENDER RH <i>1x</i>	0.00	175.00	+10.00	192.50
68	1	FRONT FENDER INNER SHIELD LH <i>11x</i>	0.00	58.00	+10.00	63.80
69	1	FRONT FENDER INNER SHIELD RH <i>11x</i>	0.00	58.00	+10.00	63.80
70	1	FRONT DOOR LH <i>1x</i>	0.00	0.00	0.00	0.00
71	1	FRONT DOOR RH <i>1x</i>	0.00	0.00	0.00	0.00
72	1	AIR CON CONDENSER <i>11x</i>	0.00	169.00	+10.00	185.90
73	2	AIR CON CONDENSER AIR GUIDE <i>?</i>	0.00	110.00	+10.00	121.00
74	1	RADIATOR <i>11x</i>	0.00	325.00	+10.00	357.50
75	1	RADIATOR FAN COWLING <i>11x</i>	0.00	240.00	+10.00	264.00
76	2	RADIATOR BRACKET <i>11x</i>	0.00	40.00	+10.00	44.00

Total Parts (S\$) 11,134.20

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS (1 SET) <i>inc 30</i>	0.00	45.00	0.00	45.00
2	1	REAR BUMPER SENSORS (1 SET) <i>shld 200</i>	0.00	220.00	0.00	220.00
3	1	REAR BUMPER LOWER SKIRT <i>dis</i>	0.00	380.00	0.00	380.00
4	1	REAR NUMBER PLATE <i>2nd 40</i>	0.00	45.00	0.00	45.00
5	2	REAR TAILLAMP GASKET <i>inc</i>	0.00	40.00	0.00	40.00
6	2	REAR FENDER INNER SHIELD CLIPS <i>11x</i>	0.00	76.00	0.00	76.00
7	1	REAR WINDSCREEN SEALANT <i>inc 40</i>	0.00	60.00	0.00	60.00
8	1	FRONT NUMBER PLATE <i>3rd 40</i>	0.00	45.00	0.00	45.00
9	1	FRONT BUMPER CLIPS <i>inc 30</i>	0.00	45.00	0.00	45.00
10	1	FRONT BUMPER LOWER SKIRT <i>dis</i>	0.00	380.00	0.00	380.00
11	2	FRONT FENDER INNER SHIELD CLIPS <i>11x</i>	0.00	76.00	0.00	76.00

Sub Total (S\$) 1,412.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 <i>inc</i>
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00 <i>50</i>
3	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	100.00	0.00	100.00 <i>—</i>
4	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	100.00	0.00	100.00 <i>60</i>
5	1	To Pressure Test Air Con Condenser and Radiator For Leakage.	120.00	120.00	0.00	120.00 <i>100</i>
6	1	To Remove & Refit air-con compressor, air-con	180.00	180.00	0.00	180.00 <i>—</i>

Estimates On Labour						
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
		motor, condenser, pipes & vacuum, including refilling of gas.				
7	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	2,800.00	2,800.00	0.00	2,800.00
						1600
Gross Labour Cost (S\$)						3,410.00

Estimates On Paint Work Labour						
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	60.00	0.00	60.00 ✓
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	45.00	0.00	45.00 X
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	80.00	80.00	0.00	80.00 ✓
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	1,600.00	1,600.00	0.00	1,600.00
						1400
Gross Labour Cost (S\$)						1,785.00

< END OF ESTIMATES >