

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : AXA INSURANCE SINGAPORE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTHQ/TP/1906/018
Policy No:	5087378448-01	Date of Loss:	28/06/2019
Vehicle Reg. No.:	SJT5984D	Driveable?	yes
Driver Age:	29/08/2019	Third Party Vehicle No.:	SLZ9593S, SGB3097H,SLB3881B, SHD6950C
Any Injuries?	no	Contact No:	
Insured/Claimant:	TAY TSE TUAN	Driver:	TAY TSE TUAN

Make/Model:	Nissan, Latio - JN1FAAC11Z0010170	Vehicle Reg. Date:	21/10/2009
Vehicle Colour:	WHITE	Engine Number:	HR15082040B
Chassis No:	JN1BAAC11Z0021073	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss CHAIN COLLISION
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

	Amount
Parts	11,134.20
Miscellaneous Items	1,412.00
Labour	3,410.00
Paintwork Labour	1,785.00
Towing	0.00

Gross Total(S\$):	17,741.20
GST 7.00%(S\$):	1,241.88
Nett Amount(S\$):	18,983.08

This claim is handled by: Vinnie Lim M H

Auto Consultants hence notify
Repairer of the following:
Resurvey before/after spray painting
display damaged part(s) during resurvey
parts prices are subject to confirmation
third party survey is on a "Without Prejudice" basis
No illegal modification(s) is allowed
complementary item(s) must be resurveyed and
acknowledged by Repairer
Signature:

not Authorised
L&L Marcus
3/7/19
TOTAL 1055
Nett repair \$2500?
Tel: 62563561

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER <i>DIS</i>	0.00	250.00	+10.00	275.00
2	1	REAR BUMPER SIDE RETAINER LH <i>sent</i>	0.00	35.00	+10.00	38.50
3	1	REAR BUMPER SIDE RETAINER RH <i>sent</i>	0.00	35.00	+10.00	38.50
4	1	REAR BUMPER BRACKET LH <i>11X</i>	0.00	45.00	+10.00	49.50
5	1	REAR BUMPER BRACKET RH <i>sent</i>	0.00	45.00	+10.00	49.50
6	1	REAR BUMPER STAY LH <i>NS &</i>	0.00	70.00	+10.00	77.00
7	1	REAR BUMPER STAY RH <i>NS &</i>	0.00	70.00	+10.00	77.00
8	1	REAR BUMPER REINFORCEMENT <i>AS &</i>	0.00	187.00	+10.00	205.70
9	1	BOOT LID <i>Buc</i>	0.00	370.00	+10.00	407.00
10	1	BOOT LID HINGES LH <i>2X</i>	0.00	65.00	+10.00	71.50
11	1	BOOT LID HINGES RH <i>2X</i>	0.00	65.00	+10.00	71.50
12	1	BOOT LID LOGO <i>nei</i>	0.00	45.00	+10.00	49.50
13	1	BOOT LID LATIO EMBLEM <i>nei</i>	0.00	55.00	+10.00	60.50
14	1	BOOT LID LOCK <i>twi</i>	0.00	83.00	+10.00	91.30
15	1	BOOT LID LOCK CATCH <i>11X</i>	0.00	0.00	0.00	0.00
16	1	BOOT LID RUBBER <i>twi</i>	0.00	83.00	+10.00	91.30
17	1	BOOT LID INNER TRIM BOARD <i>11X</i>	0.00	97.00	+10.00	106.70
18	1	BOOT LID TOP SPOILER <i>2X</i>	0.00	245.00	+10.00	269.50
19	1	REAR NUMBER PLATE OUTER CHROME <i>11X</i>	0.00	137.00	+10.00	150.70
20	2	REAR NUMBER PLATE LAMP <i>11X</i>	0.00	116.00	+10.00	127.60
21	1	REAR TAILLAMP LH <i>3no</i>	0.00	137.00	+10.00	150.70
22	1	REAR TAILLAMP RH <i>3no</i>	0.00	137.00	+10.00	150.70
23	1	REAR TAILLAMP PANEL LH <i>sent</i>	0.00	117.00	+10.00	128.70
24	1	REAR TAILLAMP PANEL RH <i>sent</i>	0.00	117.00	+10.00	128.70
25	1	REAR TAILLAMP LOWER BRACKET LH <i>ene</i>	0.00	24.00	+10.00	26.40
26	1	REAR TAILLAMP LOWER BRACKET RH <i>ene</i>	0.00	24.00	+10.00	26.40
27	1	REAR FENDER LH <i>2X</i>	0.00	576.00	+10.00	633.60
28	1	REAR FENDER RH <i>sent/buc</i>	0.00	576.00	+10.00	633.60
29	1	REAR FENDER INNER SHIELD LH <i>11X</i>	0.00	26.00	+10.00	28.60
30	1	REAR FENDER INNER SHIELD RH <i>11X</i>	0.00	26.00	+10.00	28.60
31	1	REAR FENDER INNER TRIM BOARD LH <i>11X</i>	0.00	230.00	+10.00	253.00
32	1	REAR FENDER INNER TRIM BOARD RH <i>11X</i>	0.00	230.00	+10.00	253.00
33	1	REAR WINDSCREEN GLASS MOULDING <i>nei</i>	0.00	60.00	+10.00	66.00
34	1	REAR END PANEL <i>body 20</i>	0.00	224.00	+10.00	246.40
35	1	REAR END PANEL INNER GARNISH <i>twi</i>	0.00	58.00	+10.00	63.80
36	1	REAR END PANEL KEYLESS SENSOR <i>11X</i>	0.00	85.00	+10.00	93.50
37	1	REAR SPARE TYRE PANEL <i>2X</i>	0.00	360.00	+10.00	396.00
38	1	REAR SPARE TYRE BOARD <i>250</i>	0.00	255.00	+10.00	280.50
39	1	FRONT BUMPER <i>20</i>	0.00	276.00	+10.00	303.60
40	1	FRONT BUMPER SIDE RETAINER LH <i>sent</i>	0.00	15.00	+10.00	16.50
41	1	FRONT BUMPER SIDE RETAINER RH <i>sent</i>	0.00	15.00	+10.00	16.50
42	1	FRONT BUMPER BRACKET LH <i>250</i>	0.00	95.00	+10.00	104.50
43	1	FRONT BUMPER BRACKET RH <i>250</i>	0.00	95.00	+10.00	104.50
44	1	FRONT BUMPER LOWER GRILLE <i>250</i>	0.00	110.00	+10.00	121.00
45	2	FRONT BUMPER FOG LAMP <i>11X</i>	0.00	440.00	+10.00	484.00
46	1	FRONT BUMPER INNER SPONGE <i>twi</i>	0.00	98.00	+10.00	107.80
47	1	FRONT BUMPER REINFORCEMENT <i>20</i>	0.00	180.00	+10.00	198.00
48	1	FRONT BUMPER TOWING COVER <i>nei</i>	0.00	22.00	+10.00	24.20
49	1	FRONT GRILLE <i>250</i>	0.00	240.00	+10.00	264.00
50	1	FRONT GRILLE CHROME MOULDING <i>ene</i>	0.00	95.00	+10.00	104.50
51	1	FRONT GRILLE LOGO <i>nei</i>	0.00	44.00	+10.00	48.40
52	1	FRONT BUMPER UNDER COVER <i>11X</i>	0.00	110.00	+10.00	121.00
53	1	FRONT HEADLAMP LH <i>ene</i>	0.00	277.00	+10.00	304.70

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
54	1	FRONT HEADLAMP RH <i>1 ne</i>	0.00	277.00	+10.00	304.70
55	1	FRONT HEADLAMP LOWER BRACKET LH <i>11 X</i>	0.00	55.00	+10.00	60.50
56	1	FRONT HEADLAMP LOWER BRACKET RH <i>11 X</i>	0.00	55.00	+10.00	60.50
57	1	FRONT HEADLAMP PANEL LH <i>1 X</i>	0.00	84.00	+10.00	92.40
58	1	FRONT HEADLAMP PANEL RH <i>1 X</i>	0.00	84.00	+10.00	92.40
59	1	BONNET <i>1 ne</i>	0.00	360.00	+10.00	396.00
60	1	BONNET HINGES LH <i>11 X</i>	0.00	25.00	+10.00	27.50
61	1	BONNET HINGES RH <i>11 X</i>	0.00	25.00	+10.00	27.50
62	1	BONNET LOCK <i>1 ne</i>	0.00	45.00	+10.00	49.50
63	1	BONNET INSULATOR <i>11 X</i>	0.00	95.00	+10.00	104.50
64	1	FRONT BRACE PANEL <i>1 ne</i>	0.00	30.00	+10.00	33.00
65	1	FRONT SUPPORT PANEL <i>1 X</i>	0.00	165.00	+10.00	181.50
66	1	FRONT FENDER LH <i>1 X</i>	0.00	175.00	+10.00	192.50
67	1	FRONT FENDER RH <i>1 X</i>	0.00	175.00	+10.00	192.50
68	1	FRONT FENDER INNER SHIELD LH <i>11 X</i>	0.00	58.00	+10.00	63.80
69	1	FRONT FENDER INNER SHIELD RH <i>11 X</i>	0.00	58.00	+10.00	63.80
70	1	FRONT DOOR LH <i>1 X</i>	0.00	0.00	0.00	0.00
71	1	FRONT DOOR RH <i>1 X</i>	0.00	0.00	0.00	0.00
72	1	AIR CON CONDENSER <i>11 X</i>	0.00	169.00	+10.00	185.90
73	2	AIR CON CONDENSER AIR GUIDE <i>11 X</i>	0.00	110.00	+10.00	121.00
74	1	RADIATOR <i>11 X</i>	0.00	325.00	+10.00	357.50
75	1	RADIATOR FAN COWLING <i>11 X</i>	0.00	240.00	+10.00	264.00
76	2	RADIATOR BRACKET <i>11 X</i>	0.00	40.00	+10.00	44.00

Total Parts (\$\$)
11,134.20
Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS (1 SET) <i>1 ne 30</i>	0.00	45.00	0.00	45.00
2	1	REAR BUMPER SENSORS (1 SET) <i>shld 200</i>	0.00	220.00	0.00	220.00
3	1	REAR BUMPER LOWER SKIRT <i>11 X</i>	0.00	380.00	0.00	380.00
4	1	REAR NUMBER PLATE <i>1 ne 40</i>	0.00	45.00	0.00	45.00
5	2	REAR TAILLAMP GASKET <i>1 ne</i>	0.00	40.00	0.00	40.00
6	2	REAR FENDER INNER SHIELD CLIPS <i>11 X</i>	0.00	76.00	0.00	76.00
7	1	REAR WINDSCREEN SEALANT <i>1 ne 40</i>	0.00	60.00	0.00	60.00
8	1	FRONT NUMBER PLATE <i>1 ne 40</i>	0.00	45.00	0.00	45.00
9	1	FRONT BUMPER CLIPS <i>1 ne 30</i>	0.00	45.00	0.00	45.00
10	1	FRONT BUMPER LOWER SKIRT <i>11 X</i>	0.00	380.00	0.00	380.00
11	2	FRONT FENDER INNER SHIELD CLIPS <i>11 X</i>	0.00	76.00	0.00	76.00

Sub Total (\$\$)
1,412.00
Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00
3	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	100.00	0.00	100.00
4	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	100.00	0.00	100.00
5	1	To Pressure Test Air Con Condenser and Radiator For Leakage.	120.00	120.00	0.00	120.00
6	1	To Remove & Refit air-con compressor, air-con	180.00	180.00	0.00	180.00

3

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
		motor, condenser, pipes & vacuum, including refilling of gas.				
7	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	2,800.00	2,800.00	0.00	2,800.00

1600

Gross Labour Cost (\$\$)**3,410.00****Estimates On Paint Work Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	60.00	0.00	60.00 ✓
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	45.00	0.00	45.00 X
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	80.00	80.00	0.00	80.00 ✓
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	1,600.00	1,600.00	0.00	1,600.00

1400

Gross Labour Cost (\$\$)**1,785.00**

< END OF ESTIMATES >

4