

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0805/2019/TG
11-Jul-19
CHANG
1 of 1
SDJ 422 R
AUDI A4 SEDAN 2.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	REAR FENDER SIDE REINFORCEMENT - LH/RH <i>bt</i>	2 \$ 374.00	
2	REAR LID HINGE GUIDE COVER - LH/RH	2 \$ 50.00	
3	REAR LID ANTI-THEFT GUARD COVER <i>bt</i>	\$ 58.00	
4	REAR LID LICENCE PLATE LIGHT	2 \$ 191.00	
5	SPARE WHEEL MOUNTING	\$ 122.00	
6	BATTERY CLAMPING STRIP	\$ 12.00	
7	LUGGAGE COMPARTMENT TRIM - LH/RH <i>cut</i>	2 \$ 1,433.00	
8	REAR SPARE WHEEL HOUSING INSULATION <i>see</i>	\$ 126.00	
9	BATTERY CONSOLE	\$ 40.00	
10	REAR FENDER SIDE REINFORCEMENT SUPPORT - LH/RH <i>see</i>	2 \$ 178.00	
GRAND TOTAL			\$ 2,584.00

For Premium Automobiles Pte Ltd

Rusul
12/07/19



Authorised Signature

WIP No: 58881 (AW)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0805/2019/TG
Date	:	2-Jul-19

Vehicle IN workshop. Kindly arrange for survey.

Your Insured Veh No: SLR 7930 H

AXA Insurance Singapore Pte Ltd

6 Shenton Way
#27-01 AXA Tower
Singapore 068811

Attn: Motor Claims Dept
Tel: 6880 4602 - Fax 6880 4838

Owner's Name	:	Mr. David Jeremiah Seah Hok Heng
Address	:	12 Jalan Mariam Singapore 509299
Telephone	:	HP +65 96703434
Type of Claim	:	Third Party Claim
Policy No.	:	1800120110
Vehicle No	:	SDJ 422 R
Model Code	:	A4 Sedan 2.0 TFSI S Tronic
Model / Year	:	Oct-18
Engine No	:	CVK 066822
Chassis No	:	WAUZZZF43JA216011
Mileage	:	8759
Date In	:	30-Jun-19
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	30-Jun-19
Place of Accident	:	Along West Coast Highway Towards Keppel Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDJ 422 R

S/N	Nature of Jobs			Estimated Charges
1	To tow back from accident scene.	s/n	\$	280.00 ✓
2	To carry out first measurement test on car o-liner.	s/n	\$	800.00 ?
3	To remove and transfer rear parking aid and rear lid kick sensor.	s/n	\$	360.00 ✓
4	To renew both rear 1/4 glass and rear windscreen to facilitate fender renewal.	s/n	\$	780.00 550
5	To renew and reinstall rear lid's convenience lock system, wire harness for tail lights and rear wiper assy.	s/n	\$	480.00 ✓
6	To dislodge and reinstall rer wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment. Inspect for damage and renew where necessary.	s/n	\$	1,400.00 ✓
7	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	s/n	\$	1,400.00 ✓
8	To dismantle and reinstall center console. Renew airbag control unit and both front seatbelt.	s/n	\$	1,800.00 ✓
SUB-TOTAL LABOUR CHARGES			:	\$ 7,300.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDJ 422 R

S/N	Nature of Jobs		Estimated Charges
9	To remove and renew exhaust system. To remove and reinstall rear suspension assembly. Renew accordingly.	s/n \$	2,400.00 ?
10	To remove and reinstall fuel tank assy.	s/n \$	600.00 ✓
11	To setup vehicle on car o-liner for repair.	s/n \$	2,400.00 ?
12	To dismantle and renew rear bumper and rear lid. Repair and straighten both rear chasis frames to specification of origin. Cut out and weld rear end panelling, spare wheel housing and both rear fenders. Re-organize crash management components. Reinstall all parts removed.	s/n \$	14,700.00 60500
13	To carry out stone chip primer work on rear panelling and spare wheel housing. ✓ ✓ ✓ ✓	s/n \$	780.00 500
14	To respray rear bumper, rear lid, both rear fenders, both sill panels, drain panels, roof channels, door entrances, end panelling, spare wheel housing and boot floor. To carry out stone chip treatment, cavity preservation and joint sealer works. ✓ ✓ ✓ ✓	\$	8,100.00 5600
15	To carry out wheel alignment.	s/n \$	240.00 ?
16	To carry out diagnostic check.	s/n \$	384.00 ✓
TOTAL LABOUR CHARGES			: \$ 36,904.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SDJ 422 R

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER Distorted	\$ 2,015.00	✓
2	REAR BUMPER FIXING PARTS Distorted	\$ 68.00	✓
3	REAR BUMPER SECURING STRIP Distorted	\$ 203.00	✓
4	REAR BUMPER SPOILER Distorted	\$ 227.00	✓
5	REAR BUMPER REFLECTOR - LH / RH Curled	2 \$ 75.00	✓
6	REAR BUMPER CARRIER Bent	\$ 819.00	✓
7	REAR BUMPER SEAL new	2 \$ 25.00	✓
8	UPPER GUIDE SECTION - LH / RH ?	2 \$ 80.00	✓
9	LOWER GUIDE SECTION - LH / RH ?	2 \$ 40.00	✓
10	REAR BUMPER - LOWER GUIDE PIN new	2 \$ 5.00	✓
11	RETAINER FOR AERIAL - LH ?	\$ 23.00	?
12	TELEPHONE AERIAL ?	2 \$ 327.00	?
13	CONTROL UNIT FOR BOOT LID Damaged	\$ 381.00	✓
14	TAILGATE SENSOR ?	\$ 190.00	✓
15	CABLE TIE ?	\$ 3.00	?
16	CONTROL MODULE BRACKET ?	\$ 7.00	?
17	REAR CROSS PANEL SENSOR ?	\$ 102.00	?
18	REAR BUMPER SENSOR 3 piece damaged	4 \$ 924.00 612.00	6P2
19	SEAL RING new	4 \$ 12.00	✓
20	REAR BUMPER HARNESS : bent /	\$ 618.00	?
SUB-TOTAL SPARE PARTS		\$ 6,142.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SDJ 422 R

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	PRESSURE VALVE TRIM ?	2 \$	127.00 ?
22	REAR LID Distorted		TBC ✓
23	REAR LID HINGE LH / RH Bent	2 \$	416.00 ✓
24	REAR LID LOCK Bnd.	\$	210.00 ✓
25	REAR LID COVER Lt	\$	7.00 ✓
26	REAR LID ATTACHMENT PARTS new	\$	131.00 ✓
27	REAR LID LOCK ACTUATOR ? X see	\$	1,230.00 ?
28	REAR LICENSE PLATE LIGHT new	2 \$	191.00 ✓
29	REAR BOOT LID Striker. Bent.	\$	30.00 ✓
30	REAR BOOT LID CLIP new	2 \$	3.00 ✓
31	RIVET STUD new	2 \$	17.00 ✓
32	REAR LID AUDI EMBLEM	\$	113.00 ✓
33	REAR LID INSCRIPTION 'A4' X see	\$	87.00 ✓
34	REAR LID INSCRIPTION 'TFSI'	\$	87.00 ✓
35	REAR CROSS PANEL Distorted	\$	238.00 ✓
36	REAR CROSS PANEL REINFORCEMENT Distorted	\$	461.00 ✓
37	WHEELHOUSE LINER Spare Wheel Housing Distorted	\$	2,020.00 ✓
38	REAR LID TRIM PANEL Distorted	\$	301.00 ✓
39	REAR CROSS PANEL TRIM Distorted	\$	154.00 ✓
40	LUGGAGE COMPARTMENT FLOOR new see X	\$	247.00 ✓
SUB-TOTAL SPARE PARTS		\$	6,270.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SDJ 422 R

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	LUGGAGE COMPARTMENT FLOOR COVER <i>see near floor</i>	\$ 648.00	X
42	LED TAIL LIGHT - LH / RH (OUTER)	2 \$ 1,862.00	✓
43	LED TAIL LIGHT TRIM - LH / RH (OUTER)	2 \$ 54.00	✓
44	LED TAIL LIGHT - LH / RH (INNER)	2 \$ 1,862.00	✓
45	LED TAIL LIGHT TRIM - LH / RH (INNER)	2 \$ 54.00	✓
46	GROMMET	\$ 2.00	✓
47	REAR FENDER - LH / RH <i>RH Buckled</i>	2 \$ 4,895.00	2443
48	RIVETTED CAP NUT	4 \$ 4.00	✓
49	REAR WINDOW	\$ 1,049.00	✓
50	PRIMER	2 \$ 38.00	✓
51	QUARTER GLASS (SIDE WINDOW) - LH / RH <i>RH M</i>	2 \$ 1,121.00	550.50
52	REAR SILENCER - LH / RH	2 \$ 1,625.00	?
54	REAR SILENCER CLIP	2 \$ 89.00	?
55	REAR SILENCER BRACKET	2 \$ 76.00	?
56	REAR SILENCER - CENTRE	\$ 825.00	?
57	REAR SILENCER GASKET HANGER	\$ 19.00	?
58	REAR SILENCER BRACKET HANGER	\$ 45.00	?
59	REAR SILENCER HEAT SHIELD - LH / RH	2 \$ 277.00	?
60	REAR SILENCER HEAT SHIELD - CENTER	\$ 62.00	?
61	SEAT BELT WITH TENSIONER - LH / RH <i>Accidental</i>	2 \$ 2,010.00	✓
SUB-TOTAL SPARE PARTS		\$ 16,808.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Net.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SDJ 422 R

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
62	SEAT BELT FELT STRIP - RH <i>new</i>	\$ 4.00	✓
63	SEAT BELT HEIGHT ADJUSTER ?	2 \$ 322.00	?
64	FRONT CRASH SENSOR FOR AIRBAG <i>Acclimated</i>	3 \$ 1,145.00	✓
65	CONTROL UNIT FOR AIRBAG ? <i>Acclimated</i>	\$ 1,927.00	✓
66	REAR CRASH SENSOR FOR AIRBAG	2 \$ 824.00	✓
67	BATTERY CABLE END <i>Acclimated</i>	\$ 485.00	✓
68	REAR NO. PLATE <i>Bent</i>	\$ 40.00	✓
69	ACYLIC SEALANT ?	\$ 360.00	✓
70	CAVITY WAX <i>new</i>	\$ 280.00	✓
71	STONE CHIP	\$ 360.00	✓
72	METAL FILLER POWDER ? <i>new</i>	\$ 280.00	✓
73	REAR WINDSCREEN SEALANT	\$ 200.00	✓
74	BOTH QUARTER GLASS SEALANT <i>RH new</i>	\$ 200.00 100	✓
75	SUNDRIES ?	\$ 1,000.00	?
TOTAL SPARE PARTS		: \$ 36,647.00	
TOTAL LABOUR CHARGES		: \$ 44,204.00	
GRAND TOTAL		: \$ 80,851.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lij
Surveyed Date : 03/07/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised , 25 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant