

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 568C**AAD1907-022***Not Authored*
U/Sing & 185d

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

02 JUL 2019

SHF 568C

VF1ABL15AUC278213

RENAULT

LATITUDE

1.7.19

TOKIO MARINE

20/6/2014

		PART	LIST
1	1	BUMPER COVER REAR	\$ Bu 1,108.46 —
2	1	BUMPER LOWER REAR	\$ CM 768.84 —
3	1	BUMPER BRACKET CTR REAR	\$ SL 113.47
4	1	BUMPER BRACKET SIDE RH REAR	\$ SL 135.97
5	1	BUMPER RETAINER RH REAR	\$ SL 44.99
6	1	BUMPER REFLECTOR RH	\$ SL 43.61
7	1	BUMPER BRACKET SIDE LH REAR	\$ SL 135.97
8	1	BUMPER RETAINER LH REAR	\$ SL 44.99
9	1	BUMPER REFLECTOR LH	\$ SL 43.61
10	1	BUMPER BEAM REAR	\$ H 777.52
11	1	BUMPER BEAM BRACKET LH REAR	\$ H 225.95
12	1	BUMPER BEAM BRACKET RH REAR	\$ H 225.95
13	1	OUTER PANEL REAR (End Panel)	\$ H 1,471.77
14	1	OUTER PANEL REAR (End Panel)TRIM	\$ SL 404.56
15	1	TAILLAMP RH	\$ SL 552.55
16	1	TAILLAMP PANEL RH	\$ H 986.70
17	1	TAILLAMP LH	\$ SL 552.55
18	1	TAILLAMP PANEL LH	\$ H 986.70
19	1	BOOT REAR	\$ H 2,872.68
20	1	BOOT FINISHER	\$ SL 470.06
21	1	BOOT WHEATERSTRIP	\$ SL 323.05
22	1	BOOT REFLECTOR LAMP LH	\$ SL 493.35
23	1	BOOT REFLECTOR LAMP RH	\$ SL 493.35
24	1	BOOT BADGE 'RENAULT'	\$ An 225.36
25	1	BOOT BADGE	\$ An 225.36
26	1	BOOT STRUT LH	\$ SL 276.08
27	1	BOOT STRUT RH	\$ SL 276.08
28	1	BOOT HINGE LH	\$ H 367.84
29	1	BOOT HINGE RH	\$ H 367.84

Trans-cab Auto Services Pte Ltd**AAD1907-022**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 568C

30	1	BOOT INNER TRIM	\$	586.45	X
31	1	BOOT SWITCH	\$	168.13	X
32	1	BOOT LOCK	\$	202.67	X
33	1	BOOT LOCK CATCH	\$	74.40	X
TOTAL			\$	16,046.87	
10%			\$	1,604.69	
			\$	14,442.19	

Special Nett

1	1SET	PARKING AID	\$	700.00	X
2	1SET	REAR BUMPER CLIP	\$	66.00	
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	
10	1	BOOT STICKER "Trans-cab"	\$	30.00	X
11	1	BOOT STICKER "6555-3333"	\$	30.00	
12	1	EXHAUST MOUNTING REAR	\$	17.82	
13	2	REAR WINDSCREEN SEALANT	\$	80.00	
14	1	WINDSCREEN MOULDING	\$	100.00	
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
16	1	BOOT INNER TRIM CLIP	\$	45.00	
17	1SET	BOOT FINISHER CLIP	\$	24.20	
18	1	TAILLAMP CLIP LH	\$	5.00	
19	1	TAILLAMP CLIP RH	\$	5.00	
TOTAL			\$	1,384.02	

TOTAL PARTS \$ 15,826.21**LABOUR**

To Check Electrical Lighting Concerned. \$ 170.00 X

To transfer of bootlid fittings, attachments and perform water seepage test. \$ 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1907-022

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 568C

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
To Rust-Proofing Of The Affected Areas.	\$	na	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	na	170.00	X
To reinstall rear bumper parking sensor.	\$	.	170.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		4,500.00	2001
Putty And Spray Painting Of The Affected Portion.	\$		4,500.00	229
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	L	170.00	X
To check steering geometry and computer wheel alignment	\$	L	220.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	L	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	L	380.00	X
TOTAL	\$		11,550.00	

Over All Total \$ 27,376.21

LKK Auto Consultants hence notify the Repairer of the following:

LUMP SUM (REPAIR DAY)

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

15 DAYS

2 days