

SJE : \_\_\_\_\_  
Date of Survey : \_\_\_\_\_  
Date of ReSurvey: \_\_\_\_\_ After-Paint: \_\_\_\_\_  
Contacts : \_\_\_\_\_

Vehicle Nos : **SLM 6088Y**  
Model : Elantra  
Year : \_\_\_\_\_  
Chassis No : \_\_\_\_\_

**\* AGREED Cost Of Repair and Repair Day/s with SJE \***

Amount: \_\_\_\_\_

Working Day: \_\_\_\_\_

| Nos.                 | PARTS                                | Qty | Unit S\$    | TOTAL S\$           |                  |
|----------------------|--------------------------------------|-----|-------------|---------------------|------------------|
| 1                    | Bootlid                              | 1   | \$ 1,188.00 | \$ 1,020.00         | 1,188.00 CRU ✓   |
| 2                    | Bootlid logo                         | 1   | \$ 56.00    | \$ 56.00            | ✓ 56.00 NEC ✓    |
| 3                    | Bootlid emblem 'Elantra'             | 1   | \$ 68.60    | \$ 48.00            | 68.60            |
| 4                    | Bootlid emblem 'S'                   | 1   | \$ 58.00    | \$ 32.00            | 58.00            |
| 5                    | Bootlid reflector Lh                 | 1   | \$ 362.60   | \$ 362.60           | 362.60 NNx       |
| 6                    | Bootlid reflector Rh                 | 1   | \$ 362.60   | \$ 362.60           | ✓ 362.60 CUT     |
| 7                    | Bootlid no plate lamp                | 2   | \$ 85.30    | \$ 136.00           | 170.60 BRV ✓     |
| 8                    | Bootlid reverse camera               | 1   | \$ 450.00   | \$ 280.00           | 450.00 DLV ✓     |
| 9                    | Bootlid reverse camera garnish       | 1   | \$ 86.30    | \$ 86.30            | ✓ 86.30 DLV ✓    |
| 10                   | Bootlid inner trim                   | 1   | \$ 548.00   | \$ 266.60           | 548.00 DLV ✓     |
| 11                   | Bootlid inner lock                   | 1   | \$ 158.40   | \$ 158.40           | ✓ 158.40 JMV ✓   |
| 12                   | Bootlid striker                      | 1   | \$ 52.70    | \$ 52.70            | ✓ 52.70 BT ✓     |
| 13                   | Bootlid hinge                        | 2   | \$ 94.30    | \$ 188.60           | ✓ 188.60 BT ✓    |
| 14                   | Bootlid weatherstrip                 | 1   | \$ 112.36   | \$ 112.36           | ✓ 112.36 DIS ✓   |
| 15                   | Rear bumper                          | 1   | \$ 856.30   | \$ 756.00           | 856.30 CRU ✓     |
| 16                   | Rear bumper reinforcement            | 1   | \$ 462.56   | \$ 462.56           | ✓ 462.56 DDV ✓   |
| 17                   | Rear bumper reinforcement bracket Rh | 1   | \$ 253.60   | \$ 253.60           | ✓ 253.60 BRV ✓   |
| 18                   | Rear bumper retainer                 | 2   | \$ 48.90    | \$ 97.80            | ✓ 97.80 NEC ✓    |
| 19                   | Rear bumper bracket                  | 2   | \$ 92.40    | \$ 184.80           | 369.60 BT ✓      |
| 20                   | Rear bumper lower                    | 1   | \$ 211.00   | \$ 211.00           | ✓ 211.00 DLV ✓   |
| 21                   | Rear bumper reflector                | 1   | \$ 98.50    | \$ 98.50            | 197.00 BRV ✓     |
| 22                   | Rear end panel                       | 1   | \$ 580.00   | \$ 491.00           | 580.00 DDV ✓     |
| 23                   | Rear end panel top garnish           | 1   | \$ 89.00    | \$ 89.00            | ✓ 89.00 DLV ✓    |
| 24                   | Spare tyre panel                     | 1   | \$ 1,025.70 | \$ 1,025.70         | 1,025.70 NNx     |
| 25                   | Spare tyre panel top board           | 1   | \$ 445.00   | \$ 445.00           | 445.00 NNx       |
| 26                   | Spare tyre panel insulation pad      | 1   | \$ 250.00   | \$ 200.00           | 250.00 NEC ✓     |
| 27                   | Tail lamp Lh                         | 1   | \$ 398.26   | \$ 398.26           | 398.26 NNx       |
| 28                   | Taillamp lower bracket               | 1   | \$ 68.00    | \$ 68.00            | 68.00 NNx        |
| 29                   | Taillamp Rh                          | 1   | \$ 398.26   | \$ 350.00           | 398.26 BRV ✓     |
| 30                   | Taillamp lower bracket               | 1   | \$ 68.00    | \$ 68.00            | ✓ 68.00 BRV ✓    |
| 31                   | Taillamp panel Rh                    | 1   | \$ 188.90   | \$ 188.90           | ✓ 188.90 DDV ✓   |
| 32                   | Rear fender Rh                       | 1   | \$ 1,768.30 | \$ 1,768.30         | ✓ 1,768.30 DDV ✓ |
| 33                   | Rear fender inner trim               | 1   | \$ 285.00   | \$ 285.00           | 285.00 NNx       |
| 34                   | Air vent Rh                          | 1   | \$ 98.50    | \$ 38.50            | 98.50 DK ✓       |
| 35                   | Exhaust pipe                         | 1   | \$ 834.80   | \$ 834.80           | 834.80 RX        |
| 36                   | Rear windscreen moulding             | 1   | \$ 166.00   | \$ 166.00           | ✓ 166.00 NEC     |
| Parts Sub Total :    |                                      |     |             | \$ 12,974.34        | 8223             |
| 20% Discount         |                                      |     |             | \$ 2,594.87         | 1644             |
| <b>PARTS TOTAL :</b> |                                      |     |             | <b>\$ 10,379.47</b> | <b>6579</b>      |

| Nos. | SPECIAL NETT            | Qty | Unit S\$  | TOTAL S\$ |            |
|------|-------------------------|-----|-----------|-----------|------------|
| 1    | Bootlid Sealant         | 1   | \$ 100.00 | \$ 60.00  | 100.00 NEC |
| 2    | Bootlid reflector clips | 1   | \$ 50.00  | \$ 30.00  | 50.00 NEC  |

|                      |                                    |   |    |        |           |          |      |
|----------------------|------------------------------------|---|----|--------|-----------|----------|------|
| 3                    | Bootlid reflector inner seal       | 2 | \$ | 80.00  | \$        | 160.00   | NNX  |
| 4                    | Bootlid inner trim clips           | 1 | \$ | 50.00  | \$ 30.00  | 50.00    | NECV |
| 5                    | Rear bumper clips                  | 1 | \$ | 50.00  | \$ 30.00  | 50.00    |      |
| 6                    | Rear bumper lower clips            | 1 | \$ | 50.00  | \$ 30.00  | 50.00    |      |
| 7                    | Reverse sensor                     | 2 | \$ | 200.00 | \$ 200.00 | 400.00   | DLV  |
| 8                    | Rear end panel top garnish clips   | 1 | \$ | 50.00  | \$ 30.00  | 50.00    | NECV |
| 9                    | Taillamp clips                     | 2 | \$ | 50.00  | \$ 30.00  | 100.00   |      |
| 10                   | Taillamp inner seal                | 2 | \$ | 80.00  | \$        | 160.00   | NNX  |
| 11                   | Rear fender inner trim clips       | 1 | \$ | 50.00  | \$ 30.00  | 50.00    | NECV |
| 12                   | Rear windscreen inner seal         | 1 | \$ | 150.00 | \$ 60.00  | 150.00   | NECV |
| 13                   | Rear windscreen clips              | 1 | \$ | 50.00  | \$ 30.00  | 50.00    | NECV |
| 14                   | Rear windscreen sealant            | 1 | \$ | 100.00 | \$ 60.00  | 100.00   | NECV |
| 15                   | Rear end panel sealant             | 1 | \$ | 100.00 | \$ 60.00  | 100.00   | ✓    |
| 16                   | Spare tyre panel sealant           | 1 | \$ | 100.00 | \$        | 100.00   | NNX  |
| 17                   | Rear windscreen primer and cleaner | 1 | \$ | 80.00  | \$        | 80.00    | NNX  |
| 18                   | Sundries                           | 1 | \$ | 60.00  | \$        | 60.00    | NNX  |
| SPECIAL NETT TOTAL : |                                    |   |    |        | \$ 680.00 | 1,860.00 |      |

| Nos.           | LABOUR                                                   | S\$        |          |   |
|----------------|----------------------------------------------------------|------------|----------|---|
| 1              | R&R bootlid component                                    | \$ 50.00   | 100.00   | ✓ |
| 2              | R&R reverse sensor                                       | \$ 50.00   | 100.00   | ✓ |
| 3              | R&R upholstery                                           | \$ 80.00   | 150.00   | ✓ |
| 4              | R&R rear windscreen                                      | \$ 120.00  | 250.00   | ✓ |
| 5              | R&R wire harness to facilitate repair and check function | \$ 50.00   | 100.00   | ✓ |
| 6              | Panel beat                                               | \$ 1200.00 | 1,800.00 |   |
| 7              | Rust proofing                                            | \$ 60.00   | 150.00   |   |
| 8              | Spray painting                                           | \$ 1000.00 | 1,800.00 |   |
| LABOUR TOTAL : |                                                          | \$ 2610.00 | 4,450.00 |   |

Trim /mm  
Survey on 5/7/19  
1530 hrs

Lump sum repair  
Repair days 8

Resurvey on 8/7/19  
1430 hrs  
Trim /mm

PARTS TOTAL : \$ 6578.82 10,379.47  
SPECIAL NETT TOTAL : \$ 680.00 1,860.00  
LABOUR TOTAL : \$ 2610.00 4,450.00

GRAND TOTAL : \$ 9868.82 16,689.47

@ 20% 1973.76  
7895.06

L/S 7850/- with 8 days repair

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: