

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 486R**AAD1907-009***Not Whorzel**Resony B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

02 JUL 2019

SHD 486R

VF1ABL15AUC283272

RENAULT

LATITUDE

28.6.19

AIG

22/8/2017

PART**LIST**

1	1	BUMPER COVER REAR	\$	<i>Ry</i> 1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>Rd1011</i> 768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>D,1</i> 113.47	✓
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	X
5	1	BUMPER RETAINER RH REAR	\$	<i>SL</i> 44.99	X
6	1	BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61	X
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97	X
8	1	BUMPER RETAINER LH REAR	\$	<i>SL</i> 44.99	X
9	1	BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61	X
10	1	BUMPER BEAM REAR	\$	<i>Ry</i> 777.52	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>D10</i> 225.95	✓
13	1	BOOT REAR	\$	<i>Bur</i> 2,872.68	✓
14	1	BOOT FINISHER	\$	<i>SL</i> 470.06	X
15	1	BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05	X
16	1	BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35	X
17	1	BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35	X
18	1	BOOT BADGE 'RENAULT'	\$	<i>Me</i> 225.36	✓
19	1	BOOT BADGE	\$	<i>Me</i> 225.36	✓
20	1	BOOT STRUT LH	\$	<i>SL</i> 276.08	} X
21	1	BOOT STRUT RH	\$	<i>SL</i> 276.08	
22	1	BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1	BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1	BOOT INNER TRIM	\$	<i>SL</i> 586.45	
25	1	BOOT SWITCH	\$	<i>SL</i> 168.13	
26	1	BOOT LOCK	\$	<i>R</i> 202.67	
27	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2	LICENCE PLATE LAMP	\$	<i>SL</i> 50.52	
29	2	BOOT RUBBER PLUG	\$	<i>SL</i> 221.81	

Trans-cab Auto Services Pte Ltd**AAD1907-009**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 486R

30	1	FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	
31	1	FENDER PANEL REAR RH	\$	n	3,299.13	
32	1	WHEELARCH REAR RH	\$	Sn	543.47	
33	1	FENDER PANEL REAR LH	\$	n	3,299.13	
34	1	FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	
35	1	WHEELARCH REAR LH	\$	Sn	543.47	
36	1	TAILLAMP RH	\$	Sn	552.55	
37	1	TAILLAMP PANEL RH	\$	n	986.70	
38	1	TAILLAMP LH	\$	Sn	552.55	
39	1	TAILLAMP PANEL LH	\$	n	986.70	
40	1	OUTER PANEL REAR (End Panel)	\$	Bz	1,471.77	✓
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	n	404.56	✓
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	n	2,189.88	X
43	1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
44	1	EXHAUST REAR	\$	n	7,489.05	X
45	1	EXHAUST CAP REAR	\$	n	230.49	X
46	1	FUEL FLAP	\$	n	343.57	X
TOTAL			\$		36,212.51	
10%			\$		3,621.25	
			\$		32,591.26	

Special Nett

1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	n	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	n	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	n	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	n	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	n	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	n	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	n	22.00	Λ
9	1SET	BUMPER LOWER REAR CLIP	\$	n	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	Sn	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	n	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	n	30.00	✓
13	1	BOOT STICKER "6555-3333"	\$	n	30.00	✓
14	1	BOOT INNER TRIM CLIP	\$	n	45.00	X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	n	35.00	X
16	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	n	385.00	X

Trans-cab Auto Services Pte Ltd

AAD1907-009

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 486R

17	1	SPARE TYRE	\$	SH	330.00	}	X
18	1	FENDER INNER TRIM CLIP RH	\$	nn	28.00		
19	1	TAILLAMP CLIP RH	\$	nn	5.00		
20	2	REAR WINDSCREEN SEALANT	\$	nn	80.00		
21	1	WINDSCREEN MOULDING	\$	nn	100.00		
22	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00		
23	1	TAILLAMP CLIP LH	\$	nn	5.00		
24	1	FENDER INNER TRIM CLIP LH	\$	nn	28.00		
25	1SET	FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00		
26	1	Rear left tyre	\$	SH	330.00		
27	1	Rear left tyre rim	\$	SH	380.00	}	
28	1	Rear right tyre	\$	SH	330.00		
29	1	Rear right tyre rim	\$	SH	380.00		
TOTAL			\$		3,645.02		

TOTAL PARTS \$ 36,236.28**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	6601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	6001
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	

Trans-cab Auto Services Pte Ltd**AAD1907-009**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 486R

To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To Rust-Proofing Of The Affected Areas.	\$		170.00	601
To repair and realign rear exhaust pipe.	\$		170.00	X
To transfer of tire, rim and on wheel balancing.	\$		170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	601
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn	380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn	170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	nn	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	nn	380.00	X
To Check Electrical Lighting Concerned.	\$		170.00	201
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	nn	380.00	X

TOTAL \$ 19,200.00**Over All Total \$ 55,436.28**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(PART BY PART) Repair Days**25 DAYS****5 days**